




SOURCE: ESA, 2021

College Lake Integrated Resources Management Project - Addendum


**Figure 1**  
Project Location Map





SOURCE: Carollo Engineers, 2021; ESA, 2021

College Lake Integrated Resources Management Project - Addendum




SOURCE: Carollo Engineers, 2021

College Lake Integrated Resources Management Project - Addendum

**Figure 3**  
Weir and Intake Pump Station – Perspective View





SOURCE: Carollo Engineers, 2021

College Lake Integrated Resources Management Project - Addendum

**Figure 4**  
Water Treatment Plant





SOURCE: Jacobs, 2021; ESA, 2021

College Lake Integrated Resources Management Project - Addendum



**Figure 5b**  
Pipeline Alignment





SOURCE: Jacobs, 2021; ESA, 2021

College Lake Integrated Resources Management Project - Addendum

**Figure 5c**  
Pipeline Alignment





SOURCE: Jacobs, 2021; ESA, 2021

College Lake Integrated Resources Management Project - Addendum

**Figure 5d**  
Pipeline Alignment










SOURCE: Jacobs, 2021; ESA, 2021

College Lake Integrated Resources Management Project - Addendum

**Figure 5f**  
Pipeline Alignment






SOURCE: DigitalGlobe, 2016; Carollo Engineers, 2020; ESA, 2020

College Lake Integrated Resources Management Project

**Figure 6**

College Lake Project: Tree Removal Plan






SOURCE: Santa Cruz County, 2020; PVWMA, 2022; ESA, 2022

College Lake Integrated Resources Management Project

**Figure 7**  
Replacement Tree Planting Site





SOURCE: Jacobs, 2021; ESA, 2021

College Lake Integrated Resources Management Project

**Figure 8**  
Trenchless Crossing Beneath Salsipuedes Creek





