

SOURCE: SFO, 2023

SFO Shoreline Structures Repair Program

## FIGURE 3 PIER/PILE STRENGTHENING DETAIL







FIGURE 4 TYPICAL TIMBER TRESTLE COMPONENT REPAIR – GUARDRAIL AND STRINGER

SOURCE: SFO, 2023

SFO




SOURCE: SFO, 2023

SFO Shoreline Structures Repair Program

## FIGURE 5 TYPICAL TIMBER TRESTLE COMPONENT REPAIR – CROSS AND KNEE BRACE





SOURCE: SFO, 2023

SFO Shoreline Structures Repair Program

## FIGURE 6 OUTFALL CONNECTION STRAP REPLACEMENT

