

Scandies Rose April 2019 shipyard work list

| <u>task/ issue</u> | <u>initial vendor thoughts</u> |
|--|--------------------------------|
| 1 pinhole leak in Port aft fuel tank | SY |
| 2 pinhole leak in port water tank | SY |
| 3 Replace stb fresh water tank lower valve | Labor |
| 4 #2 steering pump flow valve leaking | Ryan |
| 5 Port ME air controls/ shaft brake | Ryan/Jim Nash |
| 6 portside 45V hydraulic leak at union o/h | Ryan |
| 7 Port 60 Aux - make straight mounts and re-align | ppp ? |
| 8 crane boom ram replaced | SY |
| 9 mount spare boom ram in forepeak | SY |
| 10 water pipe feed on stbd ME replacement | SY |
| 11 circ pumps1, 2,3 impellers checked: repair/replace/ align | Ryan/labor |
| 12 re-pack all crab pumps | Ryan/labor |
| 13 fuel transfer pump leak at packing | labor force |
| 14 re-pack shafts | labor force |
| 15 re-pack rudder posts | labor force |
| 16 port stuffing box replaced | SY |
| 17 small bilge pump gate valve replaced | Labor |
| 18 small bilge pump o/b valve leaks | Labor |
| 19 deck hose/ condenser pump shaft packing leak | Labor |
| 20 check all 8D batteries and replace as necessary | Labor |
| 21 clean all fuel tanks | Labor/sound marine or other |
| 22 check sewage tank alarms | CETS |
| 23 check day tank high level alarm | CETS |
| 24 clean all Racors | Labor |
| 25 service centrifuge | Labor |
| 26 clean raw water screens | Labor |
| 27 check all reefer compressors | Highland |
| 28 rod all condensers | Labor |
| 29 flush all chillers | Highland |
| 30 test refrigeration | Highland |
| 31 oil changes on ME and gensets | Brandon |
| 32 Tune-ups on all engines | PPP |

No part of a report of a marine casualty investigation shall be admissible as evidence in any civil or administrative proceeding, other than an administrative proceeding initiated by the United States. 46 U.S.C. §6308.

| | | |
|---|------------|------------------------------------|
| 33 Hotel set rear cam seal leak | PPP | |
| 34 Hotel set injector miss | PPP | |
| 35 service air compressors | Labor | |
| 36 find all air leaks and repair | Labor | |
| 37 Re-do the crew head - toilet, shower, fixtures, cabinet, floors | Carpenter | Mike Ness, Glen Davis, Chris Davis |
| 38 replace fan in head | Labor | |
| 39 inspect exhaust pipes for holes | Labor | |
| 40 check and replace as needed all zincs in circ system | Labor | |
| 41 check and replace all zincs in raw water system | Labor | |
| 42 re-hose davit hydraulics hard tube to eliminate ware? | Ryan/labor | |
| 43 repair LED light mount over forepeak door | Ryan/labor | |
| 44 crab block hose replaced? | Ryan/labor | |
| 45 replace fwd deck hose and hanger | Ryan/labor | |
| 46 repair broken deck boards | Labor | |
| 47 AIS repaired | Mike Rudd | |
| 48 Check crane hydraulic oil tank (lower) | Labor | |
| 49 Replace crane hydraulic oil filter | Labor | |
| 50 Grease all fittings | Labor | |
| 51 Change fuel filters on mains and generators | Brandon | |
| 52 Replace table ram hoses - fittings always get loose on rod end | Ryan/labor | |
| 53 Simrad RS 35 VHF | Mike Rudd | |
| 54 Stb Rudder angle indicator light not working | Mike Rudd | |
| 55 Second computer per USCG | Lunde | |
| 56 Port Loud Hailer | Mike Rudd | |
| 57 Port side PTO air controls - works on manual only | CETS | |
| 58 Port Side tall antenna | Mike Rudd | |
| 59 Lube Oil meter - check Possibly replace | Labor | |
| 60 Anchor winch not free flowing | Ryan | Max Performance |
| 61 Hard plumb coiler with short hoses at end | Labor | |
| 62 Replace hoses under console | crew/Ryan | |
| 63 Non-skid on all hatches | Labor | |
| 64 Rebuild fwd stb trash chute and eliminate stb aft | SY ? | |
| 65 New crane tire | crew | |
| 66 check picking crane lift ram seals | Ryan | |

| | | |
|--|--------------|------|
| 67 New spectra on picking crane (1/2") | crew | |
| 68 repair non-skid around wheelhouse | Labor | |
| 69 Crab tanks painted | Romero | |
| 70 Mid tank cracks welded | SY ? | |
| 71 Butterfly valve in 8" line leaks (marked) | Labor | |
| 72 Stb main exhaust pipe loose at bottom | Labor | |
| 73 Light bulbs for engine room alarm panel | Labor | |
| 74 Stb aft wide light shuts off on vibration | labor / CETS | CETS |
| 75 Circ Pump VFDs | CETS | |
| 76 Put pipes back in tanks | | |
| 77 Weld transducer snag | | |
| 78 Weld hole in port strut | | |