

Naval Base Coronado

Sample Summary Results Table

Lead in Priority Areas (LIPA) and Corrective Actions (FY 2023)

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION					INITIAL SAMPLING RESULTS		
CATEGORY <small>[Water's intended use]</small>	BASE	SAMPLE ID <small>[Use same nomenclature as baseline sample event]</small>	Outlet Description <small>[At a minimum, room number and type of outlet; include filter identification and whether a motion sensor faucet or blended water, as applicable]</small>	Comments <small>[Provide, for example, whether filter was removed, staining was present, any identifying marks]</small>	Lead Screening Level of 15 ppb		
					First Draw <small>(ppb) ug/L</small> <small>[numeric value]</small>	Retest required? <small>[YES or NO]</small>	Date Fixture Secured? <small>[See Note 1]</small> <small>[N/A if First Draw is ≤ 15ppb; otherwise mm/dd/yyyy]</small>
SAMPLING DATE					6/14/2023		
RESULTS DATE					6/28/2023		
Drinking	NASNI CDC	NBC-605-111	Play Yard Water Fountain Outside RM 103 & 105	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Water fountain was replaced.	2.89	No	
Drinking	NASNI CDC	NBC-605-112	Play Yard Water Fountain Outside RM 103 & 106	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Water fountain was replaced.	0.609	No	
Drinking	NASNI CDC	NBC-605-113	Play Yard Water Fountain Outside RM 102	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Water fountain was replaced.	0.253	No	
Drinking	NASNI CDC	NBC-605-114	Play Yard Water Fountain Outside RM 103	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Water fountain was replaced.	0.167	No	
Drinking	NASNI CDC	NBC-605-115	Play Yard Water Fountain Outside RM 107	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Water fountain was replaced.	0.269	No	
Drinking	NASNI CDC	NBC-605-116	Play Yard Water Fountain Outside RM 108	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Water fountain was replaced.	0.677	No	
Drinking	NASNI CDC	NBC-606-117	Play Yard Water Fountain Outside RM 112	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Water fountain was replaced.	0.106	No	
Drinking	NASNI CDC	NBC-606-124	Play Yard Water Fountain Outside RM 119	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Water fountain was replaced.	0.329	No	
Drinking	NAB	PHIBCOR503-MAIN FOYER-LIPA54	Lobby Water Fountain (closest to main doors)	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Drinking water fountain was replaced.	ND (<0.100)	No	N/A
Washing	NASNI CDC	NBC-606-RM118-82	RM 118 Sink	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Sink was dripping/leaking.	0.22	No	
Washing	NASNI CDC	NBC-606-RM114-59	RM 114 Sink	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Sink was repaired.	0.27	No	
Hand Washing	NASNI CDC	NBC-606-RM113-56	Children's Sinks	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Sink was replaced.	0.36	No	
Hand Washing	NASNI CDC	NBC-606-RM113-57	Children's Sinks	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Sink was replaced.	0.43	No	
Hand Washing	NASNI CDC	NBC-606-RM114-62	Children's Sinks	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Sink was replaced.	0.30	No	
Hand Washing	NASNI CDC	NBC-606-RM114-63	Children's Sinks	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Sink was replaced.	0.29	No	
Washing	NAB	PHIBCOR503-RM102-LIPA10	Changing Table Sink	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Changing table sink leaking.	0.78	No	N/A
Hand Washing	NAB	PHIBCOR503-RM102-LIPA12	Children's Sink	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Children's sink dripping/leaking.	0.780	No	N/A
Washing	NAB	PHIBCOR503-RM104-LIPA13	Sink closet to the door	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Teacher's s sink dripping/leaking.	0.16	No	N/A
Washing	NAB	PHIBCOR503-RM100-LIPA1	Sink closest to the door	Fixture selected for sampling because the following repairs were completed since the previous Annual Audit: Teacher's sink dripping/leaking.	0.649	No	N/A