Commandant United States Coast Guard 2073 Martin Luther King Ave, SE. Washington, DC 20593-7501 Staff Symbol: CG-INV Phone: (202) 372-1030

16732 APR 1 9 2021

MEMORANDUM

From: Scott A. Buschman, VADM

To:

T. Phillips, CAPT

Subj: MARINE BOARD OF INVESTIGATION CONCERNING THE CAPSIZING OF THE SEACOR POWER (O.N. 1115290) APPROX. 7 NM SOUTH OF PORT FOURCHON, LOUISIANA, WITH MULTIPLE LOSSES OF LIFE

- 1. Pursuant to the authority contained in Title 46, United States Code (U.S.C.), Section 6301 and the regulations promulgated thereunder, you are to convene a Formal Marine Board of Investigation consisting of the following membership. The Board will convene as soon as practicable to inquire into all aspects of the subject casualty at such times and places as directed by you.
 - CAPT Tracy Phillips, USCG, Chairman
 - Mr. Andrew Lawrence, USCG, Member
 - Mr. Eric Verdin, USCG, Member
 - LT Sharyl Pels, USCG, Legal Counsel
 - LT Anthony Alger, USCG, Recorder
- 2. The Board will thoroughly investigate the capsizing of the offshore supply vessel SEACOR POWER (O.N. 1115290) and the resulting losses of life in accordance with all applicable statutory and regulatory mandates. Upon completion of the investigation, the Board will issue a report to the Commandant with the collected evidence, the established facts, and its conclusions and recommendations. Conclusions and recommendations concerning commendatory actions or misconduct that would warrant further inquiry shall be referred by separate correspondence to the cognizant District Commander for consideration and action. A daily summary of significant events shall be transmitted to Commandant (CG-5PC) while the Board is in formal session.
- 3. You will complete and submit your investigative report to Commandant (CG-5PC) within 12 months of the convening date. If this deadline cannot be met, a written explanation for the delay and the expected completion date shall be submitted. You are highly encouraged to submit any interim recommendations intended to prevent similar casualties, if appropriate, at any point in your investigation.
- 4. The National Transportation Safety Board (NTSB) is also charged with the responsibility of determining the cause or probable cause of this casualty by the Independent Safety Board Act of

Subj: MARINE BOARD OF INVESTIGATION CONCERNING THE CAPSIZING OF THE SEACOR POWER (O.N. 1115290) APPROX. 7 NM SOUTH OF PORT FOURCHON, LOUISIANA, WITH MULTIPLE LOSSES OF LIFE

1974 (49 U.S.C. 1901, et. seq.) and may designate a representative to participate in this investigation including any formal hearing sessions conducted by the Board. The NTSB representative may make recommendations regarding the scope of the inquiry, may identify and examine witnesses, and/or submit or request additional evidence.

5. The Commandant (CG-INV) will furnish such funding and/or technical assistance as may be required by the Marine Board when deemed appropriate and within the requirements for the scope of this investigation. Commander, Eighth Coast Guard District, will provide administrative, logistical, and/or legal support as may be required.

#

Copy: CG-5P

CG-LMI

LANTAREA(p)

CCGD8(dp)

SEC New Orleans