



Photo dated unknown

Source: Bart Barnum, NTSB



Date: unknown

Source: Unknown



Photo dated April 27, 2019

Source: Erling E. Jacobsen



Photo dated April 27, 2019

Source: Erling E. Jacobsen



Photo dated April 27, 2019

Source: Erling E. Jacobsen



Photo dated April 27, 2019

Source: Erling E. Jacobsen



Photo dated April 27, 2019

Source: Erling E. Jacobsen



Photo dated April 27, 2019

Source: Erling E. Jacobsen



Photo dated April 27, 2019

Source: Erling E. Jacobsen



Photo dated 2019

Source: Condition and Valuation Survey F/V SCANDIES ROSE, pg 13



Photo dated 2019

Source: Condition and Valuation Survey F/V SCANDIES ROSE, pg 13



Photo dated April 27, 2019

Source: Erling E. Jacobsen



Date: unknown

Source: unknown



Photo dated 2019

Source: Condition and Valuation Survey F/V SCANDIES ROSE, pg 14



Photo dated 2019

Source: Condition and Valuation Survey F/V SCANDIES ROSE, pg 14



Date: Unknown

Source: Unknown



Screencapture of ROV Footage taken by Global Diving & Salvage, Inc., dated February 13, 2020



Screencapture of ROV Footage taken by Global Diving & Salvage, Inc., dated February 13, 2020



Screencapture of ROV Footage taken by Global Diving & Salvage, Inc., dated February 13, 2020




Photos provided by Dean Gribble

Loading pots on the Scandies Rose



Photos provided by Dean Gribble

Loading pots on the Scandies Rose



Photos provided by Dean Gribble

Loading pots on the Scandies Rose

AT&T

7:56 PM

100%



Kenny's Post



Like



Comment



Share



Like



Comment



Share

Photo of Gary Cobban breaking ice, date unknown

Provided by Gerry Cobban Knagin




Photo of SCANDIES ROSE bow at pier, date unknown

Provided by Gerry Cobban Knagin