

Unit Summary :


Completion Date: 6/18/2014 3:42 PM
Instrument: 193-6
Serial #: 309119
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr

Summary Statistics :

Total # of Readings: 94
Average: 3.24 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Reading	Reading Units	Anomaly	Notes	Cell Description	Second Reading	Second Reading Units	Second Reading Cell Description
A2	3.2	uR/hr	No	partial grid 40%, remainder of grid is exterior	Living Room		uR/hr	
A3	3.2	uR/hr	No		Living Room		uR/hr	
A4	3.2	uR/hr	No		Living Room		uR/hr	
A5	3.2	uR/hr	No	partial grid, 70% accessible, installed base cabinet in kitchen grid	Living Room		uR/hr	
A6	3.2	uR/hr	No	partial grid- surveyed wood base cabinet/ sink 3" above floor surveyed	Kitchen		uR/hr	
A7	3.2	uR/hr	No	partial grid- installed base cabinet. wood base cabinet 3" above floor surveyed	Kitchen		uR/hr	
A8	3.2	uR/hr	No		Dining Room		uR/hr	
A9	3.2	uR/hr	No		Dining Room		uR/hr	
A10	3.2	uR/hr	No		Dining Room		uR/hr	
A11	3.2	uR/hr	No	partial grid-exterior wall within grid. 70% accessible	Dining Room		uR/hr	
B2	3.2	uR/hr	No	partial grid 40%, remainder of grid is exterior	Living Room		uR/hr	
B3	3.2	uR/hr	No		Living Room		uR/hr	
B4	3.6	uR/hr	No		Living Room		uR/hr	
B5	3.2	uR/hr	No	partial grid, 70% accessible, installed stove in kitchen grid	Living Room		uR/hr	
B6	3.2	uR/hr	No	partial grid- installed stove. 30% accessible	Kitchen		uR/hr	
B7	3.2	uR/hr	No	partial grid- wood base cabinet 3" above floor surveyed	Kitchen		uR/hr	
B8	3.2	uR/hr	No		Dining Room		uR/hr	
B9	3.2	uR/hr	No		Dining Room		uR/hr	
B10	3.6	uR/hr	No		Dining Room		uR/hr	
B11	2.8	uR/hr	No	partial grid-exterior wall within grid. 70% accessible	Dining Room		uR/hr	
C2	2.8	uR/hr	No	partial grid 40%, remainder of grid is exterior	Living Room		uR/hr	
C3	3.2	uR/hr	No		Living Room		uR/hr	
C4	3.2	uR/hr	No		Living Room		uR/hr	
C5	3.2	uR/hr	No		Living Room	3.2	uR/hr	Kitchen
C6	3.2	uR/hr	No		Kitchen		uR/hr	
C7	3.2	uR/hr	No		Kitchen		uR/hr	
C8	3.2	uR/hr	No		Dining Room		uR/hr	



**Summary Report
1301 Gateview Avenue Unit A**

Grid	Reading	Reading Units	Anomaly	Notes	Cell Description	Second Reading	Second Reading Units	Second Reading Cell Description
C9	3.2	uR/hr	No		Dining Room		uR/hr	
C10	3.2	uR/hr	No		Dining Room		uR/hr	
C11	3.2	uR/hr	No		Dining Room	2.8	uR/hr	Trash
C12	2.8	uR/hr	No		Trash		uR/hr	
C13		uR/hr	No	N/A grid covers outside exterior	Trash		uR/hr	
D1	3.2	uR/hr	No	partial grid, 10% accessible, remainder is exterior	Living Room		uR/hr	
D2	3.2	uR/hr	No	partial grid, 80% accessible, remainder of grid is exterior	Living Room		uR/hr	
D3	3.6	uR/hr	No		Living Room		uR/hr	
D4	3.6	uR/hr	No		Living Room		uR/hr	
D5	3.6	uR/hr	No	partial grid, 80% accessible, kitchen section gas installed base cabinets	Living Room		uR/hr	
D6	3.2	uR/hr	No		Kitchen		uR/hr	
D7	3.2	uR/hr	No	wood base cabinet 3" above floor surveyed	Kitchen		uR/hr	
D8	3.2	uR/hr	No		Hallway		uR/hr	
D9	3.2	uR/hr	No		Hallway		uR/hr	
D10	3.2	uR/hr	No		Hallway		uR/hr	
E1	3.2	uR/hr	No		Living Room		uR/hr	
E2	3.6	uR/hr	No		Living Room		uR/hr	
E3	3.2	uR/hr	No		Living Room		uR/hr	
E4	3.6	uR/hr	No		Living Room		uR/hr	
E5	3.6	uR/hr	No		Living Room		uR/hr	
E6	3.2	uR/hr	No		Hallway		uR/hr	
E7	3.2	uR/hr	No		Hallway		uR/hr	
E8	3.2	uR/hr	No		Hallway		uR/hr	
E9	3.2	uR/hr	No	partial grid 70% accessible, remainder in MECH room N/A	Hallway		uR/hr	
E10	2.8	uR/hr	No	partial grid- installed water heater, 10% accessible	Mech Room		uR/hr	
E11	2.8	uR/hr	No	partial grid- 20% accessible, remainder of grid is outside exterior	Storage		uR/hr	
E12	2.8	uR/hr	No	partial grid- 30% accessible, remainder of grid is outside exterior	Storage		uR/hr	

Grid	Reading	Reading Units	Anomaly	Notes	Cell Description	Second Reading	Second Reading Units	Second Reading Cell Description
E13		uR/hr	No	N/A grid covers outside exterior	Storage		uR/hr	
F1	3.2	uR/hr	No		Living Room		uR/hr	
F2	3.6	uR/hr	No		Living Room		uR/hr	
F3	3.2	uR/hr	No		Living Room		uR/hr	
F4	3.6	uR/hr	No		Living Room		uR/hr	
F5	3.6	uR/hr	No		Living Room	3.2	uR/hr	Closet
F6	3.2	uR/hr	No	partial grid 90% accessible, remainder is interior wall	Storage		uR/hr	
F7	3.2	uR/hr	No	contact reading stairs .4 meters or 16 inches	Stairs		uR/hr	
F8	3.2	uR/hr	No		Bathroom		uR/hr	
F9	3.2	uR/hr	No		Utility		uR/hr	
F10	3.2	uR/hr	No		Utility		uR/hr	
F11	3.2	uR/hr	No		Storage	2.8	uR/hr	Bathroom
F12	3.2	uR/hr	No		Storage		uR/hr	
F13		uR/hr	No	N/A grid covers outside exterior	Storage		uR/hr	
G1	3.2	uR/hr	No		Living Room		uR/hr	
G2	3.2	uR/hr	No		Living Room		uR/hr	
G3	3.6	uR/hr	No		Living Room		uR/hr	
G4	3.6	uR/hr	No		Living Room		uR/hr	
G5	3.6	uR/hr	No	partial grid, 80% accessible, remainder of grid under staircase	Living Room	3.2	uR/hr	Closet
G6	3.2	uR/hr	No	partial grid, 25% accessible, remainder of grid under staircase	Storage		uR/hr	
G7	2.8	uR/hr	No	contact reading stairs 1 meter or 39 inches	Stairs		uR/hr	
G8	3.6	uR/hr	No		Bathroom		uR/hr	
G9	3.6	uR/hr	No		Utility		uR/hr	
G10	3.2	uR/hr	No		Utility		uR/hr	
G11	3.2	uR/hr	No		Storage	3.2	uR/hr	Bathroom
G12	3.2	uR/hr	No		Storage		uR/hr	
G13		uR/hr	No	N/A grid covers outside exterior	Storage		uR/hr	

Summary Report
1301 Gateview Avenue Unit A

Grid	Reading	Reading Units	Anomaly	Notes	Cell Description	Second Reading	Second Reading Units	Second Reading Cell Description
H1	3.2	uR/hr	No	partial grid, 50% accessible, remainder of grid exterior	Living Room		uR/hr	
H2	3.2	uR/hr	No	partial grid, 50% accessible, remainder of grid exterior	Living Room		uR/hr	
H3	3.2	uR/hr	No	partial grid, 50% accessible, remainder of grid exterior	Living Room		uR/hr	
H4	3.2	uR/hr	No	partial grid, 50% accessible, remainder of grid exterior	Living Room		uR/hr	
H5	3.2	uR/hr	No	partial grid, 20% accessible, remainder of grid N/A exterior and under staircase	Living Room		uR/hr	
H6	2.8	uR/hr	No	contact reading stairs 1.35 meters or 52.5 inches	Stairs		uR/hr	
H7	2.8	uR/hr	No	contact reading stairs 1.35 meters or 52.5 inches	Stairs		uR/hr	
H8	4.0	uR/hr	No		Bathroom		uR/hr	
H9	4.0	uR/hr	No	50% near toilet, 50% in tub	Bathroom	3.2	uR/hr	Bathroom
H10	2.8	uR/hr	No	grid fully in bathtub	Bathroom		uR/hr	
H11	2.8	uR/hr	No	partial grid- 30% accessible, remainder of grid n/a exterior wall and interior wall and tub	Storage		uR/hr	
H12	3.2	uR/hr	No	partial grid- 50% accessible, remainder of grid is outside exterior	Storage		uR/hr	
H13		uR/hr	No	N/A grid covers outside exterior	Storage		uR/hr	



CBI Supervisor : Joyce McGee

Senior Technician : Efraim Ramirez

Signature :

A handwritten signature in black ink on a light blue rectangular background. The signature appears to read "J. McGee".

Signature :

A handwritten signature in black ink on a light blue rectangular background. The signature is stylized and appears to read "Efraim Ramirez".



Summary Report
1301 Gateview Avenue Unit B

Unit Summary :

Completion Date: 8/7/2014 10:36 AM

Instrument: 193-6

Serial #: 309127

Layout: Floor Plan 7

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.5

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

ADA converted half of living room to bedroom,
utility to bathroom and storage to utility. D11, D12
and E11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 112

Average: 3.62 uR/hr

Standard Deviation: 0.24 uR/hr

Minimum: 2.80 uR/hr


Maximum: 4.40 uR/hr

Median: 3.20 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Stairs		4.0	uR/hr	Living Room			uR/hr			No	Stairs reading taken 60" from floor.
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 60" from floor.
A7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 60" from floor.
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Bathroom		4.4	uR/hr	Bathroom			uR/hr			No	Utility converted into Bathroom.
A10	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	Utility converted into Bathroom.
A11	3.6	uR/hr	Utility	Washing machine within grid.		uR/hr				uR/hr			No	75% accessible. Storage converted into Utility.
A12	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible. Partial grid due to installed dryer. Storage converted into Utility.
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room			uR/hr			No	



Summary Report
1301 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.6	uR/hr	Storage		3.6	uR/hr	Stairs			uR/hr			No	Stairs reading taken 44" from floor.
B7	3.6	uR/hr	Stairs		3.2	uR/hr	Hallway		3.6	uR/hr	Bathroom		No	Stairs reading taken 44" from floor.
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Bathroom		4.0	uR/hr	Bathroom			uR/hr			No	Utility converted into Bathroom.
B10	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	Utility converted into Bathroom.
B11	3.6	uR/hr	Utility			uR/hr				uR/hr			No	Storage converted into Utility.
B12	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible. Storage converted into Utility.
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Living Room		No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Stairs		No	Stairs reading taken 12" from floor.
C7	3.6	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 12" from floor.
C8	3.6	uR/hr	Hallway		3.6	uR/hr	Bathroom			uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C9	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	80% accessible. Partial grid in mech room inaccessible due to installed furnace. Utility converted into Bathroom.
C10	3.6	uR/hr	Bathroom		3.6	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible. Utility converted into Bathroom.
C11	3.2	uR/hr	Utility			uR/hr				uR/hr			No	Storage converted into Utility.
C12	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible. Storage converted into Utility.
D1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	80% accessible. Partial grid in mech room inaccessible due to installed furnace.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.6	uR/hr	Mech Room	Percentage of grid falls outside of unit.		uR/hr			No	20% accessible. Partial grid due to installed water heater.
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible. Living room converted into Bedroom.
E3	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Living room converted into Bedroom.
E4	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Living room converted into Bedroom.
E5	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Bedroom			uR/hr			No	Living room converted into Bedroom.
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	
E8	3.6	uR/hr	Hallway		3.6	uR/hr	Dining Room			uR/hr			No	
E9	4.0	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
E11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F2	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible. Living room converted into Bedroom.
F3	4.0	uR/hr	Bedroom			uR/hr				uR/hr			No	Living room converted into Bedroom. Bed moved for survey
F4	4.0	uR/hr	Bedroom			uR/hr				uR/hr			No	Living room converted into Bedroom. Bed moved for survey
F5	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Bedroom			uR/hr			No	Living room converted into Bedroom. Bed moved for survey
F6	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	80% accessible.
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible.
G2	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible. Living room converted into Bedroom.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G3	4.0	uR/hr	Bedroom			uR/hr				uR/hr			No	Living room converted into Bedroom. Bed moved for survey
G4	4.0	uR/hr	Bedroom			uR/hr				uR/hr			No	Living room converted into Bedroom. Bed moved for survey
G5	4.0	uR/hr	Bedroom			uR/hr				uR/hr			No	20% accessible. Kitchen reading inaccessible due to installed stove. Living room converted into Bedroom.
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	4.0	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	Kitchen reading taken 12" from floor inside base cabinet.
G8	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible.
H2	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	45% accessible.
H3	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible. Living room converted into Bedroom. Bed moved for survey



Summary Report
1301 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H4	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible. Living room converted into Bedroom. Bed moved for survey
H5	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible. Kitchen reading is inaccessible due to base cabinet. Living room converted into Bedroom.
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible. Kitchen reading taken 12" from floor inside base cabinet.
H7	4.0	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible. Kitchen reading taken 12" from floor inside base cabinet.
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Summary Report
1301 Gateview Avenue Unit C

Unit Summary :

Completion Date: 8/11/2014 12:59 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.7
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Bed in living room moved for survey. Grids in column I, row 13 and D11 fall outside of unit.

Summary Statistics :

Total # of Readings: 133
Average: 3.40 uR/hr
Standard Deviation: 0.26 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	30% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	Partial grid in Kitchen inaccessible due to installed stove. 40% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



**Summary Report
1301 Gateview Avenue Unit C**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Living Room		3.2	uR/hr	Hallway		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	No	



Summary Report
1301 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D6	3.2	uR/hr	Hallway		3.6	uR/hr	Kitchen			uR/hr			No	refrigerator moved for survey
D7	3.2	uR/hr	Hallway		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway		2.8	uR/hr	Mech Room	Installed furnace.		uR/hr			No	60% accessible
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	20% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible installed hot water heater
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



**Summary Report
1301 Gateview Avenue Unit C**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Hallway		3.6	uR/hr	Storage		3.2	uR/hr	Stairs		No	stair static taken at 12" above floor
F7	3.2	uR/hr	Hallway		3.2	uR/hr	Stairs			uR/hr			No	stair static taken at 12" above floor
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Hallway	Installed furnace.	3.2	uR/hr	Utility			uR/hr			No	70% accessible
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room			uR/hr			No	
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken at 44" above floor



**Summary Report
1301 Gateview Avenue Unit C**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		2.8	uR/hr	Stairs		No	stair static taken at 44" above floor
G8	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
G9	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Utility	Washing machine within grid.	No	70% accessible
G10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	70% accessible
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	70% accessible, stair static taken at 60" above floor
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	stair static taken at 60" above floor, 70% accessible



Summary Report
1301 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H7	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	70% accessible. Survey performed within accessible base cabinet. Stair static taken at 60" above floor
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible. Survey performed within accessible base cabinet.
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr			No	70% accessible. Washing machine within grid
H10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	40% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1301 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1301 Gateview Avenue Unit D

Unit Summary :

Completion Date: 8/7/2014 1:28 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.7
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids D11 and D12 fall outside unit.

Summary Statistics :

Total # of Readings: 110
Average: 3.41 uR/hr
Standard Deviation: 0.27 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken 60" above floor
A7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken 60" above floor
A8	3.2	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.2	uR/hr	Utility	Washing machine within grid.		uR/hr			No	70% accessible
A10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	50% accessible
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken 44" above floor



Summary Report
1301 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken 44" above floor
B8	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Utility		No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.6	uR/hr	Hallway			uR/hr			No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.2	uR/hr	Stairs		No	stair static taken 12" above floor
C7	3.6	uR/hr	Hallway		3.2	uR/hr	Stairs			uR/hr			No	stair static taken 12" above floor
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway	Installed furnace.	3.2	uR/hr	Utility			uR/hr			No	80% accessible
C10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
C11	3.2	uR/hr	Storage		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1301 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D5	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	80% accessible
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	installed furnace 60% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.6	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	30% accessible
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	70% accessible



**Summary Report
1301 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
F6	3.6	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	80% accessible
F7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	60% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	installed dishwasher 80% accessible
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	70% accessible
H6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	installed dishwasher 60% accessible remainder of grid fall outside
H7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid 70% accessible remainder of grid fall outside



Summary Report
1301 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/12/2014 2:15 PM
Instrument: 193-6
Serial #: 309119
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 125
Average: 2.94 uR/hr
Standard Deviation: 0.24 uR/hr
Minimum: 2.00 uR/hr
Maximum: 3.20 uR/hr
Median: 2.40 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	Installed refrigerator moved for survey.
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	40% accessible. Partial grid in kitchen inaccessible due to installed stove



Summary Report
1302 (905) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Trash			uR/hr			No	90% accessible
C12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



Summary Report
1302 (905) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	85% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		2.8	uR/hr	Kitchen		No	
D6	3.2	uR/hr	Kitchen		2.8	uR/hr	Hallway			uR/hr			No	Installed refrigerator moved for survey
D7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	40% accessible. Partial grid in mech room inaccessible due to installed furnace
E10	2.8	uR/hr	Mech Room	Installed water heater.	2.4	uR/hr	Hallway			uR/hr			No	10% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
F6	2.8	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken at 0.4 meters above ground floor
F7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken at 0.4 meters above ground floor
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Utility		2.8	uR/hr	Hallway			uR/hr			No	
F10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	stair static taken at 1.2 meters above ground floor
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken at 0.8 meters above ground floor
G8	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Utility	Washing machine within grid.	2.8	uR/hr	Bathroom			uR/hr			No	90% accessible
G10	2.8	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	70% accessible
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.0	uR/hr	Stairs			uR/hr			No	60% accessible, stair static taken at 1.5 meters above ground floor
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, stair static taken at 1.5 meters above ground floor
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, stair static taken at 1.5 meters above ground floor
H8	2.8	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.	3.2	uR/hr	Bathroom			uR/hr			No	60% accessible, installed washer moved for survey
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible



Summary Report
1302 (905) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1302 (905) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/12/2014 2:52 PM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Grids D11, D12, and E12 are outside of floor plan. E11 grid less than 6" wide and was surveyed along with adjacent grid.

Summary Statistics :

Total # of Readings: 107
Average: 3.20 uR/hr
Standard Deviation: 0.24 uR/hr
Minimum: 2.40 uR/hr
Maximum: 3.60 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	Stairs reading taken 60" from floor.
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 60" from floor.
A7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 60" from floor.
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Utility	Washing machine within grid.	3.6	uR/hr	Bathroom			uR/hr			No	50% accessible.
A10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	40% accessible.
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Storage		2.4	uR/hr	Stairs		3.2	uR/hr	Living Room		No	Stairs reading taken 60" from floor.
B6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	Stairs reading taken 60" from floor.
B7	2.4	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	Stairs reading taken 60" from floor.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B8	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Storage		3.2	uR/hr	Hallway			uR/hr			No	
C6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs		3.2	uR/hr	Hallway		No	Stairs reading taken 12" from floor.
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	Stairs reading taken 12" from floor.
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	50% accessible. Partial grid in Mech room inaccessible due to installed furnace.
C10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible.
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	50% accessible. Partial grid in Mech room inaccessible due to installed furnace.
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. Partial grid in Mech room inaccessible due to installed furnace.
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1302 (905) Avenue B Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	60% accessible.
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	20% accessible. Partial grid in kitchen inaccessible due to installed stove.
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. Partial grid in kitchen inaccessible due to installed base cabinet.
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Kitchen reading taken 12" from floor inside base cabinet.
H7	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible. Installed dishwasher



Summary Report
1302 (905) Avenue B Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.




CBI Supervisor : Garrick Anderson

Senior Technician : John Massey

Signature :



Signature :



Signoff Notes:




Completion Date:	8/12/2014 1:48 PM		
Instrument:	193-6		
Serial #:	309136		
Layout:	Floor Plan 7B		
Background Reading:	2.8	uR/hr	
Dimensions (m):	D	11.8	W 7.6
Unit Furnished:	Yes		
Tenant Present:	Yes		

Grids in column I, row 13, and D11 are outside of survey unit.

Total # of Readings:	129	
Average:	2.68	uR/hr
Standard Deviation:	0.27	uR/hr
Minimum:	2.00	uR/hr
Maximum:	3.60	uR/hr
Median:	2.40	uR/hr
# Anomalies:	0	

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Living Room		2.4	uR/hr	Kitchen			uR/hr			No	
A6	2.4	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	30% accessible, survey inside installed cabinets
A8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	survey scan through 1" wood bookcase base 30% of grid
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	survey scan through 1" wood bookcase base 30% of grid
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B5	2.8	uR/hr	Living Room	Installed Stove.	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	30% accessible
B6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen			uR/hr			No	
C6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Trash			uR/hr			No	60% accessible
C12	2.4	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
D1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Living Room		2.4	uR/hr	Hallway		2.4	uR/hr	Kitchen		No	
D6	2.8	uR/hr	Kitchen		2.4	uR/hr	Dining Room			uR/hr			No	refrigerator moved for survey
D7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.4	uR/hr	Dining Room			uR/hr			No	
D8	2.4	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.4	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.4	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.4	uR/hr	Living Room		2.8	uR/hr	Hallway			uR/hr			No	
E6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.4	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	30% accessible
E10	2.4	uR/hr	Mech Room	Installed water heater.		uR/hr				uR/hr			No	30% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	surveyed through 1" wood TV stand in living room
F6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	Stair static taken at 0.5 meters above ground level
F7	2.4	uR/hr	Stairs		2.4	uR/hr	Hallway			uR/hr			No	Stair static taken at 0.5 meters above ground level
F8	2.4	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	2.4	uR/hr	Utility		2.8	uR/hr	Hallway			uR/hr			No	
F10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Living Room		2.0	uR/hr	Stairs		2.8	uR/hr	Storage		No	surveyed through 1" wood aquarium pedestal in living room, Stair static taken at 1.5 meters above ground level
G6	2.8	uR/hr	Storage		2.0	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.3 meters above ground level
G7	2.0	uR/hr	Stairs		2.8	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.3 meters above ground level
G8	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Utility		2.8	uR/hr	Bathroom			uR/hr			No	
G10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.4	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.0	uR/hr	Stairs			uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground level, surveyed through 1" wood aquarium pedestal in living room
H6	2.0	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground level
H7	2.0	uR/hr	Stairs	Percentage of grid falls outside of unit.	2.8	uR/hr	Bathroom			uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground level
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	60% accessible
H10	2.4	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, moved dryer for survey

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan




Summary Report
1302 (905) Avenue B Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan


CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 6/24/2014 4:10 PM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.51 W 7.61
Unit Furnished: No
Tenant Present: No


Unit Notes:

Summary Statistics :

Total # of Readings: 87
Average: 3.50 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.40 uR/hr
Median: 3.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	stairs reading taken 58" from floor
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stairs reading taken 58" from floor
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stairs reading taken 58" from floor
A8	4.4	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Utility		4.4	uR/hr	Bathroom			uR/hr			No	
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	No washer or dryer
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
B6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	stairs reading taken 28" from floor
B7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway		3.6	uR/hr	Bathroom		No	stairs reading taken 28" from floor
B8	3.6	uR/hr	Hallway		3.6	uR/hr	Bathroom			uR/hr			No	
B9	3.6	uR/hr	Utility		3.6	uR/hr	Hallway		3.6	uR/hr	Bathroom		No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway		3.2	uR/hr	Storage		No	
C6	3.6	uR/hr	Hallway		3.6	uR/hr	Storage		3.2	uR/hr	Stairs		No	stairs reading taken 12" from floor
C7	3.6	uR/hr	Hallway		3.6	uR/hr	Stairs		3.2	uR/hr	Bathroom		No	stairs reading taken 12" from floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Hallway		3.6	uR/hr	Utility		3.6	uR/hr	Storage	Installed furnace.	No	30% accessible
C10	3.2	uR/hr	Utility		3.6	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
C11	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	85% accessible
C12	3.2	uR/hr	Storage			uR/hr				uR/hr			No	85% accessible
D1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	installed base cabinets in kitchen
E6	3.2	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	60% accessible. installed base cabinets
E7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	installed base cabinets
E8	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	25% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Installed base cabinets.		uR/hr			No	installed base cabinet in kitchen. 90% accessible due to installed stove
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	installed base cabinets
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	installed base cabinet in grid
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room	Installed base cabinets.		uR/hr				uR/hr			No	30% accessible. installed stove and base cabinets in kitchen
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Grid partially obstructed by installed.		uR/hr				uR/hr			No	90% accessible, dishwasher
G8	3.6	uR/hr	Dining Room	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	installed base cabinet in grid

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. installed stove base cabinets in kitchen
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. installed base cabinets
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. installed base cabinets
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. installed base cabinet in grid.
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible


CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/19/2014 10:48 AM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Living room was used as bedroom. Grids in column I, row 13 and D11 fall outside of floor plan.

Summary Statistics :

Total # of Readings: 130
Average: 3.01 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
A6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1302 (905) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Trash		2.8	uR/hr	Dining Room			uR/hr			No	
C12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room		No	
D6	2.8	uR/hr	Hallway		3.2	uR/hr	Kitchen			uR/hr			No	moved installed refrigerator to survey grid
D7	2.8	uR/hr	Hallway		3.2	uR/hr	Kitchen			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1302 (905) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Mech Room	Installed furnace.	3.2	uR/hr	Hallway			uR/hr			No	60% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F7	3.2	uR/hr	Hallway		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Hallway		3.2	uR/hr	Utility			uR/hr			No	



Summary Report
1302 (905) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F10	2.8	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	
G6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G7	3.2	uR/hr	Bathroom		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G8	3.2	uR/hr	Hallway		3.2	uR/hr	Bathroom			uR/hr			No	
G9	3.2	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1302 (905) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	60% accessible, static taken on stairs 56" from floor surface
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, static taken on stairs 56" from floor surface
H7	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	60% accessible, static taken on stairs 56" from floor surface
H8	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.	4.0	uR/hr	Bathroom			uR/hr			No	60% accessible, static taken by toilet, moved installed washer to survey grid
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, moved installed dryer to survey grid
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1302 (905) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan




Summary Report
1302 (905) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan


CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/19/2014 10:33 AM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Grid E12 is outside unit interior boundary. Moved bed in living room to survey grids.

Summary Statistics :

Total # of Readings: 110
Average: 3.33 uR/hr
Standard Deviation: 0.26 uR/hr
Minimum: 2.40 uR/hr
Maximum: 3.60 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		3.6	uR/hr	Living Room			uR/hr			No	
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	
A7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	moved washer to survey grid
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	moved dryer to survey grid
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.6	uR/hr	Storage			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor
B8	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Utility		3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	



Summary Report
1302 (905) Avenue B Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
C6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs		3.2	uR/hr	Hallway		No	reading .6 meters from floor for stairs
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	reading .6 meters from floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Utility	Installed furnace.	3.6	uR/hr	Hallway			uR/hr			No	75% accessible
C10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible



Summary Report
1302 (905) Avenue B Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D10	3.2	uR/hr	Hallway	Installed water heater.		uR/hr				uR/hr			No	30% accessible
D11	3.2	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr			No	15% accessible
D12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid
E7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	moved bed to survey grid



Summary Report
1302 (905) Avenue B Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	moved bed to survey grid
F5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr			No	90% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	moved bed to survey grid
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	moved bed to survey grid
G5	3.2	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	50% accessible



Summary Report
1302 (905) Avenue B Unit F


Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. moved bed to survey grid
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. moved bed to survey grid
H5	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible- installed dishwasher
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible- installed dishwasher
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Summary Report
1303 Gateview Avenue Unit A

Unit Summary :

Completion Date: 7/15/2014 2:28 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 12 W 7.7
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Grids I1 thru I12 are outside of floor plan.

Summary Statistics :

Total # of Readings: 113
Average: 3.44 uR/hr
Standard Deviation: 0.27 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid 80% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	50% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



**Summary Report
1303 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	4.0	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	80% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Trash	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1303 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Kitchen	Installed base cabinets.	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway		No	40% accessible
D6	3.6	uR/hr	Kitchen		3.6	uR/hr	Hallway			uR/hr			No	(installed refrigerator) inspector measurement ID: K-40 NORM File name: 201407151339 35
D7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	40% accessible



**Summary Report
1303 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible (installed hot water heater)
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E12	3.2	uR/hr	Storage	Survey performed on non-movable item.		uR/hr				uR/hr			No	partial grid - percentage of grid falls outside of unit, 20% accessible, (non-movable item is a PVC shelf attached to wall)
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	stairs static taken 20" above floor
F7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	static taken 20" above floor
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Hallway	Installed furnace.	3.2	uR/hr	Utility			uR/hr			No	80% accessible
F10	2.8	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Utility			uR/hr			No	80% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage			uR/hr				uR/hr			No	



**Summary Report
1303 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
G6	4.0	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken 44" above floor
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	static taken 44" above floor
G8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
G9	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		3.2	uR/hr	Utility		No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1303 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	Static taken 60" above floor (70% accessible)
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken 60" above floor (70% accessible)
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken 60" above floor (70% accessible)
H8	3.6	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid 70% accessible
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.6	uR/hr	Utility	Clothes dryer within grid.		uR/hr			No	40% accessible
H10	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible (installed washing machine)
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1303 Gateview Avenue Unit B

Unit Summary :

Completion Date: 6/30/2014 4:10 PM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.7 W 7.6
Unit Furnished: No
Tenant Present: No


Unit Notes:

Summary Statistics :

Total # of Readings: 87
Average: 3.57 uR/hr
Standard Deviation: 0.20 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.40 uR/hr
Median: 3.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 60" from floor
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 60" from floor
A7	3.6	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 60" from floor
A8	4.4	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	No washer or dryer in Utility Room
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
B6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	Stairs reading taken 44" from floor
B7	3.6	uR/hr	Hallway		3.6	uR/hr	Bathroom		3.2	uR/hr	Stairs		No	Stairs reading taken 44" from floor
B8	3.6	uR/hr	Hallway		3.6	uR/hr	Bathroom			uR/hr			No	



Summary Report
1303 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Hallway		4.0	uR/hr	Bathroom		4	uR/hr	Utility		No	
B10	3.6	uR/hr	Utility		3.6	uR/hr	Storage			uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway		3.6	uR/hr	Storage		No	
C6	3.6	uR/hr	Hallway		3.6	uR/hr	Storage		3.6	uR/hr	Stairs		No	static on stairs taken at 12 inches from the floor surface
C7	3.6	uR/hr	Hallway		3.6	uR/hr	Stairs		3.6	uR/hr	Bathroom		No	static on stairs taken at 12 inches from the floor surface
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway	Installed furnace.	3.6	uR/hr	Utility			uR/hr			No	50% accessible. Partial grid-Partial grid due to installed furnace in Mech Room
C10	3.6	uR/hr	Utility		3.6	uR/hr	Mech Room	Installed water heater.		uR/hr			No	30% accessible
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



**Summary Report
1303 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
E8	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.6	uR/hr	Hallway		3.6	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	40% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible



Summary Report
1303 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	80% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	30% accessible. Partial grid-partial grid due to installed stove in kitchen
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	



Summary Report
1303 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	60% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Survey performed within accessible base cabinet
H7	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. Partial grid-Partial grid due to installed dishwasher
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1303 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :

Signature :

Signoff Notes:



Summary Report
1303 Gateview Avenue Unit C

Unit Summary :

Completion Date: 7/15/2014 2:49 PM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7B
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids I1 through I13 are outside of floor plan

Summary Statistics :

Total # of Readings: 124
Average: 2.96 uR/hr
Standard Deviation: 0.29 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr			No	60% accessible
A6	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	90% accessible
A7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	60% accessible
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	90% accessible
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



Summary Report
1303 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Trash		2.8	uR/hr	Dining Room			uR/hr			No	
C12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
C13		uR/hr	Trash	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
D1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Kitchen		2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		No	
D6	4.0	uR/hr	Kitchen		3.6	uR/hr	Hallway			uR/hr			No	Moved refrigerator 100% scanned
D7	3.6	uR/hr	Kitchen	Installed base cabinets.	2.8	uR/hr	Hallway			uR/hr			No	60% accessible
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1303 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
D11		uR/hr		Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Mech Room	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	40% accessible, static taken 22" from floor surface in mech room
E10	2.8	uR/hr	Mech Room	Installed water heater.	2.8	uR/hr	Hallway			uR/hr			No	40% accessible
E11	2.8	uR/hr	Utility		2.8	uR/hr	Hallway			uR/hr			No	
E12	2.8	uR/hr	Storage			uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	



Summary Report
1303 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F6	2.8	uR/hr	Stairs		2.8	uR/hr	Storage		2.8	uR/hr	Hallway		No	static taken on stairs 16" from floor surface
F7	2.8	uR/hr	Stairs		2.8	uR/hr	Hallway			uR/hr			No	static taken on stairs 16" from floor surface
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Mech Room	Installed furnace.	2.8	uR/hr	Utility		2.8	uR/hr	Hallway		No	60% accessible
F10	2.8	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	
G6	2.4	uR/hr	Stairs		2.8	uR/hr	Storage			uR/hr			No	static taken on stairs 48" from floor surface
G7	2.4	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 48" from floor surface
G8	3.2	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
G9	2.8	uR/hr	Utility		3.2	uR/hr	Bathroom		2.8	uR/hr	Hallway		No	
G10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1303 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.	2.8	uR/hr	Living Room			uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.	2.8	uR/hr	Bathroom			uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	2.8	uR/hr	Utility	Washing machine within grid.		uR/hr			No	40% accessible
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible. Clothes dryer within grid.



Summary Report
1303 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes	
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility			uR/hr			No	60% accessible	
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible	
H13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan	



CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized and appears to read "N. Rothell".

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized and appears to read "Ricky Laguna".

Signoff Notes:



Summary Report
1303 Gateview Avenue Unit D

Unit Summary :

Completion Date: 7/15/2014 1:36 PM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.7 W 7.6
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:

Summary Statistics :

Total # of Readings: 107
Average: 3.48 uR/hr
Standard Deviation: 0.29 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	static reading 1.8 meters from floor
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static reading 1.8 meters from floor
A7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static reading 1.8 meters from floor
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	moved clothes dryer in utility room to survey grid
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	moved clothes washer and dryer to survey grid
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Storage		3.6	uR/hr	Living Room			uR/hr			No	
B6	3.6	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	static reading 1.3 meters from floor



Summary Report
1303 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static reading 1.3 meters from floor
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		3.6	uR/hr	Utility		No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Storage		3.6	uR/hr	Living Room		3.6	uR/hr	Hallway		No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.2	uR/hr	Stairs		No	static reading .6 meters from floor
C7	3.2	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	static reading .6 meters from floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway	Installed furnace.	3.6	uR/hr	Utility			uR/hr			No	75% accessible
C10	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	75% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1303 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D5	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible-installed water heater
D11	4.0	uR/hr	Storage	Installed water heater.		uR/hr				uR/hr			No	10% accessible. Measurement taken with Model 19 s/n 267078, entry 1 -meter 4 microR/hr
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid
E7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	static reading taken at 4" due to cabinet shelf
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1303 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible. Moved 2nd refrigerator to survey grid
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	50% accessible from living room, kitchen half of grid installed stove.
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1303 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.6	uR/hr	Kitchen			uR/hr			No	60% accessible
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible-installed dishwasher
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1303 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Summary Report
1303 Gateview Avenue Unit E

Unit Summary :

Completion Date: 7/15/2014 2:47 PM

Instrument: 193-6

Serial #: 309119

Layout: Floor Plan 7B

Background Reading: 3.2 uR/hr

Dimensions (m): D 12 W 7.5

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids I1 through I13 are outside of floor plan.
From front door to back of unit is 9.4 m deep,
length from back of unit to dining room is 10.3 m

Summary Statistics :

Total # of Readings: 109

Average: 3.12 uR/hr

Standard Deviation: 0.27 uR/hr

Minimum: 2.40 uR/hr


Maximum: 4.00 uR/hr

Median: 2.80 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible, survey performed in installed base cabinets
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	20% accessible, stove in kitchen grid
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	



**Summary Report
1303 Gateview Avenue Unit E**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Dining Room		2.8	uR/hr	Trash			uR/hr			No	
C12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
C13		uR/hr	Trash	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



**Summary Report
1303 Gateview Avenue Unit E**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
D6	3.2	uR/hr	Kitchen	Installed refrigerator.	3.2	uR/hr	Hallway	Grid partially contained within wall construction.		uR/hr			No	40% accessible, survey performed in installed base cabinets
D7	3.2	uR/hr	Kitchen	Installed base cabinets.	3.2	uR/hr	Hallway	Grid partially contained within wall construction.		uR/hr			No	50% accessible
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr		Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	80% accessible, furnace installed in mechanical room portion of grid cell.
E10	2.4	uR/hr	Mech Room	Installed water heater.	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr			No	70% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading on stairs taken at .4 m from ground level
F7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading on stairs taken at .4 m from ground level
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	
F10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	reading on stairs taken at 1.4 m from ground level
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading on stairs taken at 1 m from ground level
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
G13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	50% accessible, reading on stairs taken at 1.5 m from ground level
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, reading on stairs taken at 1.5 m from ground level
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, reading on stairs taken at 1.5 m from ground level
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, survey performed in installed base cabinets
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility	Washing machine within grid.		uR/hr			No	50% accessible, washer moved for survey
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, dryer moved for survey
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :

Signature :

Signoff Notes:



Summary Report
1303 Gateview Avenue Unit F

Unit Summary :

Completion Date: 6/30/2014 3:57 PM

Instrument: 193-6

Serial #: 309127

Layout: Floor Plan 7

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.7 W 7.6

Unit Furnished: No

Tenant Present: No

Unit Notes:


Elevated measurement located 117.5" S along E dining room wall from N end to intersect the open door (mid point) to the hallway and 115" E from W dining room wall to intersect N-S centerline.

Summary Statistics :

Total # of Readings: 113
Average: 3.64 uR/hr
Standard Deviation: 0.60 uR/hr
Minimum: 2.80 uR/hr
Maximum: 8.80 uR/hr
Median: 3.20 uR/hr
Anomalies: 1

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken at 60" from floor
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken at 60" from floor
A7	2.8	uR/hr	Stairs		4.0	uR/hr	Bathroom			uR/hr			No	Stairs reading taken at 60" from floor
A8	5.6	uR/hr	Bathroom			uR/hr				uR/hr			No	Reading taken at left side of the toilet. K-40 NORM File name 201406301510 07 MCA
A9	4.8	uR/hr	Bathroom		4.0	uR/hr	Utility			uR/hr			No	
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	No washer or dryer installed
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
B6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	Stairs reading taken 44" from floor



**Summary Report
1303 Gateview Avenue Unit F**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.2	uR/hr	Stairs		3.6	uR/hr	Hallway		4	uR/hr	Bathroom		No	Stairs reading taken 44" from floor
B8	3.6	uR/hr	Hallway		4.0	uR/hr	Bathroom			uR/hr			No	
B9	3.6	uR/hr	Hallway		3.6	uR/hr	Utility		4	uR/hr	Bathroom		No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage		3.6	uR/hr	Hallway		No	
C6	3.6	uR/hr	Hallway		3.6	uR/hr	Storage		3.2	uR/hr	Stairs		No	
C7	3.2	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway	Installed furnace.	3.6	uR/hr	Utility	Installed furnace.		uR/hr			No	50% accessible
C10	3.6	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	70% accessible
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1303 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D5	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	4.0	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	4.0	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	80% accessible
D10	3.2	uR/hr	Mech Room	Percentage of grid falls outside of unit.		uR/hr	Hallway			uR/hr			No	50% accessible. Partial grid-partial grid due to installed water heater
D11	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	4.0	uR/hr	Kitchen	Survey performed within accessible base cabinet.	4.4	uR/hr	Hallway			uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E8	8.8	uR/hr	Hallway			uR/hr				uR/hr			Yes	Elevated measurement direct center line doorway, between entry/kitchen. Model19#26707 8 on contact 23, 14 at 4", 11 at 12", 7 at 40"; all uR/hr. 07022014 MCA-File #07022014120 606-GT0101190000 0000-GA0.
E9	3.6	uR/hr	Dining Room		3.6	uR/hr	Hallway			uR/hr			No	
E10	3.6	uR/hr	Dining Room		3.2	uR/hr	Hallway			uR/hr			No	50% accessible.
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
F6	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	4.4	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1303 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	80% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	Reading taken inside of stove 14" from floor.
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	60% accessible



Summary Report
1303 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. Partial grid-partial grid due to installed dishwasher
H7	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Survey performed within accessible base cabinet
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible

Secondary Readings : E8

Secondary Type	Instrument ID	Instrument Serial	Reading	Reading Unit	Bulls Eye Location	ROC
Static Reading - 36 inch height, Center	193-6	309127	4.8	uR/hr		
Static Reading - On Contact, Center	193-6	309127	20.0	uR/hr		
Static Reading - 4 inch height, Bullseye	193-6	309127	16.0	uR/hr	Location 0	
Static Reading - 4 inch height, Bullseye	193-6	309127	10.0	uR/hr	Location 1	
Static Reading - 4 inch height, Bullseye	193-6	309127	12.0	uR/hr	Location 2	
Static Reading - 4 inch height, Bullseye	193-6	309127	12.0	uR/hr	Location 3	
Static Reading - 4 inch height, Bullseye	193-6	309127	12.0	uR/hr	Location 4	
Static Reading - 4 inch height, Bullseye	193-6	309127	7.6	uR/hr	Location 5	
Static Reading - 4 inch height, Bullseye	193-6	309127	8.8	uR/hr	Location 6	
Static Reading - 4 inch height, Bullseye	193-6	309127	12.0	uR/hr	Location 7	
Static Reading - 4 inch height, Bullseye	193-6	309127	7.6	uR/hr	Location 8	
Static Reading - 12 inch height, Center	193-6	309127	8.8	uR/hr		
Inspector 1000 Spectrum	Inspector 1000 Spectrum	13000529				Other

Secondary Type	Notes
Inspector 1000 Spectrum	File#20140630143530 NO NUCLIDE ID'D; Note: 07022014-CDPH Falcon 500 MCA detected Ra-226 only

WIN_20140630_152524.JPG





CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :

Signature :

Signoff Notes:

 ***** N U C L I D E I D E N T I F I C A T I O N R E P O R T *****

Sample Title: Sample title.
 Nuclide Library Used: C:\GENIE2K\CAMFILES\FALCON_LIB.NLB

..... IDENTIFIED NUCLIDES

Nuclide Name	Id Confidence	Energy (keV)	Yield (%)	Activity (uCi/Unit)	Activity Uncertainty
Ra226dau	0.164	53.23	1.20		
		74.82*	6.33	1.05028E-001	1.25962E-002
		76.86	0.40		
		77.11	10.50		
		79.29	0.66		
		86.83	1.28		
		87.35	2.44		
		89.26	0.08		
		89.79	1.05		
		92.32	0.06		
		186.21	3.59		
		242.00	7.43		
		295.22	19.30		
		351.93*	37.60	1.10627E-002	3.48033E-003
		609.31*	46.10	2.66759E-002	3.52117E-003
		1120.29	15.10		
		1238.11	5.79		
		1764.49	15.40		
		2204.21	5.08		

* = Energy line found in the spectrum.

@ = Energy line not used for Weighted Mean Activity

Energy Tolerance : 1.000 FWHM

Nuclide confidence index threshold = 0.10

Errors quoted at 1.000 sigma

 ***** I N T E R F E R E N C E C O R R E C T E D R E P O R T *****

Nuclide Name	Nuclide Id Confidence	Wt mean Activity (uCi/Unit)	Wt mean Activity Uncertainty
Ra226dau	0.164	2.198499E-002	2.428825E-003

? = nuclide is part of an undetermined solution

X = nuclide rejected by the interference analysis

@ = nuclide contains energy lines not used in Weighted Mean Activity

Errors quoted at 1.000 sigma

***** U N I D E N T I F I E D P E A K S *****

Peak Locate Performed on: 7/2/2014 2:28:47 PM
 Peak Locate From Channel: 125
 Peak Locate To Channel: 8192

Peak No.	Energy (keV)	Peak Size in Counts per Second	Peak CPS % Uncertainty	Peak Type	Tol. Nuclide
M 1	73.12	3.4808E-001	8.93		
3	85.08	1.5941E-001	45.65		
6	935.88	2.9645E-002	54.65		
7	1122.46	1.8710E-001	10.24		
8	1380.58	6.9349E-002	17.94		
9	1463.93	4.1262E-001	4.74		
10	1512.23	2.9787E-002	30.80		
11	1665.20	2.5005E-002	29.17		
12	1733.57	5.7130E-002	13.39		
13	1768.43	3.4075E-001	4.51		
14	2209.30	1.4023E-001	6.79		
15	2453.83	6.1485E-002	10.43		
16	2621.47	6.2418E-002	9.92		

M = First peak in a multiplet region

m = Other peak in a multiplet region

F = Fitted singlet

Errors quoted at 1.000 sigma

 ***** G A M M A S P E C T R U M A N A L Y S I S *****

Filename: C:\GENIE2K\CAMFILES\07022014120606-GT01011900000000-GA0.00000

Report Generated On : 7/2/2014 2:58:03 PM

Sample Title : Treasure Island Bldg 1303F
 Sample Description : Hallway/Kitchen Floor
 Sample Identification : 1303F
 Sample Type :

Sample Geometry :
Peak Locate Threshold : 3.00
Peak Locate Range (in channels) : 1 - 65535
Peak Area Range (in channels) : 1 - 65535
Identification Energy Tolerance : 1.000 keV

Sample Size : 1.000E+000 Unit

Sample Taken On : 7/2/2014 12:06:03 PM
Acquisition Started : 7/2/2014 11:35:47 AM

Live Time : 1800.0 seconds
Real Time : 1806.5 seconds

Dead Time : 0.36 %

Energy Calibration Used Done On : 6/13/2011
Efficiency Calibration Used Done On : 4/27/2007
Efficiency ID : Bare version 4



Unit Summary :

Completion Date: 8/12/2014 1:06 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 133
Average: 3.36 uR/hr
Standard Deviation: 0.29 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	20% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	40% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1304 (901) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.6	uR/hr	Trash			uR/hr			No	90% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen		3.2	uR/hr	Hallway		No	
D6	3.6	uR/hr	Kitchen	Installed refrigerator.	3.2	uR/hr	Hallway			uR/hr			No	80% accessible



Summary Report
1304 (901) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	50% accessible
E10	2.8	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr			No	25% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1304 (901) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	stair static taken at 12" above floor
F7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	stair static taken at 12" above floor
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Hallway	Installed furnace.	3.6	uR/hr	Utility			uR/hr			No	70% accessible
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible
F11	3.2	uR/hr	Storage		2.8	uR/hr	Mech Room			uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage		2.4	uR/hr	Stairs		No	stair static taken at 60" above floor
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken at 44" above floor
G7	2.8	uR/hr	Stairs		3.2	uR/hr	Bathroom		3.6	uR/hr	Hallway		No	stair static taken at 44" above floor ,



Summary Report
1304 (901) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G8	3.2	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
G9	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.6	uR/hr	Utility		No	
G10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			2.4	uR/hr	Stairs		No	60% accessible, stair static taken at 60" above floor
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	stair static taken at 60" above floor
H7	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible, stair static taken at 60" above floor

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible surveyed inside accessible base cabinet
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr			No	30% accessible
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. Installed washing machine
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan




Summary Report
1304 (901) Avenue B Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/19/2014 10:32 AM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Grid E12 falls outside of floor plan.

Summary Statistics :

Total # of Readings: 118
Average: 3.29 uR/hr
Standard Deviation: 0.26 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	static taken on stairs at 60" above floor
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static taken on stairs at 60" above floor
A7	3.2	uR/hr	Bathroom	Survey performed within accessible base cabinet.	2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs at 60" above floor
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.6	uR/hr	Utility	Washing machine within grid.		uR/hr			No	40% accessible
A10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	40% accessible
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	2.8	uR/hr	Stairs		3.2	uR/hr	Storage			uR/hr			No	static taken on stairs at 44" above floor

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Stairs		No	static taken on stairs at 44" above floor
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Bathroom		3.2	uR/hr	Utility	Washing machine within grid.	3.6	uR/hr	Hallway		No	90% accessible
B10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	90% accessible
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
C6	3.2	uR/hr	Stairs		3.2	uR/hr	Storage		3.2	uR/hr	Hallway		No	static taken on stairs at 12" above floor
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	static taken on stairs at 12" above floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Hallway		3.6	uR/hr	Utility	Installed furnace.		uR/hr			No	60% accessible
C10	2.8	uR/hr	Mech Room	Installed water heater.	2.8	uR/hr	Utility			uR/hr			No	80% accessible
C11	3.6	uR/hr	Storage		2.8	uR/hr	Mech Room			uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1304 (901) Avenue B Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	80% accessible
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	20% accessible
D11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	Refrigerator in grid moved for survey.
E7	3.2	uR/hr	Kitchen	Installed base cabinets.	3.2	uR/hr	Hallway			uR/hr			No	40% accessible
E8	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.6	uR/hr	Hallway		3.6	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	40% accessible



Summary Report
1304 (901) Avenue B Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen		3.6	uR/hr	Living Room			uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	90% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	80% accessible
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1304 (901) Avenue B Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible, percentage of kitchen grid falls outside of unit
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	survey performed within accessible base cabinet, 60% accessible
H7	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible

CBI Supervisor : Tina Piquet

Signature :



Signoff Notes:

Senior Technician : Daphne Degering

Signature :





Unit Summary :

Completion Date: 8/5/2014 3:39 PM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.7 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I and row 13, and grid D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 124
Average: 3.36 uR/hr
Standard Deviation: 0.26 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room	Installed Stove.	3.6	uR/hr	Kitchen			uR/hr			No	40% accessible
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	95% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
D6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room			uR/hr			No	25% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading .6 meters from floor for stairs.
F7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading .6 meters from floor for stairs.
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility	Installed furnace.	3.6	uR/hr	Hallway			uR/hr			No	75% accessible
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
F11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs.
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs.
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G9	4.0	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	
G10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs.
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs.
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs.
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1304 (901) Avenue B Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility			uR/hr			No	60% accessible
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1304 (901) Avenue B Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/13/2014 2:06 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: No


Unit Notes:
Grid E12 falls outside of unit.

Summary Statistics :

Total # of Readings: 117
Average: 3.34 uR/hr
Standard Deviation: 0.27 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	stair static taken 60" above floor
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken 60" above floor
A7	3.6	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	stair static taken 60" above floor
A8	4.0	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr			No	50% accessible
A10	3.2	uR/hr	Utility	Washing machine within grid.		uR/hr				uR/hr			No	50% accessible
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage		2.4	uR/hr	Stairs		No	stair static taken 60" above floor



Summary Report
1304 (901) Avenue B Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken 44" above floor
B7	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway		2.8	uR/hr	Stairs		No	stair static taken 44" above floor
B8	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		3.2	uR/hr	Storage		No	
C6	3.2	uR/hr	Storage		3.6	uR/hr	Hallway		3.2	uR/hr	Stairs		No	stair static taken 12" above floor
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	stair static taken 12" above floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility	Installed furnace.	3.6	uR/hr	Hallway			uR/hr			No	70% accessible
C10	3.2	uR/hr	Utility	Installed water heater.	3.2	uR/hr	Mech Room			uR/hr			No	70% accessible
C11	3.2	uR/hr	Storage		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1304 (901) Avenue B Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	60% accessible
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	35% accessible
D11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
D12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.6	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	30% accessible
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
E8	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	35% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1304 (901) Avenue B Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	40% accessible, installed stove in kitchen section
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	60% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, survey performed in accessible base cabinet



Summary Report
1304 (901) Avenue B Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, survey performed in accessible base cabinet
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/13/2014 2:41 PM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7B
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.7 W 7.8
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 128
Average: 3.04 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Kitchen	Installed base cabinets.	2.8	uR/hr	Living Room			uR/hr			No	60% accessible
A6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Kitchen	Installed Stove.	2.8	uR/hr	Living Room			uR/hr			No	60% accessible
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1304 (901) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
C6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Trash		2.8	uR/hr	Dining Room			uR/hr			No	moved installed refrigerator to survey grid
C12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		No	
D6	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	
D7	2.8	uR/hr	Kitchen		2.8	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1304 (901) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway		3.2	uR/hr	Mech Room	Installed furnace.		uR/hr			No	60% accessible
E10	2.8	uR/hr	Mech Room	Installed furnace.		uR/hr				uR/hr			No	40% accessible
E11	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
F6	2.8	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F7	3.2	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F8	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	



Summary Report
1304 (901) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F9	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Bathroom		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible
F11	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G7	3.2	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	static taken by toilet
G9	3.2	uR/hr	Bathroom		3.2	uR/hr	Bathroom			uR/hr			No	
G10	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface, 80% accessible
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Static taken on stairs 56" from floor surface, 80% accessible
H7	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface, 80% accessible
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken by toilet, 80% accessible
H9	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	80% accessible, grid scanned inside bath tub
H10	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible, grid scanned inside bath tub
H11	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible, no washer in grid
H12	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, moved installed dryer to survey grid



Summary Report
1304 (901) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1304 (901) Avenue B Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan


CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/13/2014 2:15 PM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Unit is ADA modified. Bathroom and utility room combined into a bathroom. Grid E12 is outside unit interior boundary.

Summary Statistics :

Total # of Readings: 109
Average: 3.43 uR/hr
Standard Deviation: 0.23 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	reading 1.8 meters from floor for stairs
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	surveyed in bathtub.
A10	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	surveyed in bathtub.
A11	3.2	uR/hr	Utility			uR/hr				uR/hr			No	moved washer to survey grid.
A12	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible-no installed dryer
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
B7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
B8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room		3.6	uR/hr	Hallway		No	
C6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs		3.6	uR/hr	Hallway		No	reading .6 meters from floor for stairs
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	reading .6 meters from floor for stairs
C8	3.2	uR/hr	Hallway		3.6	uR/hr	Bathroom			uR/hr			No	
C9	3.6	uR/hr	Bathroom	Installed furnace.	3.6	uR/hr	Hallway			uR/hr			No	75% accessible
C10	3.6	uR/hr	Bathroom		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible
C11	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1304 (901) Avenue B Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible
D11	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	15% accessible
D12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1304 (901) Avenue B Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr			No	95% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1304 (901) Avenue B Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible-installed dishwasher
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible-installed dishwasher
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Summary Report
1305 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/7/2014 1:20 PM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.9 W 7.7
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Grids in column I, row 13 and grid D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 127
Average: 3.05 uR/hr
Standard Deviation: 0.23 uR/hr
Minimum: 2.40 uR/hr
Maximum: 3.60 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
A6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Living Room	Installed Stove.	3.2	uR/hr	Kitchen			uR/hr			No	60% accessible
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



**Summary Report
1305 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Trash		2.8	uR/hr	Dining Room			uR/hr			No	
C12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen		2.8	uR/hr	Hallway		No	
D6	3.2	uR/hr	Kitchen		2.8	uR/hr	Hallway			uR/hr			No	moved installed refrigerator to survey grid.
D7	3.2	uR/hr	Kitchen		2.8	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	



**Summary Report
1305 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Mech Room	Installed furnace.	3.2	uR/hr	Hallway			uR/hr			No	60% accessible
E10	2.8	uR/hr	Mech Room	Installed water heater.	2.8	uR/hr	Hallway			uR/hr			No	60% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	static taken on stairs 16" from floor surface
F8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	



Summary Report
1305 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
G6	2.8	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	static taken on stairs 40" from floor surface
G8	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Utility		3.2	uR/hr	Bathroom			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1305 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface, 70% accessible
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken on stairs 56" from floor surface, 70% accessible
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken on stairs 56" from floor surface, 70% accessible
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	moved installed washer to survey grid, 70% accessible
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	moved installed washer to survey grid, 70% accessible
H11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan



Summary Report
1305 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1305 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes	
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan	
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan	



CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized, starting with a small 'N' and ending with a long, sweeping horizontal stroke.

Signature :

A handwritten signature in black ink on a light blue background. The signature is written in a cursive style, with the first name 'Ricky' and the last name 'Laguna' clearly visible.

Signoff Notes:



Summary Report
1305 Gateview Avenue Unit B

Unit Summary :

Completion Date: 8/7/2014 12:40 PM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.7 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids D12 and E12 are outside unit interior boundary.

Summary Statistics :

Total # of Readings: 109
Average: 3.46 uR/hr
Standard Deviation: 0.23 uR/hr
Minimum: 2.80 uR/hr
Maximum: 3.60 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	reading 1.8 meters from floor for stairs
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	moved washer to survey grid
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	moved dryer to survey grid
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room			uR/hr			No	
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	



Summary Report
1305 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.2	uR/hr	Living Room		3.6	uR/hr	Hallway		No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.2	uR/hr	Stairs		No	reading .6 meters from floor for stairs
C7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading .6 meters from floor for stairs
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway	Installed furnace.	3.6	uR/hr	Utility			uR/hr			No	75% accessible
C10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
D1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	



**Summary Report
1305 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
D10	3.2	uR/hr	Hallway		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
D11	3.2	uR/hr	Mech Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved freezer to survey grid.
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1305 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Kitchen	Installed Stove.	3.6	uR/hr	Living Room			uR/hr			No	70% accessible
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	moved refrigerator to survey grid
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	95% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible-installed dishwasher
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible-installed dishwasher
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :

Signature :

Signoff Notes:



Summary Report
1305 Gateview Avenue Unit C

Unit Summary :

Completion Date: 7/1/2014 12:28 PM
Instrument: 193-6
Serial #: 309136
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: No
Tenant Present: No

Unit Notes:


The majority of major appliances were removed save for the dishwasher unit in the kitchen.

Summary Statistics :

Total # of Readings: 88
Average: 2.89 uR/hr
Standard Deviation: 0.26 uR/hr
Minimum: 2.40 uR/hr
Maximum: 3.20 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
B2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		2.8	uR/hr	Living Room			uR/hr			No	
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1305 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Dining Room		2.8	uR/hr	Trash			uR/hr			No	
C12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
D2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	80% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	No	
D6	2.8	uR/hr	Kitchen		2.8	uR/hr	Hallway			uR/hr			No	
D7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.



Summary Report
1305 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.4	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	55% accessible. Static in mech room taken .06 meters from ground level.
E10	2.8	uR/hr	Mech Room	Installed furnace.	2.4	uR/hr	Hallway		2.4	uR/hr	Mech Room	Installed furnace.	No	55% accessible. Static in mech room taken .06 meters from ground level.
E11	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	30% accessible in mech room.
E12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	45% accessible
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
F6	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Static taken 0.5 meters above ground level.



Summary Report
1305 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F8	2.8	uR/hr	Hallway		3.2	uR/hr	Utility			uR/hr			No	
F9	3.2	uR/hr	Utility		2.4	uR/hr	Mech Room	Installed water heater.		uR/hr			No	30% accessible. Static in mech room taken .06 meters from ground level.
F10	2.4	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	30% accessible in mech room.
F11	2.4	uR/hr	Storage		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	30% accessible in mech room.
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
G6	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Static taken 1.1 meters above ground level.
G8	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	Toilet removed from bathroom.
G9	2.8	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	Toilet removed from bathroom.
G10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
G11	2.4	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	Static on stairs taken 1.5 meters above ground level. 60% accessible
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Static taken 1.5 meters above ground level. 60% accessible
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Static taken 1.5 meters above ground level. 60% accessible
H8	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Toilet removed from bathroom. 60% accessible
H9	2.8	uR/hr	Bathroom	Percentage of grid falls outside of unit.	2.8	uR/hr	Utility			uR/hr			No	Toilet removed from bathroom. 60% accessible
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H11	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :

A handwritten signature in black ink on a light blue background. The signature appears to be "Adam Hickok" written in a cursive, stylized font.

Signature :

A handwritten signature in black ink on a light blue background. The signature appears to be "P. Perez" written in a cursive, stylized font.

Signoff Notes:



Summary Report
1305 Gateview Avenue Unit D

Unit Summary :

Completion Date: 8/7/2014 1:49 PM
Instrument: 193-6
Serial #: 309119
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.7
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:

D12 and E12 fall outside unit interior floor plan.

Summary Statistics :

Total # of Readings: 114
Average: 3.00 uR/hr
Standard Deviation: 0.30 uR/hr
Minimum: 2.00 uR/hr
Maximum: 3.60 uR/hr
Median: 2.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	Stair static taken at 1.5 meters above ground floor
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.4 meters above ground floor
A7	2.0	uR/hr	Stairs		3.2	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr			No	Stair static taken at .4 meters above ground floor
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	2.4	uR/hr	Utility	Washing machine within grid.	3.6	uR/hr	Bathroom			uR/hr			No	50% accessible, installed washer moved for survey
A10	2.8	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	30% accessible, installed dryer moved for survey
A11	2.4	uR/hr	Storage	Installed refrigerator.		uR/hr				uR/hr			No	80% accessible, installed refrigerator moved for survey
A12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stair static taken at 0.8 meters above ground floor
B7	2.8	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	Stair static taken at 0.8 meters above ground floor
B8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	2.8	uR/hr	Utility		3.2	uR/hr	Hallway		2.8	uR/hr	Bathroom		No	
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.4	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Storage		2.8	uR/hr	Hallway		3.2	uR/hr	Living Room		No	
C6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stair static taken at 0.4 meters above ground floor
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	Stair static taken at 0.4 meters above ground floor
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	
C10	2.8	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	50% accessible



**Summary Report
1305 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C11	2.4	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	95% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	80% accessible
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible, mech room installed furnace
D11	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	



**Summary Report
1305 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E6	3.2	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	70% accessible
E7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
E8	2.8	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.2	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.4	uR/hr	Dining Room			uR/hr			No	70% accessible
E11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room	Grid partially contained within wall construction.		uR/hr			No	60% accessible
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	90% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	30% accessible
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	70% accessible
H6	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible. survey performed inside base cabinets.



Summary Report
1305 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H7	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, installed dishwasher
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/7/2014 1:57 PM

Instrument: 193-6

Serial #: 309127

Layout: Floor Plan 7B

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.5

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids in column I, row 13 and grid D11 are outside of floor plan. Bed in living room moved for survey.

Summary Statistics :

Total # of Readings: 128

Average: 3.48 uR/hr

Standard Deviation: 0.29 uR/hr

Minimum: 2.80 uR/hr


Maximum: 4.40 uR/hr

Median: 3.20 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	4.0	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	Kitchen reading taken 4" from floor inside base cabinet.
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	Kitchen reading taken 4" from floor inside base cabinet.
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	40% accessible.
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	4.0	uR/hr	Living Room		3.6	uR/hr	Kitchen	Installed Stove.		uR/hr			No	30% accessible. Kitchen reading taken 4" from floor inside base cabinet.
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1306 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	4.0	uR/hr	Living Room		4.0	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	60% accessible.
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



**Summary Report
1306 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	4.0	uR/hr	Living Room		3.6	uR/hr	Hallway		3.6	uR/hr	Kitchen		No	
D6	3.6	uR/hr	Kitchen		3.6	uR/hr	Hallway			uR/hr			No	
D7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	Kitchen reading taken 4" from floor inside base cabinet.
D8	3.6	uR/hr	Stairs			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible.
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	60% accessible. Mech room reading inaccessible due to installed furnace.
E10	3.2	uR/hr	Mech Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Hallway			uR/hr			No	30% accessible. Partial grid due to installed water heater.



Summary Report
1306 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.6	uR/hr	Stairs			uR/hr			No	Stairs reading taken 12" from floor.
F7	3.6	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	Stairs reading taken 12" from floor.
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	80% accessible. Mech room reading inaccessible due to installed furnace
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible.
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1306 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage		2.8	uR/hr	Stairs		No	Bed in living room (moved for survey). Stairs reading taken 60" from floor.
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 60" from floor.
G7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 60" from floor.
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.



Summary Report
1306 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible. Bed in living room (moved for survey).
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	50% accessible. Bed in living room (moved for survey). Stairs reading taken 60" from floor.
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible. Stairs reading taken 60" from floor.
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	50% accessible. Stairs reading taken 60" from floor.
H8	4.4	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H9	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.	4.0	uR/hr	Bathroom			uR/hr			No	40% accessible. Partial grid due to installed dryer.
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible. Partial grid due to installed dryer.
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible.



Summary Report
1306 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1306 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :

Signature :

Signoff Notes:



Summary Report
1306 Gateview Avenue Unit B

Unit Summary :

Completion Date: 7/17/2014 3:30 PM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.8
Unit Furnished: Yes
Tenant Present: Yes


Unit Notes:
Grid D12 is outside of floor plan.

Summary Statistics :

Total # of Readings: 108
Average: 3.48 uR/hr
Standard Deviation: 0.22 uR/hr
Minimum: 2.80 uR/hr
Maximum: 3.60 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		3.6	uR/hr	Living Room			uR/hr			No	reading 1.8 meters from floor for stairs
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A8	3.2	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A9	3.2	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	
A10	3.6	uR/hr	Utility	Washing machine within grid.		uR/hr				uR/hr			No	20% accessible
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room			uR/hr			No	
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs



Summary Report
1306 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Utility		No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room		3.6	uR/hr	Hallway		No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.2	uR/hr	Stairs		No	reading .6 meters from floor for stairs
C7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading .6 meters from floor for stairs
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway		3.2	uR/hr	Utility			uR/hr			No	75% accessible-installed furnace
C10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	75% accessible
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1306 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible-installed furnace
D10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible-installed furnace and water heater
D11	3.2	uR/hr	Utility			uR/hr				uR/hr			No	10% accessible
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1306 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Kitchen		3.6	uR/hr	Living Room			uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Kitchen	Installed Stove.	3.6	uR/hr	Living Room			uR/hr			No	70% accessible
G6	3.6	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	70% accessible
G7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



**Summary Report
1306 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G8	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H5	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.6	uR/hr	Living Room			uR/hr			No	80% accessible
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible-installed dishwasher
H8	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :

Signature :

Signoff Notes:



Summary Report
1306 Gateview Avenue Unit C

Unit Summary :

Completion Date: 8/7/2014 1:56 PM
Instrument: 193-6
Serial #: 309136
Layout: Floor Plan 7B
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Bed in living room - Grids A3-A5, B3-B5, C3-5.
Grids in column I, row 13 and grid D11 are
outside of floor plan.

Summary Statistics :

Total # of Readings: 128
Average: 2.73 uR/hr
Standard Deviation: 0.23 uR/hr
Minimum: 2.00 uR/hr
Maximum: 3.60 uR/hr
Median: 2.40 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	70% accessible, survey inside installed cabinets
A8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen	Installed Stove.		uR/hr			No	20% accessible, survey inside installed cabinets
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1306 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.4	uR/hr	Living Room		2.8	uR/hr	Kitchen			uR/hr			No	
C6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	refrigerator moved for survey
C11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Trash			uR/hr			No	70% accessible
C12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1306 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		2.4	uR/hr	Kitchen	Survey performed within accessible base cabinet.	No	
D6	2.8	uR/hr	Kitchen		2.4	uR/hr	Hallway			uR/hr			No	refrigerator moved for survey
D7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.4	uR/hr	Hallway			uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.4	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway			uR/hr			No	
E6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	30% accessible
E10	2.4	uR/hr	Mech Room	Installed water heater.		uR/hr				uR/hr			No	30% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.4	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
F6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs		2.8	uR/hr	Hallway		No	Stair static taken at 0.7 meters above ground level
F7	2.4	uR/hr	Stairs		2.8	uR/hr	Hallway			uR/hr			No	Stair static taken at 0.7 meters above ground level
F8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Utility		2.8	uR/hr	Hallway			uR/hr			No	
F10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Living Room		2.4	uR/hr	Storage			uR/hr			No	
G6	2.8	uR/hr	Storage		2.0	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.5 meters above ground level
G7	2.4	uR/hr	Stairs		2.8	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.3 meters above ground level
G8	2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
G9	2.8	uR/hr	Utility	Washing machine within grid.	2.8	uR/hr	Bathroom			uR/hr			No	50% accessible, washer partially moved for survey
G10	2.8	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	60% accessible, dryer partially moved for survey
G11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1306 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H5	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H6	2.0	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground level
H7	2.0	uR/hr	Stairs	Percentage of grid falls outside of unit.	2.8	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.5 meters above ground level, 60% accessible
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	60% accessible
H10	2.4	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan




Summary Report
1306 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :



Signature :



Signoff Notes:



Summary Report
1306 Gateview Avenue Unit D

Unit Summary :

Completion Date: 8/7/2014 3:39 PM

Instrument: 193-6

Serial #: 309110

Layout: Floor Plan 7

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

D12 and E12 grids are outside unit interior boundary.

Summary Statistics :

Total # of Readings: 113

Average: 3.42 uR/hr

Standard Deviation: 0.25 uR/hr

Minimum: 2.80 uR/hr


Maximum: 4.00 uR/hr

Median: 3.20 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	reading 1.8 meters from floor for stairs
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	moved washer to survey grid.
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	moved dryer to survey grid
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room			uR/hr			No	
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	



Summary Report
1306 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Bathroom		3.6	uR/hr	Utility		3.6	uR/hr	Hallway		No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.2	uR/hr	Living Room		3.6	uR/hr	Hallway		No	
C6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs		3.6	uR/hr	Hallway		No	reading .6 meters from floor for stairs
C7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading .6 meters from floor for stairs
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Utility	Installed furnace.	3.2	uR/hr	Hallway			uR/hr			No	75% accessible
C10	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	75% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	75% accessible. Partial grid in mech room inaccessible due to installed furnace
D10	3.2	uR/hr	Hallway		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible
D11	3.2	uR/hr	Mech Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid.
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	70% accessible



Summary Report
1306 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Kitchen	Installed Stove.	3.6	uR/hr	Living Room			uR/hr			No	80% accessible
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	95% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Kitchen	Installed Stove.	3.6	uR/hr	Living Room			uR/hr			No	75% accessible
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.6	uR/hr	Living Room			uR/hr			No	60% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible-installed dishwasher
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible-installed dishwasher
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1306 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :

Signature :

Signoff Notes:



Summary Report
1306 Gateview Avenue Unit E

Unit Summary :

Completion Date: 8/15/2014 3:33 PM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.7
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Unit ADA compliant. Living room divided into two rooms. Utility room combined into bathroom. Storage is Utility Room with washer/dryer. Grids in column I, row 13, and D11 are outside of survey unit.

Summary Statistics :

Total # of Readings: 122
Average: 3.41 uR/hr
Standard Deviation: 0.28 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible



**Summary Report
1306 Gateview Avenue Unit E**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
D6	3.2	uR/hr	Kitchen	Installed refrigerator.	3.2	uR/hr	Hallway			uR/hr			No	50% accessible
D7	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible



Summary Report
1306 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	70% accessible
E10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E11	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible installed hot water heater
E12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken 24" above floor



Summary Report
1306 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken 24" above floor
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Hallway		3.2	uR/hr	Bathroom			uR/hr			No	50% accessible Partial grid in mech room inaccessible due to installed furnace
F10	3.6	uR/hr	Bathroom	Installed water heater.		uR/hr				uR/hr			No	60% accessible
F11	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken 44" above floor
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken 44" above floor
G8	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
G9	3.6	uR/hr	Bathroom		3.2	uR/hr	Bathroom			uR/hr			No	
G10	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Utility			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible stair static taken 60" above floor
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible stair static taken 60" above floor
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	70% accessible
H10	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1306 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible installed washing machine
H12	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, installed dryer
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan



Summary Report
1306 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :

Signature :

Signoff Notes:



Summary Report
1306 Gateview Avenue Unit F

Unit Summary :

Completion Date: 7/1/2014 4:00 PM

Instrument: 193-6

Serial #: 309136

Layout: Floor Plan 7

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: No

Tenant Present: No

Unit Notes:

Unit modified: bath tub within A9&A10; living room partitioned with a 1.4 m framed doorway between cells D2&E2, D3&E3, D4&E4, D5&E5. After data review, 2nd bkgd taken at standard location: 2.8uR/hr

Summary Statistics :

Total # of Readings: 86

Average: 2.75 uR/hr

Standard Deviation: 0.21 uR/hr

Minimum: 2.40 uR/hr


Maximum: 3.60 uR/hr

Median: 2.80 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Static taken at 1.5 meters from ground level.
A7	2.4	uR/hr	Stairs		2.8	uR/hr	Bathroom			uR/hr			No	Static taken at 1.5 meters from ground level.
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Bathroom		2.8	uR/hr	Bathroom			uR/hr			No	
A10	2.4	uR/hr	Bathroom			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	
B6	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B7	2.4	uR/hr	Stairs		2.8	uR/hr	Bathroom			uR/hr			No	Static taken at 1.1 meters from ground level.
B8	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	
B9	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	



Summary Report
1306 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Storage		2.8	uR/hr	Hallway		2.8	uR/hr	Living Room		No	
C6	2.8	uR/hr	Storage		2.8	uR/hr	Hallway		2.8	uR/hr	Stairs		No	Static taken at 0.5 meters from ground level.
C7	2.8	uR/hr	Stairs		2.8	uR/hr	Hallway		2.8	uR/hr	Bathroom		No	Static taken at 0.5 meters from ground level.
C8	2.8	uR/hr	Bathroom		2.8	uR/hr	Closet			uR/hr			No	
C9	2.8	uR/hr	Utility		2.4	uR/hr	Mech Room	Percentage of grid falls outside of unit.		uR/hr			No	55% accessible. Static taken at 0.6m
C10	2.8	uR/hr	Bathroom		2.4	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible.
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1306 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D9	2.4	uR/hr	Mech Room	Installed furnace.		uR/hr				uR/hr			No	Static taken at 0.6m. 55% accessible.
D10	2.4	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
E2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E6	2.4	uR/hr	Kitchen			uR/hr				uR/hr			No	Refrigerator pulled out for survey.
E7	2.4	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	2.4	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
F6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1306 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.4	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.4	uR/hr	Trash		2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr			No	40% accessible
F12	2.4	uR/hr	Trash			uR/hr				uR/hr			No	
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	20% accessible
G6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible

Summary Report
1306 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible
H6	2.4	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	60% accessible
H7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	20% accessible
H8	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :



Signature :



Signoff Notes:



Summary Report
1307 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/7/2014 3:48 PM

Instrument: 193-6

Serial #: 293633

Layout: Floor Plan 7B

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.7

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 122

Average: 3.31 uR/hr

Standard Deviation: 0.23 uR/hr

Minimum: 2.80 uR/hr


Maximum: 4.00 uR/hr

Median: 3.00 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room	Installed base cabinets.		uR/hr				uR/hr			No	50% accessible
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	30% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	second installed refrigerator moved for survey
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	second installed refrigerator moved for survey
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	90% accessible
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
D6	3.2	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	80% accessible
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	60% accessible
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible installed water heater



Summary Report
1307 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible installed hot water heater
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	stair static taken at 12" above floor
F7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken at 12" above floor
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Hallway		3.6	uR/hr	Utility			uR/hr			No	
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible
F11	3.6	uR/hr	Storage		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken at 44" above floor
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken at 44" above floor
G8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
G9	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Utility		No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1307 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible, stair static taken at 60" above floor
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible, stair static taken at 60" above floor
H8	3.2	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	70% accessible, remainder of grid falls outside
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr			No	50% accessible
H10	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	installed washing machine 40% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1307 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1307 Gateview Avenue Unit B

Unit Summary :

Completion Date: 7/2/2014 4:00 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 9.4 W 7.6
Unit Furnished: No
Tenant Present: No


Unit Notes:

Summary Statistics :

Total # of Readings: 106
Average: 3.32 uR/hr
Standard Deviation: 0.24 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.40 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	static reading taken on landing at 56 inches
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	static reading taken on landing at 56 inches
A7	3.6	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	static reading taken on landing at 56 inches
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Utility		4.4	uR/hr	Bathroom			uR/hr			No	Elevated measurements due to NORM in toilet bowl and tile materials.
A10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Utility		3.6	uR/hr	Storage			uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	



Summary Report
1307 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static reading taken on 5th step at 40 inches
B7	3.6	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	static reading taken on 5th step at 40 inches
B8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
C6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	static reading taken on first riser at 8 inches
C7	3.2	uR/hr	Hallway		3.2	uR/hr	Stairs			uR/hr			No	static reading taken on first riser at 8 inches
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Utility	Installed furnace.		uR/hr				uR/hr			No	20% accessible
C11	3.6	uR/hr	Storage		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	35% accessible
D10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	35% accessible
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	85% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E11	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	85% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	20% accessible
F12	3.2	uR/hr	Trash			uR/hr				uR/hr			No	
F13	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	85% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1307 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H6	3.6	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	60% accessible
H7	3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	60% accessible
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible


CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1307 Gateview Avenue Unit C

Unit Summary :


Completion Date: 7/2/2014 4:32 PM
Instrument: 193-6
Serial #: 309136
Layout: Floor Plan 7B
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes
Unit Notes:

Summary Statistics :

Total # of Readings: 104
Average: 2.84 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible.
A8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen	Installed Stove.		uR/hr			No	70% accessible.
B6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen			uR/hr			No	
C6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	No	
D6	2.8	uR/hr	Kitchen		2.4	uR/hr	Hallway			uR/hr			No	
D7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Living Room		2.8	uR/hr	Hallway			uR/hr			No	
E6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Mech Room	Installed furnace.		uR/hr				uR/hr			No	25% accessible in Mech Room. Static taken 0.5 meters from ground level.
E10	2.8	uR/hr	Mech Room	Installed furnace.		uR/hr				uR/hr			No	25% accessible in Mech Room. Static taken 0.5 meters from ground level.
E11	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
E12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
F6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F7	2.4	uR/hr	Stairs		2.8	uR/hr	Hallway			uR/hr			No	Static taken at 0.6 meters from ground level.
F8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Mech Room	Installed furnace.		uR/hr				uR/hr			No	25% accessible in Mech Room. Static taken 0.5 meters from ground level.
F10	2.8	uR/hr	Mech Room	Installed furnace.	2.8	uR/hr	Utility			uR/hr			No	25% accessible in Mech Room. Static taken 0.5 meters from ground level.
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
G6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	
G7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Static taken at 0.6 meters from ground level.
G8	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
G10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Static taken at 1.4 meters from ground level. 60% accessible.
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Static taken at 1.4 meters from ground level. 60% accessible.
H8	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	4.0	uR/hr	Bathroom	Elevated measurements due to NORM in toilet bowl a	4.0	uR/hr	Bathroom		2.8	uR/hr	Utility		No	60% accessible. Elevated measurements due to NORM in toilet bowl and tile materials.
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. No washer or dryer in unit.
H11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1307 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.



CBI Supervisor : Adam Hickok

Senior Technician : Mark Cafouras

Signature :

A handwritten signature in black ink on a light blue background. The signature consists of the letters "AH" in a stylized, cursive font.

Signature :

A handwritten signature in black ink on a light blue background. The signature is written in a cursive style and appears to read "Mark Cafouras".

Signoff Notes:



Summary Report
1307 Gateview Avenue Unit D

Unit Summary :

Completion Date: 7/7/2014 2:52 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.7
Unit Furnished: No
Tenant Present: No


Unit Notes:

Summary Statistics :

Total # of Readings: 105
Average: 3.44 uR/hr
Standard Deviation: 0.37 uR/hr
Minimum: 2.80 uR/hr
Maximum: 5.60 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	static reading was taken on stairs at 60 inches from floor
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	static reading was taken on stairs at 60 inches from floor
A7	3.6	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	static reading was taken on stairs at 60 inches from floor
A8	5.6	uR/hr	Bathroom			uR/hr				uR/hr			No	Elevated measurements due to NORM in toilet bowl materials
A9	5.2	uR/hr	Bathroom		4.0	uR/hr	Utility			uR/hr			No	Elevated measurements due to NORM in toilet bowl materials
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Storage		3.6	uR/hr	Utility			uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static reading was taken on stairs at 36 inches from floor
B7	3.6	uR/hr	Hallway		2.8	uR/hr	Stairs			uR/hr			No	static reading was taken on stairs at 36 inches from floor
B8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
C6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	static reading was taken on stairs at 20 inches from floor
C7	3.2	uR/hr	Hallway		3.2	uR/hr	Stairs			uR/hr			No	static reading was taken on stairs at 20 inches from floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C9	3.6	uR/hr	Utility	Installed furnace.		uR/hr				uR/hr			No	10% accessible in mechanical room due to furnace
C10	3.2	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	80% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room			uR/hr			No	20% accessible
D12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	



**Summary Report
1307 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Dining Room		3.2	uR/hr	Hallway			uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	40% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	80% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	70% accessible
H6	3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	70% accessible
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible


CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1307 Gateview Avenue Unit E

Unit Summary :

Completion Date: 7/7/2014 2:48 PM

Instrument: 193-6

Serial #: 309136

Layout: Floor Plan 7B

Background Reading: 2.8 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: No

Tenant Present: No

Unit Notes:

Grids C13, E13 - H13, and I11 - I12 are outside of floor plan.

Summary Statistics :

Total # of Readings: 109

Average: 2.80 uR/hr

Standard Deviation: 0.19 uR/hr

Minimum: 2.00 uR/hr


Maximum: 3.60 uR/hr

Median: 2.40 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	
A6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	30% accessible.
A8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Kitchen	Installed Stove.	2.8	uR/hr	Living Room			uR/hr			No	30% accessible.
B6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	
C6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
C8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room		No	Pulled out refrigerator and surveyed.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway		2.4	uR/hr	Mech Room	Installed furnace.		uR/hr			No	Mech room static taken 0.6 meters from ground level. 40% accessible.
E10	2.8	uR/hr	Hallway		2.4	uR/hr	Mech Room	Installed water heater.		uR/hr			No	50% accessible.
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Living Room		2.8	uR/hr	Storage		2.8	uR/hr	Hallway		No	
F6	2.8	uR/hr	Stairs		2.8	uR/hr	Storage			uR/hr			No	Stairs static taken at 0.5 meters from ground level.
F7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs static taken at 0.5 meters from ground level.
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Utility		2.8	uR/hr	Hallway		2.8	uR/hr	Mech Room	Installed furnace.	No	Mech Room static taken 0.6 meters above ground level. 30% accessible.
F10	2.4	uR/hr	Mech Room	Installed water heater.	2.8	uR/hr	Utility			uR/hr			No	30% accessible.
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.4	uR/hr	Stairs		2.0	uR/hr	Living Room		2.8	uR/hr	Storage		No	Stairs static taken at 1.5 meters from ground level.
G6	2.4	uR/hr	Stairs		2.8	uR/hr	Storage			uR/hr			No	Stairs static taken at 1.5 meters from ground level.
G7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs static taken at 1.1 meters from ground level.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G8	2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
G9	2.8	uR/hr	Utility		2.8	uR/hr	Bathroom			uR/hr			No	No washer or dryer installed.
G10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	No washer or dryer installed.
G11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible. Stairs static taken at 1.5 meters from ground level.
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Stairs static taken at 1.5 meters from ground level.
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Stairs static taken at 1.5 meters from ground level.
H8	2.8	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.



Summary Report
1307 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H9	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	Elevated measurements due to NORM in toilet bowl and tile materials 60% accessible.
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. No washer or dryer installed.
H11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.

CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :



Signature :



Signoff Notes:



Summary Report
1307 Gateview Avenue Unit F

Unit Summary :

Completion Date: 8/7/2014 10:49 AM

Instrument: 193-6

Serial #: 309136

Layout: Floor Plan 7

Background Reading: 2.8 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: No

Unit Notes:

D11-12 are less than 6" wide and surveyed with adjacent grid. E12 is outside of survey unit.

Summary Statistics :

Total # of Readings: 109

Average: 2.79 uR/hr

Standard Deviation: 0.20 uR/hr

Minimum: 2.40 uR/hr

Maximum: 3.60 uR/hr

Median: 2.60 uR/hr

Anomalies: 0

Grid Legend:

-  No anomalous measurements
-  Inaccessible (no measurement collected)
-  Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	Stair static taken at 1.5 meters above ground level
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.5 meters above ground level
A7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.5 meters above ground level
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Utility	Washing machine within grid.	3.6	uR/hr	Bathroom			uR/hr			No	50% accessible, washer moved for survey
A10	2.8	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	70% accessible, dryer moved for survey
A11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	refrigerator moved for survey
A12	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	



Summary Report
1307 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.1 meters above ground level
B7	2.4	uR/hr	Stairs			uR/hr	Hallway			uR/hr			No	Stair static taken at 1.1 meters above ground level
B8	2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
B9	2.8	uR/hr	Utility		2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway		No	
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		No	
C6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs		2.8	uR/hr	Hallway		No	Stair static taken at 0.5 meters above ground level
C7	2.4	uR/hr	Stairs		2.8	uR/hr	Hallway			uR/hr			No	Stair static taken at 0.5 meters above ground level
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	
C10	2.8	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	70% accessible
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
D1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.8	uR/hr	Living Room			uR/hr			No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	70% accessible
D10	2.8	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	20% accessible
E2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	
E6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	refrigerator moved for survey
E7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
E8	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	40% accessible
E11	2.4	uR/hr	Dining Room			uR/hr				uR/hr			No	20% accessible



Summary Report
1307 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	
F6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Trash			uR/hr			No	60% accessible
F12	2.4	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	30% accessible
G6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	



Summary Report
1307 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.4	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H5	2.4	uR/hr	Kitchen	Percentage of grid falls outside of unit.	2.4	uR/hr	Living Room			uR/hr			No	80% accessible, survey inside installed cabinets
H6	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible, survey inside installed cabinets
H7	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible, static taken at 4" due to installed cabinets
H8	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1307 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes	
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible	



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :

A handwritten signature in black ink on a light blue background. The signature appears to be "AH" with a stylized, looped flourish at the end.

Signature :

A handwritten signature in black ink on a light blue background. The signature appears to be "P. Perez" with a stylized, looped flourish at the end.

Signoff Notes:



Summary Report
1308 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/8/2014 10:23 AM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and grid D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 130
Average: 3.41 uR/hr
Standard Deviation: 0.28 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.80 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	installed dishwasher, 40% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B6	3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	installed stove, 90% accessible
B7	3.6	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	70% accessible



Summary Report
1308 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B8	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
C6	3.2	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	90% accessible
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Trash		3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
D6	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	



**Summary Report
1308 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.2	uR/hr	Kitchen	Installed base cabinets.	3.2	uR/hr	Hallway			uR/hr			No	90% accessible
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	60% accessible
E10	3.2	uR/hr	Hallway		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	50% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



**Summary Report
1308 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.6	uR/hr	Stairs			uR/hr			No	static taken on stairs at 12" above ground.
F7	3.6	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	static taken on stairs at 12" above ground.
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Utility		3.6	uR/hr	Hallway	Installed furnace.		uR/hr			No	80% accessible
F10	3.2	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Stairs		4.0	uR/hr	Storage			uR/hr			No	static taken on stairs at 44" above ground.
G7	3.2	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	static taken on stairs at 44" above ground.
G8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
G9	4.0	uR/hr	Bathroom		3.6	uR/hr	Hallway		3.6	uR/hr	Utility	Washing machine within grid.	No	90% accessible



**Summary Report
1308 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	80% accessible
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible, static taken on stairs at 60" above ground.
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, static taken on stairs at 60" above ground.
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	60% accessible, static taken on stairs at 60" above ground.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Survey performed within accessible base cabinet
H9	4.8	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility	Washing machine within grid.		uR/hr			No	50% accessible
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	clothes dryer in grid, 50% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1308 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1308 Gateview Avenue Unit B

Unit Summary :

Completion Date: 8/8/2014 11:06 AM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.5
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Scanned underside immovable fish tank desk with model 19, SN# 267078 with a reading of 4 uR/hr, background was 4 uR/hr at standard location in grid H3. D12 and E12 are outside of floor plan.

Summary Statistics :

Total # of Readings: 118
Average: 3.07 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static taken on stairs 56" from floor surface
A7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	static taken on stairs 56" from floor surface
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	static taken by toilet
A9	2.8	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	moved washer to survey grid
A10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	moved dryer to survey grid
A11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
B7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	static taken on stairs 40" from floor surface



Summary Report
1308 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B8	3.2	uR/hr	Hallway		3.2	uR/hr	Bathroom			uR/hr			No	
B9	2.8	uR/hr	Utility		3.2	uR/hr	Hallway		3.2	uR/hr	Bathroom		No	
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
C6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs		3.2	uR/hr	Hallway		No	static taken on stairs 16" from floor surface
C7	3.2	uR/hr	Hallway		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Hallway		3.2	uR/hr	Utility			uR/hr			No	
C10	2.8	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	



**Summary Report
1308 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway		3.2	uR/hr	Mech Room			uR/hr			No	
D10	3.2	uR/hr	Hallway		3.2	uR/hr	Mech Room	Installed furnace.		uR/hr			No	70% accessible
D11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
E6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	moved installed refrigerator to survey grid
E7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	2.8	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



**Summary Report
1308 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Kitchen		3.2	uR/hr	Dining Room			uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Trash		3.2	uR/hr	Dining Room			uR/hr			No	
F12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1308 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible, scanned underside immovable fish tank desk with model 19, SN# 267078 with a reading of 4 uR/hr, background was 4 uR/hr at standard location in grid.
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	70% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible




CBI Supervisor : Daniel Fielding

Senior Technician : Ricky Laguna

Signature :



Signature :



Signoff Notes:



Summary Report
1308 Gateview Avenue Unit C

Unit Summary :

Completion Date: 8/8/2014 10:25 AM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.8
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 125
Average: 3.29 uR/hr
Standard Deviation: 0.22 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	moved 2nd refrigerator to survey grid.
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	60% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1308 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	moved 3rd refrigerator to survey grid.
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	95% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D6	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	moved refrigerator to survey grid.



**Summary Report
1308 Gateview Avenue Unit C**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	20% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1308 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	reading .6 meters from floor for stairs
F7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading .6 meters from floor for stairs
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Hallway	Installed furnace.	3.2	uR/hr	Utility			uR/hr			No	75% accessible
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	



Summary Report
1308 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G9	3.6	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	
G10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H5	3.2	uR/hr	Living Room	Installed Stove.	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	80% accessible. reading 1.8 meters from floor for stairs
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible. reading 1.8 meters from floor for stairs
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible. reading 1.8 meters from floor for stairs
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1308 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility			uR/hr			No	80% accessible. moved washer to survey grid.
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible. moved dyer to survey grid
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1308 Gateview Avenue Unit C


Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan




CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Summary Report
1308 Gateview Avenue Unit D

Unit Summary :

Completion Date: 8/8/2014 10:14 AM
Instrument: 193-6
Serial #: 309119
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.9 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids D11, D12 and E12 fall outside unit.

Summary Statistics :

Total # of Readings: 118
Average: 3.04 uR/hr
Standard Deviation: 0.24 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.4	uR/hr	Stairs			uR/hr			No	stair static taken 44" above floor
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken 44" above floor
A7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr			No	stair static taken 44" above floor
A8	3.2	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.2	uR/hr	Utility	Washing machine within grid.		uR/hr			No	80% accessible
A10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	80% accessible
A11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	



**Summary Report
1308 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken 36" above floor
B7	2.8	uR/hr	Stairs		2.8	uR/hr	Hallway		3.2	uR/hr	Bathroom		No	stair static taken 36" above floor
B8	2.8	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Utility		No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		2.8	uR/hr	Storage		2.8	uR/hr	Hallway		No	
C6	3.2	uR/hr	Storage		3.2	uR/hr	Hallway		2.8	uR/hr	Stairs		No	stair static taken 20" above floor
C7	3.2	uR/hr	Hallway		2.8	uR/hr	Stairs			uR/hr			No	stair static taken 20" above floor
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Hallway		2.8	uR/hr	Utility			uR/hr			No	
C10	2.8	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
C11	3.2	uR/hr	Storage		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	95% accessible
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1308 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		2.8	uR/hr	Hallway			uR/hr			No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	80% accessible
D10	2.8	uR/hr	Hallway		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	50% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.2	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	40% accessible
E7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	



Summary Report
1308 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E8	2.8	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	2.8	uR/hr	Dining Room		3.2	uR/hr	Hallway			uR/hr			No	
E10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Hallway			uR/hr			No	35% accessible
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Trash			uR/hr			No	90% accessible
F12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1308 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	50% accessible. Partial grid in kitchen inaccessible due to installed stove
G6	3.2	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	90% accessible
G7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	60% accessible
H6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid, remainder of grid falls outside 60% accessible



Summary Report
1308 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid, remainder of grid falls outside 30% accessible
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :

A handwritten signature in black ink on a light blue background. The signature appears to be "S Phelps" written in a cursive, flowing style.

Signature :

A handwritten signature in black ink on a light blue background. The signature appears to be "ER" written in a stylized, cursive manner.

Signoff Notes:



Summary Report
1308 Gateview Avenue Unit E

Unit Summary :

Completion Date: 8/8/2014 11:53 AM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and grid D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 129
Average: 3.33 uR/hr
Standard Deviation: 0.29 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.40 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	Kitchen reading 12" from floor inside base cabinet.
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	50% accessible.
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	30% accessible. Kitchen reading 8" from floor inside base cabinet.
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1308 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room			uR/hr			No	60% accessible.
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway		No	



Summary Report
1308 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D6	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	20% accessible. Mech room reading inaccessible due to installed furnace.
E10	2.8	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr			No	40% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible.