



Summary Report
1308 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	Stairs reading taken 12" from floor.
F7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	Stairs reading taken 12" from floor.
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	80% accessible. Partial grid in mech room inaccessible due to installed furnace
F10	3.2	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	50% accessible.
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1308 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage		2.8	uR/hr	Stairs		No	Stairs reading taken 44" from floor.
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 44" from floor.
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 44" from floor.
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Utility		3.2	uR/hr	Bathroom			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible. Stairs reading taken 44" from floor.



Summary Report
1308 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Stairs reading taken 44" from floor.
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	60% accessible. Stairs reading taken 44" from floor.
H8	4.4	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.	4.4	uR/hr	Bathroom			uR/hr			No	50% accessible. Partial grid due to installed washer.
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible. Partial grid due to installed dryer.
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. Partial grid due to non-movable furniture.
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. Partial grid due to non-movable furniture.
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1308 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1308 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Summary Report
1308 Gateview Avenue Unit F

Unit Summary :

Completion Date: 8/8/2014 10:54 AM

Instrument: 193-6

Serial #: 309136

Layout: Floor Plan 7

Background Reading: 2.8 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids D11, D12, E11 and E12 are outside of survey unit.

Summary Statistics :

Total # of Readings: 112

Average: 2.71 uR/hr

Standard Deviation: 0.31 uR/hr

Minimum: 2.00 uR/hr

Maximum: 4.40 uR/hr

Median: 2.40 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.0	uR/hr	Stairs		2.4	uR/hr	Living Room			uR/hr			No	stair static taken at 1.5 meters above ground floor
A6	2.0	uR/hr	Stairs			uR/hr				uR/hr			No	stair static taken at 1.5 meters above ground floor
A7	2.0	uR/hr	Stairs		2.4	uR/hr	Bathroom			uR/hr			No	stair static taken at 1.5 meters above ground floor
A8	4.4	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Utility		4.4	uR/hr	Bathroom			uR/hr			No	dryer moved for survey
A10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	washer moved for survey
A11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	
B6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	stair static taken at 1.1 meters above ground floor



**Summary Report
1308 Gateview Avenue Unit F**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.4	uR/hr	Stairs		2.4	uR/hr	Bathroom			uR/hr			No	stair static taken at 1.1 meters above ground floor
B8	2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
B9	2.8	uR/hr	Utility		2.4	uR/hr	Bathroom		2.8	uR/hr	Hallway		No	
B10	2.4	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		No	
C6	2.8	uR/hr	Storage		2.8	uR/hr	Hallway		2.8	uR/hr	Stairs		No	stair static taken at 0.5 meters above ground floor
C7	2.4	uR/hr	Stairs		2.4	uR/hr	Hallway			uR/hr			No	stair static taken at 0.5 meters above ground floor
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	2.4	uR/hr	Utility	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	50% accessible
C10	2.4	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	60% accessible
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	2.4	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1308 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	95% accessible
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.4	uR/hr	Living Room			uR/hr			No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.4	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.4	uR/hr	Living Room			uR/hr			No	
E6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	refrigerator moved for survey



Summary Report
1308 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.4	uR/hr	Hallway			uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	2.4	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	
F6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.4	uR/hr	Trash	Percentage of grid falls outside of unit.	2.4	uR/hr	Dining Room			uR/hr			No	60% accessible



**Summary Report
1308 Gateview Avenue Unit F**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F12	2.4	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	2.4	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.4	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.4	uR/hr	Kitchen	Installed Stove.	2.8	uR/hr	Living Room			uR/hr			No	50% accessible
G6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible, unmovable weight set
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.	2.4	uR/hr	Living Room			uR/hr			No	60% accessible
H6	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, survey inside installed cabinet



Summary Report
1308 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H7	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, installed dishwasher, survey inside installed cabinets
H8	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :

A handwritten signature in black ink on a light blue background. The signature consists of a large, stylized 'A' followed by a vertical line and a horizontal crossbar, resembling the letters 'AH'.

Signature :

A handwritten signature in black ink on a light blue background. The signature consists of a stylized 'P' followed by a vertical line and a horizontal crossbar, resembling the letters 'PR'.

Signoff Notes:



Summary Report
1309 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/8/2014 1:00 PM

Instrument: 193-6

Serial #: 293633

Layout: Floor Plan 7B

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.7

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Two beds in living room moved for survey. Grids in column I, row 13 and grid D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 130

Average: 3.42 uR/hr

Standard Deviation: 0.30 uR/hr

Minimum: 2.80 uR/hr


Maximum: 4.80 uR/hr

Median: 3.20 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	
A6	3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	70% accessible
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	30% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B6	3.6	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	80% accessible
B7	3.6	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	70% accessible
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Kitchen		3.6	uR/hr	Living Room			uR/hr			No	
C6	3.6	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	80% accessible
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	60% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway		No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D6	3.6	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	installed refrigerator moved for survey
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	40% accessible
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	30% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



Summary Report
1309 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	Bed in grid moved for survey
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	Bed in grid moved for survey
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	Bed in grid moved for survey
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	Bed in grid moved for survey
F6	3.2	uR/hr	Stairs		3.6	uR/hr	Storage		3.6	uR/hr	Hallway		No	static taken on stairs at 20" above floor
F7	3.2	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	static taken on stairs at 20" above floor
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Hallway		3.2	uR/hr	Utility	Installed furnace.		uR/hr			No	40% accessible
F10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	Bed in grid moved for survey



**Summary Report
1309 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	Bed in grid moved for survey
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	Bed in grid moved for survey
G5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	Bed in grid moved for survey
G6	2.8	uR/hr	Stairs		3.6	uR/hr	Storage			uR/hr			No	static taken on stairs at 44" above floor
G7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		No	static taken on stairs at 44" above floor
G8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
G9	3.6	uR/hr	Bathroom		3.6	uR/hr	Utility	Washing machine within grid.		uR/hr			No	70% accessible
G10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	80% accessible
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Bed in grid moved for survey, 70% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Bed in grid moved for survey, 70% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1309 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Bed in grid moved for survey, 70% accessible
H5	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.6	uR/hr	Living Room			uR/hr			No	Bed in grid moved for survey, 70% accessible, static taken on stairs at 60" above floor
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken on stairs at 60" above floor, 70% accessible
H7	2.8	uR/hr	Stairs		4.0	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr			No	static taken on stairs at 60" above floor, 70% accessible
H8	4.8	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	4.8	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.6	uR/hr	Utility	Washing machine within grid.		uR/hr			No	40% accessible
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	installed clothes dryer, 30% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1309 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1309 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1309 Gateview Avenue Unit B

Unit Summary :

Completion Date: 8/8/2014 2:43 PM

Instrument: 193-6

Serial #: 309099

Layout: Floor Plan 7

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.8 W 7.7

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids D12 and E12 are outside of floor plan.

Summary Statistics :

Total # of Readings: 117

Average: 3.14 uR/hr

Standard Deviation: 0.20 uR/hr

Minimum: 2.40 uR/hr

Maximum: 4.00 uR/hr

Median: 2.80 uR/hr

Anomalies: 0

Grid Legend:

-  No anomalous measurements
-  Inaccessible (no measurement collected)
-  Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static taken on stairs 56" from floor surface
A7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	static taken on stairs 56" from floor surface
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	static taken by toilet
A9	2.8	uR/hr	Utility		3.2	uR/hr	Bathroom			uR/hr			No	moved dryer moved to survey grid
A10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	moved washer moved to survey grid
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
B7	2.8	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	static taken on stairs 40" from floor surface



Summary Report
1309 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Utility		3.2	uR/hr	Bathroom			uR/hr			No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
C6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs		3.2	uR/hr	Hallway		No	static taken on stairs 16" from floor surface
C7	3.2	uR/hr	Hallway		3.2	uR/hr	Stairs		3.2	uR/hr	Hallway		No	static taken on stairs 16" from floor surface
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	
C10	2.8	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway	Installed furnace.	3.2	uR/hr	Mech Room	Installed furnace.		uR/hr			No	40% accessible
D10	3.2	uR/hr	Mech Room	Installed furnace.	3.2	uR/hr	Hallway			uR/hr			No	60% accessible
D11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.	2.8	uR/hr	Hallway			uR/hr			No	40% accessible
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid
E7	3.2	uR/hr	Kitchen		3.2	uR/hr	Dining Room			uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Dining Room		3.2	uR/hr	Kitchen			uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Trash		2.8	uR/hr	Dining Room			uR/hr			No	
F12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1309 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H5	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	70% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H7	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible, installed dishwasher
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



CBI Supervisor : Daniel Fielding

Senior Technician : Ricky Laguna

Signature :



Signature :



Signoff Notes:



Summary Report
1309 Gateview Avenue Unit C

Unit Summary :

Completion Date: 8/8/2014 12:51 PM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and grid D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 127
Average: 3.31 uR/hr
Standard Deviation: 0.23 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room	Installed Stove.	3.2	uR/hr	Kitchen			uR/hr			No	60% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr			No	95% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway		No	
D6	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	moved refrigerator to survey grid.



**Summary Report
1309 Gateview Avenue Unit C**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	60% accessible
E10	3.2	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr			No	40% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	25% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1309 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	reading .6 meters from floor for stairs
F7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading .6 meters from floor for stairs
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility	Installed furnace.	3.6	uR/hr	Hallway			uR/hr			No	75% accessible
F10	3.2	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Utility			uR/hr			No	80% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G9	3.2	uR/hr	Utility		4.0	uR/hr	Bathroom			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1309 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H9	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.	4.0	uR/hr	Bathroom			uR/hr			No	60% accessible. moved washer to survey grid.
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. moved dryer to survey grid.
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1309 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Summary Report
1309 Gateview Avenue Unit D

Unit Summary :

Completion Date: 7/7/2014 2:32 PM

Instrument: 193-6

Serial #: 309127

Layout: Floor Plan 7

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.6 W 7.6

Unit Furnished: No

Tenant Present: No

Unit Notes:

A-D13, F13, D11-12 grids are outside of floor plan

Summary Statistics :

Total # of Readings: 113

Average: 3.42 uR/hr

Standard Deviation: 0.27 uR/hr

Minimum: 2.40 uR/hr


Maximum: 4.40 uR/hr

Median: 3.00 uR/hr

Anomalies: 0

Grid Legend:

-  No anomalous measurements
-  Inaccessible (no measurement collected)
-  Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 60" from floor
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 60" from floor
A7	2.4	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 60" from floor
A8	4.4	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	No washer installed
A10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	No dryer installed
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
B6	3.2	uR/hr	Stairs		3.6	uR/hr	Storage			uR/hr			No	Stairs reading taken 28" from floor
B7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway		3.6	uR/hr	Bathroom		No	Stairs reading taken 28" from floor
B8	3.6	uR/hr	Hallway		3.2	uR/hr	Bathroom			uR/hr			No	



**Summary Report
1309 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Hallway		3.6	uR/hr	Bathroom		3.6	uR/hr	Utility		No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway		3.2	uR/hr	Storage		No	
C6	3.6	uR/hr	Hallway		3.2	uR/hr	Stairs		3.6	uR/hr	Storage		No	Stairs reading taken 12" from floor
C7	3.2	uR/hr	Hallway		3.2	uR/hr	Stairs			uR/hr			No	Stairs reading taken 12" from floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway	Installed furnace.	4.0	uR/hr	Utility			uR/hr			No	50% accessible
C10	3.6	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	50% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
D1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	



Summary Report
1309 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	80% accessible
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible. Partial grid-partial grid due to installed water heater
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E8	3.2	uR/hr	Hallway		3.6	uR/hr	Dining Room			uR/hr			No	
E9	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room			uR/hr			No	70% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1309 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room		3.2	uR/hr	Trash			uR/hr			No	
F12	3.2	uR/hr	Trash			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Installed Stove.		uR/hr			No	30% accessible
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible



**Summary Report
1309 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	60% accessible. Kitchen reading taken 12" from floor.
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Kitchen reading taken 12" from floor inside accessible base cabinet
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. Partial grid-partial grid due to installed dishwasher. Kitchen reading taken 12" from floor inside accessible base cabinet
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :

A handwritten signature in black ink on a light blue background. The signature is cursive and appears to read "Garrick Anderson".

Signature :

A handwritten signature in black ink on a light blue background. The signature is cursive and appears to read "Patricia Lozano".

Signoff Notes:



Summary Report
1309 Gateview Avenue Unit E

Unit Summary :

Completion Date: 7/7/2014 3:36 PM

Instrument: 193-6

Serial #: 309119

Layout: Floor Plan 7B

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: No

Tenant Present: No

Unit Notes:

storage area at front of unit is longest point, main unit is 9.4 m F13, G13, H13 are outside unit boundary

Summary Statistics :

Total # of Readings: 109

Average: 3.07 uR/hr

Standard Deviation: 0.24 uR/hr

Minimum: 2.40 uR/hr


Maximum: 4.00 uR/hr

Median: 2.80 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room	Grid partially contained within wall construction.	3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	50% accessible, survey taken in installed base cabinets
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Dining Room		2.8	uR/hr	Trash			uR/hr			No	
C12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	total depth 11.8 m.
D1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway		No	
D6	3.2	uR/hr	Kitchen		2.8	uR/hr	Hallway			uR/hr			No	refrigerator moved for survey
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Mech Room	Installed furnace.		uR/hr				uR/hr			No	50% accessible
E10	2.8	uR/hr	Mech Room	Installed water heater.		uR/hr				uR/hr			No	80% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible



Summary Report
1309 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	reading on stairs taken at .4 m from ground level
F7	2.8	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	reading on stairs taken at .4 m from ground level
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	reading on stairs taken at .8 m from ground level
G7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	reading on stairs taken at 1 m from ground level
G8	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Bathroom		2.8	uR/hr	Utility			uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	60% accessible, reading on stairs taken at 1.4 m from ground level
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, reading on stairs taken at 1.4 m from ground level
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	2.8	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr			No	60% accessible, reading on stairs taken at 1.4 m from ground level
H8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	Elevated measurement is near toilet
H9	3.6	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
H10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
H11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes	
H12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible	



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :

Signature :

Signoff Notes:



Summary Report
1309 Gateview Avenue Unit F

Unit Summary :

Completion Date: 8/8/2014 1:06 PM

Instrument: 193-6

Serial #: 309119

Layout: Floor Plan 7

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.9 W 7.7

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grid D11, D12, and E12 fall outside of survey unit.

Summary Statistics :

Total # of Readings: 113

Average: 3.05 uR/hr

Standard Deviation: 0.23 uR/hr

Minimum: 2.40 uR/hr

Maximum: 3.60 uR/hr

Median: 2.80 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.4	uR/hr	Stairs			uR/hr			No	Stair static taken 60" above floor
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken 60" above floor
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken 60" above floor
A8	3.2	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A9	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	30% accessible
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
B6	2.4	uR/hr	Stairs		3.2	uR/hr	Storage			uR/hr			No	Stair static taken 44" above floor



Summary Report
1309 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken 44" above floor
B8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Utility	Washing machine within grid.	No	30% accessible
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		3.2	uR/hr	Storage		No	
C6	3.2	uR/hr	Hallway		2.8	uR/hr	Stairs		3.2	uR/hr	Storage		No	Stair static taken 20" above floor
C7	3.2	uR/hr	Hallway		2.8	uR/hr	Stairs			uR/hr			No	Stair static taken 20" above floor
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility	Installed furnace.	3.2	uR/hr	Hallway			uR/hr			No	80% accessible
C10	2.8	uR/hr	Mech Room	Installed water heater.	2.8	uR/hr	Utility			uR/hr			No	70% accessible
C11	2.8	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Storage			uR/hr			No	90% accessible
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	80% accessible
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room			uR/hr			No	installed hot water heater 40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		2.8	uR/hr	Kitchen	Installed base cabinets.		uR/hr			No	50% accessible
E6	3.2	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	30% accessible
E7	2.8	uR/hr	Hallway		3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr			No	60% accessible
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	35% accessible
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible



**Summary Report
1309 Gateview Avenue Unit F**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Trash			uR/hr			No	90% accessible
F12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	40% accessible. Partial grid in kitchen inaccessible due to installed stove
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1309 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	second refrigerator moved for survey
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible second refrigerator moved for survey
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	partial grid remainder fall outside unit 70% accessible
H6	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid remainder fall outside unit 70% accessible
H7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid remainder fall outside unit 70% accessible



Summary Report
1309 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible second refrigerator moved for survey
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible second refrigerator moved for survey



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :



Signature :



Signoff Notes:



Summary Report
1310 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/7/2014 4:35 PM

Instrument: 193-6

Serial #: 309099

Layout: Floor Plan 7B

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.7 W 7.7

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids in column I, row 13 and grid D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 126

Average: 2.97 uR/hr

Standard Deviation: 0.27 uR/hr

Minimum: 2.40 uR/hr


Maximum: 4.00 uR/hr

Median: 2.60 uR/hr

Anomalies: 0

Grid Legend:

-  No anomalous measurements
-  Inaccessible (no measurement collected)
-  Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
A6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1310 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Trash		2.8	uR/hr	Dining Room			uR/hr			No	
C12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen		No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway		2.8	uR/hr	Kitchen			uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1310 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	2.8	uR/hr	Mech Room	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	40% accessible
E11	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Storage			uR/hr			No	20% accessible
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		2.8	uR/hr	Storage			uR/hr			No	
F6	2.8	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	static taken on stairs 16" from floor surface
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Hallway		2.8	uR/hr	Utility			uR/hr			No	
F10	2.8	uR/hr	Utility	Installed water heater.	2.8	uR/hr	Mech Room			uR/hr			No	60% accessible



Summary Report
1310 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static taken on stairs 40" from floor surface
G8	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Utility		2.8	uR/hr	Bathroom			uR/hr			No	
G10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1310 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface, 70% accessible
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken on stairs 56" from floor surface, 70% accessible
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken on stairs 56" from floor surface, 70% accessible
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible, static taken by toilet
H9	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.	4.0	uR/hr	Bathroom			uR/hr			No	70% accessible, moved installed washer
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible, moved installed dryer
H11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan



Summary Report
1310 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1310 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes	
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan	
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan	



CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized, starting with a large 'N' and ending with a large 'O'.

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized, starting with a large 'R' and ending with a horizontal line.

Signoff Notes:



Summary Report
1310 Gateview Avenue Unit B

Unit Summary :

Completion Date: 7/8/2014 3:40 PM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.7 W 7.6
Unit Furnished: No
Tenant Present: No
Unit Notes:

Summary Statistics :

Total # of Readings: 123
Average: 3.02 uR/hr
Standard Deviation: 0.24 uR/hr
Minimum: 2.40 uR/hr
Maximum: 3.60 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Living Room		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56 inches from floor surface
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static taken on stairs 56 inches from floor surface
A7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	static taken on stairs 56 inches from floor surface
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	
A10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
A13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	



Summary Report
1310 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 40 inches from floor surface
B7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		No	static taken on stairs 40 inches from floor surface
B8	3.2	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Utility		2.8	uR/hr	Bathroom		3.2	uR/hr	Hallway		No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
B13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage		3.2	uR/hr	Hallway		No	
C6	3.2	uR/hr	Storage		3.2	uR/hr	Hallway		3.2	uR/hr	Stairs		No	static taken on stairs 8 inches from floor surface
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	static taken on stairs 8 inches from floor surface
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed furnace.		uR/hr			No	40% accessible
C10	3.2	uR/hr	Mech Room	Installed water heater.	2.8	uR/hr	Utility		2.8	uR/hr	Hallway		No	40% accessible



Summary Report
1310 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
C13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
D1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway		3.2	uR/hr	Mech Room			uR/hr			No	
D10	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D11	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
D13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	



**Summary Report
1310 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E6	3.2	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	30% accessible
E7	3.2	uR/hr	Kitchen		2.8	uR/hr	Hallway			uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway		2.8	uR/hr	Hallway			uR/hr			No	
E10	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr			No	50% accessible
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Trash		No	25% accessible
F12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	45% accessible
F13		uR/hr	Trash	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside floor plan
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1310 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	45% accessible
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Kitchen			uR/hr			No	50% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H7	2.8	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	10% accessible
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible



Summary Report
1310 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible



CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized and appears to read "N. Rothell".

Signature :

A handwritten signature in black ink on a light blue background. The signature is written in a cursive style and clearly reads "Ricky Laguna".

Signoff Notes:



Summary Report
1310 Gateview Avenue Unit C

Unit Summary :

Completion Date: 8/8/2014 3:15 PM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 130
Average: 3.37 uR/hr
Standard Deviation: 0.28 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.40 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	Kitchen reading taken 12" from floor inside base cabinet.
A6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	30% accessible.
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible.
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	30% accessible.
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible.



Summary Report
1310 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	50% accessible.
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway		No	Kitchen reading taken 12" from floor inside base cabinet.



Summary Report
1310 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D6	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	
D7	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	Kitchen reading taken 12" from floor inside base cabinet.
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	30% accessible. Mech room inaccessible due to furnace.
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	45% accessible.
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.



**Summary Report
1310 Gateview Avenue Unit C**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	Stairs reading taken 12" from floor.
F7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 12" from floor.
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Utility		3.6	uR/hr	Hallway			uR/hr			No	60% accessible. Mech room inaccessible due to furnace.
F10	3.6	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible.
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1310 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage		2.8	uR/hr	Stairs		No	Stairs reading taken 44" from floor.
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 44" from floor.
G7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 44" from floor.
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Utility		4.0	uR/hr	Bathroom			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible. Stairs reading taken 44" from floor.



Summary Report
1310 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Stairs reading taken 44" from floor.
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	60% accessible. Stairs reading taken 44" from floor.
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.	4.4	uR/hr	Bathroom			uR/hr			No	30% accessible. Partial grid due to installed washer.
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible. Partial grid due to installed dryer.
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1310 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Summary Report
1310 Gateview Avenue Unit D

Unit Summary :

Completion Date: 7/8/2014 2:13 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.7
Unit Furnished: No
Tenant Present: No


Unit Notes:
Elevated measurements due to NORM in toilet.
A13 through C13 are outside.

Summary Statistics :

Total # of Readings: 107
Average: 3.24 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.4	uR/hr	Stairs			uR/hr			No	static reading taken on stairs at 64 inches from floor
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static reading taken on stairs at 64 inches from floor
A7	3.2	uR/hr	Bathroom	Installed base cabinets.	2.4	uR/hr	Stairs			uR/hr			No	static reading taken on stairs at 64 inches from floor
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
A10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Storage		3.2	uR/hr	Utility			uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage		2.8	uR/hr	Stairs		No	static reading taken on stairs at 64 inches from floor
B6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static reading taken on stairs at 60 inches from floor



Summary Report
1310 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.2	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	static reading taken on stairs at 60 inches from floor
B8	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
C6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	static reading taken on stairs at 12 inches from floor
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	static reading taken on stairs at 12 inches from floor
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility	Installed furnace.		uR/hr				uR/hr			No	20% accessible
C10	3.2	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	20% accessible
C11	3.2	uR/hr	Storage		3.2	uR/hr	Mech Room			uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1310 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
D11	3.2	uR/hr	Storage	Installed water heater.		uR/hr				uR/hr			No	5% accessible
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Dining Room		3.2	uR/hr	Hallway			uR/hr			No	
E10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Hallway			uR/hr			No	40% accessible
E11	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1310 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Dining Room		3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr			No	80% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	50% accessible due to stove
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible



Summary Report
1310 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Kitchen			uR/hr			No	70% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible due to installed dishwasher
H7	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized, starting with a large 'T' and 'P' followed by a cursive flourish.

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized, starting with a large 'D' and 'D' followed by a cursive flourish.

Signoff Notes:



Summary Report
1310 Gateview Avenue Unit E

Unit Summary :

Completion Date: 7/8/2014 3:02 PM

Instrument: 193-6

Serial #: 309136

Layout: Floor Plan 7B

Background Reading: 2.8 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: No

Tenant Present: No

Unit Notes:

Grids G13, F13, E13 and H13 are outside of floor plan

Summary Statistics :

Total # of Readings: 112

Average: 2.67 uR/hr

Standard Deviation: 0.24 uR/hr

Minimum: 2.00 uR/hr


Maximum: 3.60 uR/hr

Median: 2.40 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Kitchen	Kitchen cabinets and appliances not installed.	2.4	uR/hr	Living Room			uR/hr			No	
A6	2.4	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	2.4	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.4	uR/hr	Kitchen	Installed Stove.	2.4	uR/hr	Living Room			uR/hr			No	30% accessible.
B6	2.8	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	30% accessible.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Kitchen		2.4	uR/hr	Living Room			uR/hr			No	
C6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	2.4	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	2.4	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Trash			uR/hr			No	20% accessible in dining room.
C12	2.4	uR/hr	Trash			uR/hr				uR/hr			No	
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.4	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.4	uR/hr	Living Room		2.4	uR/hr	Hallway		No	



Summary Report
1310 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D6	2.8	uR/hr	Kitchen		2.4	uR/hr	Hallway			uR/hr			No	Pulled out refrigerator and surveyed.
D7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
D8	2.4	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.4	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Hallway		2.4	uR/hr	Living Room			uR/hr			No	
E6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.4	uR/hr	Mech Room	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	Mech room static taken at 0.6 meters above ground level. 80% accessible.
E10	2.4	uR/hr	Mech Room	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	30% accessible.
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible
E12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
F1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	
F6	2.4	uR/hr	Stairs		2.8	uR/hr	Storage			uR/hr			No	Stairs static taken at 0.5 meters from ground level.
F7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs static taken at 0.5 meters from ground level.
F8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Utility		2.4	uR/hr	Mech Room	Installed furnace.	2.8	uR/hr	Hallway		No	Mech room static taken at 0.6 meters above ground level. 30% accessible
F10	2.8	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	30% accessible
F11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
F12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	
G5	2.0	uR/hr	Stairs		2.8	uR/hr	Living Room		2.8	uR/hr	Storage		No	Stairs static taken at 1.5 meters from ground level.
G6	2.4	uR/hr	Stairs		2.8	uR/hr	Storage			uR/hr			No	Stairs static taken at 1.1 meters from ground level.



Summary Report
1310 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs static taken at 1.1 meters from ground level.
G8	2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
G9	2.8	uR/hr	Utility		2.8	uR/hr	Bathroom			uR/hr			No	
G10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Storage		2.8	uR/hr	Utility			uR/hr			No	
G12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
H1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	2.0	uR/hr	Stairs	Percentage of grid falls outside of unit.	2.4	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	Stairs static taken at 1.5 meters from ground level. 60% accessible.
H6	2.0	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Stairs static taken at 1.5 meters from ground level. 60% accessible.
H7	2.0	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Stairs static taken at 1.5 meters from ground level. 60% accessible.



Summary Report
1310 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H8	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	2.4	uR/hr	Utility	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	Elevated materials due to NORM in toilet bowl material. 60% accessible.
H10	2.4	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.	2.8	uR/hr	Storage			uR/hr			No	60% accessible.
H12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :



Signature :



Signoff Notes:



Summary Report
1310 Gateview Avenue Unit F

Unit Summary :

Completion Date: 8/8/2014 1:35 PM

Instrument: 193-6

Serial #: 309136

Layout: Floor Plan 7

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Bed located in living room - Grids A1-2 and B1-2.
Moved bed for survey. Grids D11, D12 and E12
are outside of survey unit.

Summary Statistics :

Total # of Readings: 114

Average: 2.74 uR/hr

Standard Deviation: 0.22 uR/hr

Minimum: 2.00 uR/hr


Maximum: 3.60 uR/hr

Median: 2.40 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.0	uR/hr	Stairs		2.8	uR/hr	Living Room			uR/hr			No	Stair static taken at 1.5 meters above floor level
A6	2.0	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.5 meters above floor level
A7	2.0	uR/hr	Stairs		2.8	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.5 meters above floor level
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Utility	Washing machine within grid.	3.6	uR/hr	Bathroom			uR/hr			No	90% accessible, washer partially moved for survey
A10	2.8	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	60% accessible, dryer partially moved for survey
A11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	



Summary Report
1310 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	2.8	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.1 meters above floor level
B7	2.4	uR/hr	Stairs		2.4	uR/hr	Hallway		2.4	uR/hr	Bathroom		No	Stair static taken at 1.1 meters above floor level
B8	2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
B9	2.8	uR/hr	Utility		2.8	uR/hr	Bathroom			uR/hr			No	
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		No	
C6	2.8	uR/hr	Storage		2.8	uR/hr	Hallway		2.8	uR/hr	Stairs		No	Stair static taken at 0.5 meters above floor level
C7	2.4	uR/hr	Stairs		2.8	uR/hr	Hallway			uR/hr			No	Stair static taken at 0.5 meters above floor level
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Utility	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	60% accessible
C10	2.8	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	40% accessible
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1310 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	95% accessible
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.8	uR/hr	Living Room			uR/hr			No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	50% accessible
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	



Summary Report
1310 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E6	2.8	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	80% accessible, refrigerator partially moved for survey
E7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
E8	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E9	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.4	uR/hr	Dining Room			uR/hr			No	30% accessible
E11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	
F6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1310 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F11	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.	2.4	uR/hr	Dining Room			uR/hr			No	40% accessible
F12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	30% accessible
G6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	2.4	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.4	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.	2.4	uR/hr	Living Room			uR/hr			No	60% accessible, survey through bottom 1" wood shelf in living room bookcase



Summary Report
1310 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, survey inside installed cabinets
H7	2.4	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible, installed dishwasher, survey inside installed cabinets
H8	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible

CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :



Signature :



Signoff Notes:



Summary Report
1311 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/8/2014 4:02 PM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 126
Average: 3.39 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room	Survey performed on non-movable item.	3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	60% accessible. reading taken on unstable non-movable book shelf at 6".
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1311 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	95% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1311 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
D6	3.2	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	moved refrigerator to survey grid.
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
E10	3.2	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr			No	40% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	25% accessible



**Summary Report
1311 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading .6 meters from floor for stairs
F7	3.6	uR/hr	Stairs			uR/hr				uR/hr			No	reading .6 meters from floor for stairs
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Hallway	Installed furnace.	3.6	uR/hr	Utility			uR/hr			No	75% accessible
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible
F11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	



Summary Report
1311 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	4.0	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs



**Summary Report
1311 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible. moved washer to survey grid.
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. moved dryer to survey grid
H11	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1311 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :

Signature :

Signoff Notes:



Summary Report
1311 Gateview Avenue Unit B

Unit Summary :

Completion Date: 7/8/2014 3:53 PM

Instrument: 193-6

Serial #: 309110

Layout: Floor Plan 7

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.65

Unit Furnished: No

Tenant Present: No

Unit Notes:

Summary Statistics :

Total # of Readings: 116

Average: 3.50 uR/hr

Standard Deviation: 0.22 uR/hr

Minimum: 2.80 uR/hr

Maximum: 4.00 uR/hr

Median: 3.20 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	reading taken at 1.8 meters from floor for stairs
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading taken at 1.8 meters from floor
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading taken at 1.8 meters from floor
A8	3.6	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A9	3.6	uR/hr	Utility		4.0	uR/hr	Bathroom			uR/hr			No	
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Storage		3.6	uR/hr	Utility			uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
B6	3.6	uR/hr	Storage			uR/hr				uR/hr			No	reading taken at 1.3 meters from floor for stairs



**Summary Report
1311 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading taken at 1.3 meters from floor
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Utility		3.6	uR/hr	Hallway		3.6	uR/hr	Bathroom		No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage		3.6	uR/hr	Utility			uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway		3.6	uR/hr	Storage		No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.2	uR/hr	Stairs		No	reading taken at .6 meters from floor for stairs
C7	3.6	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	reading taken at .6 meters from floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed furnace.	3.6	uR/hr	Hallway		No	75% accessible
C10	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible
C11	3.2	uR/hr	Storage		3.2	uR/hr	Mech Room		3.2	uR/hr	Utility		No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1311 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible- installed furnace in mechanical room
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible due to installed water heater and furnace
D11	3.2	uR/hr	Mech Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible, installed water heater
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	



Summary Report
1311 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr			No	80% accessible
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Installed Stove.		uR/hr			No	70% accessible
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.6	uR/hr	Trash			uR/hr			No	95% accessible
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
F13	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Kitchen	Installed Stove.	3.6	uR/hr	Living Room			uR/hr			No	60% accessible



**Summary Report
1311 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	90% accessible
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	65% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	65% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	65% accessible. static reading taken at 4" due to base cabinet shelf
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	65% accessible
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible-installed dishwasher
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	65% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	65% accessible



Summary Report
1311 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes	
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	65% accessible	
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible	



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Summary Report
1311 Gateview Avenue Unit C

Unit Summary :


Completion Date: 7/8/2014 3:32 PM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes
Unit Notes:

Summary Statistics :

Total # of Readings: 115
Average: 3.48 uR/hr
Standard Deviation: 0.22 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
A3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
A4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
A5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible. Partial grid-partial grid due to installed base cabinet in kitchen
A6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Survey performed within accessible base cabinet at 12" from floor
A7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. Partial grid-partial grid due to installed dishwasher. Survey performed inside accessible base cabinet at 12" from floor
A8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
A9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1311 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
A11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	50% accessible. Partial grid-partial grid due to installed stove
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	60% accessible.
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	



**Summary Report
1311 Gateview Avenue Unit C**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	80% accessible
C12	3.2	uR/hr	Trash			uR/hr				uR/hr			No	
C13		uR/hr	Trash	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
D6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
D8	3.2	uR/hr	Dining Room		3.6	uR/hr	Hallway			uR/hr			No	
D9	3.6	uR/hr	Dining Room		3.6	uR/hr	Hallway			uR/hr			No	
D10	3.6	uR/hr	Dining Room		3.2	uR/hr	Hallway			uR/hr			No	Grid is 80% accessible.
D11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible



Summary Report
1311 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	Grid is 80% accessible due to the furnace.
E10	3.2	uR/hr	Mech Room			uR/hr				uR/hr			No	Grid is 30% accessible.
E11		uR/hr		Grids are outside unit interior boundary.		uR/hr				uR/hr			No	
E12		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	
E13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.2	uR/hr	Hallway		3.6	uR/hr	Storage		No	
F6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Stairs		No	Reading taken 12 inches from the floor



Summary Report
1311 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F7	3.6	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	Reading taken 12 inches from floor.
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Hallway		3.2	uR/hr	Utility			uR/hr			No	No washer and dryer
F10	3.6	uR/hr	Utility		2.8	uR/hr	Mech Room			uR/hr			No	
F11	3.6	uR/hr	Storage	Installed water heater.		uR/hr				uR/hr			No	Grid is 80% accessible.
F12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Grid is 70% accessible.
F13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.2	uR/hr	Stairs			uR/hr			No	Reading taken 68 inches from floor.
G6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	Reading taken 28 inches from the floor.
G7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	Reading taken 28 inches from floor.
G8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
G9	3.6	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Grid is 70% accessible.



Summary Report
1311 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G13		uR/hr	Storage	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	
H1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
H2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
H3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
H4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
H5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage		3.2	uR/hr	Stairs		No	Reading taken 60 inches from floor.
H6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Reading taken 60 inches from floor.
H7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Reading taken 60 inches from floor.
H8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	Toilet is contributor to measurement.
H9	3.6	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	
H10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
H11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
H12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Grid is 70% accessible.
H13		uR/hr		Grids are outside unit interior boundary.		uR/hr				uR/hr			No	




CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Summary Report
1311 Gateview Avenue Unit D

Unit Summary :

Completion Date: 7/9/2014 3:41 PM

Instrument: 193-6

Serial #: 293633

Layout: Floor Plan 7

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: No

Tenant Present: No

Unit Notes:

Elevated measurements due to NORM in toilet construction materials. A13 through C13 along with F13 are outside and D11 -D12 are outside unit footprint.

Summary Statistics :

Total # of Readings: 104

Average: 3.42 uR/hr

Standard Deviation: 0.32 uR/hr

Minimum: 2.40 uR/hr


Maximum: 4.80 uR/hr

Median: 3.00 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	static reading taken on stairs at 60 inches from floor
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	static reading taken on stairs at 60 inches from floor
A7	2.4	uR/hr	Stairs		4.0	uR/hr	Bathroom			uR/hr			No	static reading taken on stairs at 60 inches from floor
A8	4.4	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Utility		4.8	uR/hr	Bathroom			uR/hr			No	
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	No washer and dryer in unit
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage		2.4	uR/hr	Stairs		No	static reading taken on stairs at 68 inches from floor
B6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	static reading taken on stairs at 52 inches from floor



Summary Report
1311 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	static reading taken on stairs at 52 inches from floor
B8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Utility		3.2	uR/hr	Bathroom			uR/hr			No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
C6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	static reading taken on stairs at 12 inches from floor
C7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	static reading taken on stairs at 12 inches from floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr				uR/hr			No	20% accessible
C10	3.2	uR/hr	Mech Room	Installed furnace.		uR/hr				uR/hr			No	20% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1311 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D6	4.0	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Dining Room		3.6	uR/hr	Hallway			uR/hr			No	
E10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Hallway			uR/hr			No	40% accessible
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1311 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	85% accessible
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	80% accessible
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	10% accessible
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1311 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H5	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
H6	3.2	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	60% accessible
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible, installed dishwasher
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1311 Gateview Avenue Unit E

Unit Summary :

Completion Date: 8/8/2014 4:28 PM

Instrument: 193-6

Serial #: 293633

Layout: Floor Plan 7B

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 129

Average: 3.49 uR/hr

Standard Deviation: 0.30 uR/hr

Minimum: 2.80 uR/hr


Maximum: 5.00 uR/hr

Median: 3.20 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Living Room			uR/hr			No	
A6	3.6	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	40% accessible
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	40% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B6	3.6	uR/hr	Kitchen	Installed Stove.		uR/hr				uR/hr			No	90% accessible
B7	3.6	uR/hr	Kitchen	Installed base cabinets.		uR/hr				uR/hr			No	70% accessible
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1311 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room		5.0	uR/hr	Dining Room			uR/hr			No	Model 19 267078 used to scan under non-movable shelf, background at standard location 5 uR/hr. optional 2nd static taken with model 19
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	60% accessible
C12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1311 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D5	3.6	uR/hr	Kitchen	Installed base cabinets.	3.6	uR/hr	Living Room		3.2	uR/hr	Hallway		No	70% accessible
D6	3.6	uR/hr	Kitchen		3.6	uR/hr	Kitchen			uR/hr			No	installed refrigerator moved for survey
D7	3.6	uR/hr	Kitchen		3.6	uR/hr	Hallway			uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed furnace.		uR/hr			No	40% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



Summary Report
1311 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs		3.6	uR/hr	Hallway		No	Static taken on stairs 12" above ground
F7	3.2	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	Static taken on stairs 12" above ground
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
G6	2.8	uR/hr	Stairs		3.6	uR/hr	Storage			uR/hr			No	Static taken on stairs 44" above ground

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Static taken on stairs 44" above ground
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible, Static taken on stairs 60" above ground
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	Static taken on stairs 60" above ground, 60% accessible
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	60% accessible, Static taken on stairs 60" above ground



Summary Report
1311 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Utility	Washing machine within grid.	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr			No	40% accessible
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	clothes dryer in grid, 40% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1311 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Page 1 of 8

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		2.8	uR/hr	Stairs			uR/hr			No	Stairs static taken 60" above floor
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs static taken 60" above floor
A7	3.6	uR/hr	Bathroom	Survey performed within accessible base cabinet.	2.8	uR/hr	Stairs			uR/hr			No	Stairs static taken 60" above floor
A8	4.4	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.2	uR/hr	Utility	Washing machine within grid.		uR/hr			No	60% accessible
A10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	30% accessible
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage		2.8	uR/hr	Stairs		No	Stairs static taken 60" above floor
B6	4.0	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stairs static taken 44" above floor



Summary Report
1311 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Stairs		No	Stairs static taken 44" above floor
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		3.6	uR/hr	Utility		No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room		3.6	uR/hr	Storage		No	
C6	4.0	uR/hr	Hallway		3.6	uR/hr	Storage		3.6	uR/hr	Stairs		No	Stairs static taken 12" above floor
C7	3.6	uR/hr	Hallway		3.6	uR/hr	Stairs			uR/hr			No	Stairs static taken 12" above floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Utility	Installed furnace.		uR/hr				uR/hr			No	70% accessible
C10	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
C11	3.2	uR/hr	Storage		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1311 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	70% accessible
D10	3.2	uR/hr	Hallway	Installed water heater.		uR/hr				uR/hr			No	20% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	4.0	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	40% accessible
E7	4.0	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Hallway			uR/hr			No	
E8	3.6	uR/hr	Dining Room		3.6	uR/hr	Hallway			uR/hr			No	
E9	3.6	uR/hr	Dining Room		3.6	uR/hr	Hallway			uR/hr			No	
E10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Hallway			uR/hr			No	35% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	installed stove in kitchen section of grid 40% accessible



Summary Report
1311 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	60% accessible
H6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid remainder of grid falls outside 60% accessible
H7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	partial grid remainder of grid falls outside 60% accessible
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1311 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible


CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1312 Gateview Avenue Unit A

Unit Summary :


Completion Date: 6/19/2014 3:49 PM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7B
Background Reading: 4.0 uR/hr
Dimensions (m): D W
Unit Furnished:
Tenant Present:
Unit Notes:

Summary Statistics :

Total # of Readings: 93
Average: 3.70 uR/hr
Standard Deviation: 0.26 uR/hr
Minimum: 3.20 uR/hr
Maximum: 5.20 uR/hr
Median: 3.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Reading	Reading Units	Anomaly	Notes	Cell Description	Second Reading	Second Reading Units	Second Reading Cell Description
A2	3.6	uR/hr	No	portion of grid is patio	Living Room		uR/hr	
A3	3.6	uR/hr	No		Living Room		uR/hr	
A4	4.0	uR/hr	No		Living Room		uR/hr	
A5	3.6	uR/hr	No	optional reading - inside kitchen cabinet	Living Room	3.6	uR/hr	Kitchen
A6	3.6	uR/hr	No		Kitchen		uR/hr	
A7	4.0	uR/hr	No	reading in front of dishwasher	Kitchen		uR/hr	
A8	3.6	uR/hr	No		Dining Room		uR/hr	
A9	3.6	uR/hr	No		Dining Room		uR/hr	
A10	3.6	uR/hr	No		Dining Room		uR/hr	
A11	3.6	uR/hr	No	partial of grid outside the house	Dining Room		uR/hr	
B2	3.6	uR/hr	No	portion of grid is patio	Living Room		uR/hr	
B3	4.0	uR/hr	No		Living Room		uR/hr	
B4	3.6	uR/hr	No		Living Room		uR/hr	
B5	3.6	uR/hr	No	kitchen portion inaccessible due to stove	Living Room		uR/hr	
B6	3.6	uR/hr	No		Kitchen		uR/hr	
B7	3.6	uR/hr	No		Kitchen		uR/hr	
B8	4.0	uR/hr	No		Dining Room		uR/hr	
B9	4.0	uR/hr	No		Dining Room		uR/hr	
B10	3.6	uR/hr	No		Dining Room		uR/hr	
B11	3.6	uR/hr	No	partial outside the house	Dining Room		uR/hr	
C2	3.6	uR/hr	No	portion of grid is patio	Living Room		uR/hr	
C3	3.6	uR/hr	No		Living Room		uR/hr	
C4	3.6	uR/hr	No		Living Room		uR/hr	
C5	3.6	uR/hr	No		Living Room		uR/hr	
C6	3.6	uR/hr	No		Kitchen		uR/hr	
C7	4.0	uR/hr	No		Kitchen		uR/hr	
C8	4.0	uR/hr	No		Dining Room		uR/hr	



Summary Report
1312 Gateview Avenue Unit A

Grid	Reading	Reading Units	Anomaly	Notes	Cell Description	Second Reading	Second Reading Units	Second Reading Cell Description
C9	3.6	uR/hr	No		Dining Room		uR/hr	
C10	3.6	uR/hr	No		Dining Room		uR/hr	
C11	3.2	uR/hr	No		Dining Room	3.6	uR/hr	Trash
C12	3.6	uR/hr	No		Trash		uR/hr	
C13		uR/hr	No	N/A- Trash area contained within area C12.	Trash		uR/hr	
D1		uR/hr	No	N/A- Grids are outside of unit interior boundary.	Living Room		uR/hr	
D2	3.6	uR/hr	No		Living Room		uR/hr	
D3	4.0	uR/hr	No		Living Room		uR/hr	
D4	4.0	uR/hr	No		Living Room		uR/hr	
D5	3.6	uR/hr	No		Living Room		uR/hr	
D6		uR/hr	No	inaccessible cell installed refrigerator.	Kitchen		uR/hr	
D7		uR/hr	No	inaccessible cell, base cabinet, no door.	Kitchen		uR/hr	
D8	3.6	uR/hr	No		Hallway		uR/hr	
D9	3.6	uR/hr	No		Hallway		uR/hr	
D10	3.6	uR/hr	No		Hallway		uR/hr	
E1	3.6	uR/hr	No		Living Room		uR/hr	
E2	4.0	uR/hr	No		Living Room		uR/hr	
E3	4.0	uR/hr	No		Living Room		uR/hr	
E4	3.6	uR/hr	No		Living Room		uR/hr	
E5	3.6	uR/hr	No		Living Room		uR/hr	
E6	3.6	uR/hr	No		Hallway		uR/hr	
E7	3.6	uR/hr	No		Hallway		uR/hr	
E8	3.6	uR/hr	No		Hallway		uR/hr	
E9	3.6	uR/hr	No		Hallway		uR/hr	
E10	3.6	uR/hr	No		Mech Room		uR/hr	
E11	3.6	uR/hr	No		Storage		uR/hr	
E12	3.6	uR/hr	No		Storage		uR/hr	
F1	3.6	uR/hr	No		Living Room		uR/hr	

Grid	Reading	Reading Units	Anomaly	Notes	Cell Description	Second Reading	Second Reading Units	Second Reading Cell Description
F2	3.6	uR/hr	No		Living Room		uR/hr	
F3	3.6	uR/hr	No		Living Room		uR/hr	
F4	3.6	uR/hr	No		Living Room		uR/hr	
F5	3.6	uR/hr	No		Living Room	3.6	uR/hr	Closet
F6	3.6	uR/hr	No	partial of grid under stairs	Storage		uR/hr	
F7	3.6	uR/hr	No	most of grid is under stairs	Stairs		uR/hr	
F8	3.6	uR/hr	No		Hallway		uR/hr	
F9	3.6	uR/hr	No		Utility	3.6	uR/hr	Utility
F10	3.6	uR/hr	No		Utility		uR/hr	
F11	3.6	uR/hr	No		Storage		uR/hr	
F12	3.6	uR/hr	No		Storage		uR/hr	
F13		uR/hr	No	N/A- Grids are outside unit interior boundary.	Storage		uR/hr	
G1	4.0	uR/hr	No		Living Room		uR/hr	
G2	3.6	uR/hr	No		Living Room		uR/hr	
G3	4.0	uR/hr	No		Living Room		uR/hr	
G4	3.6	uR/hr	No		Living Room		uR/hr	
G5	4.0	uR/hr	No		Living Room	3.6	uR/hr	Closet
G6	3.6	uR/hr	No	partial under stairs	Storage		uR/hr	
G7	3.6	uR/hr	No		Stairs		uR/hr	
G8	3.6	uR/hr	No		Bathroom	3.6	uR/hr	Hallway
G9	4.0	uR/hr	No		Utility	3.6	uR/hr	Utility
G10	3.6	uR/hr	No		Utility		uR/hr	
G11	3.6	uR/hr	No		Storage		uR/hr	
G12	3.6	uR/hr	No		Storage		uR/hr	
G13		uR/hr	No	N/A- Grids are outside unit interior boundary.	Storage		uR/hr	
H1	3.6	uR/hr	No		Living Room		uR/hr	
H2	4.0	uR/hr	No		Living Room		uR/hr	
H3	3.6	uR/hr	No		Living Room		uR/hr	



Summary Report
1312 Gateview Avenue Unit A

Grid	Reading	Reading Units	Anomaly	Notes	Cell Description	Second Reading	Second Reading Units	Second Reading Cell Description
H4	3.6	uR/hr	No		Living Room		uR/hr	
H5	3.6	uR/hr	No		Living Room		uR/hr	
H6		uR/hr	No	N/A- Area under stairs not accessible.	Stairs		uR/hr	
H7	3.6	uR/hr	No		Stairs		uR/hr	
H8	4.8	uR/hr	No	Elevated measurements due to NORM in toilet bowl and tile materials.	Bathroom		uR/hr	
H9	5.2	uR/hr	No	Elevated measurements due to NORM in tile materials.	Utility	3.6	uR/hr	Utility
H10	3.6	uR/hr	No		Utility		uR/hr	
H11	3.6	uR/hr	No		Storage	3.6	uR/hr	Storage
H12	3.6	uR/hr	No		Storage		uR/hr	
H13		uR/hr	No	N/A- Grids are outside unit interior boundary.	Storage		uR/hr	



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Summary Report
1312 Gateview Avenue Unit B

Unit Summary :

Completion Date: 8/11/2014 10:55 AM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:

Grids D11, D12, and E12 are outside of floor plan.

Summary Statistics :

Total # of Readings: 113
Average: 3.07 uR/hr
Standard Deviation: 0.27 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		2.4	uR/hr	Stairs			uR/hr			No	Static taken on stairs 56" from floor surface
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	static taken on stairs 56" from floor surface
A7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	Static taken on stairs 56" from floor surface
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	static taken by toilet
A9	2.8	uR/hr	Utility		4.0	uR/hr	Bathroom			uR/hr			No	static taken by toilet, moved installed washer to survey grid
A10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	moved installed washer to survey grid
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface



Summary Report
1312 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom		2.8	uR/hr	Hallway		No	static taken on stairs 40" from floor surface
B8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
C6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs		3.2	uR/hr	Hallway		No	static taken on stairs 16" from floor surface
C7	3.2	uR/hr	Hallway		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	
C10	2.8	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1312 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway		2.8	uR/hr	Mech Room	Installed furnace.		uR/hr			No	70% accessible
D10	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
E6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	moved installed refrigerator to survey grid
E7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1312 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Trash		2.8	uR/hr	Dining Room			uR/hr			No	
F12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Kitchen	Installed Stove.	2.8	uR/hr	Living Room			uR/hr			No	60% accessible
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1312 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible


CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :



Signature :



Signoff Notes:



Summary Report
1312 Gateview Avenue Unit C

Unit Summary :

Completion Date: 8/11/2014 10:42 AM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 127
Average: 3.37 uR/hr
Standard Deviation: 0.24 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	60% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	



**Summary Report
1312 Gateview Avenue Unit C**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr			No	95% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	No	
D6	3.6	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	moved refrigerator to survey grid



Summary Report
1312 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room			uR/hr			No	25% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1312 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	reading .6 meters from floor for stairs
F7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading .6 meters from floor for stairs
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Hallway	Installed furnace.	3.2	uR/hr	Utility			uR/hr			No	75% accessible
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	75% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	



Summary Report
1312 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G9	3.6	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. reading 1.8 meters from floor for stairs
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1312 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H9	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible. moved washer to survey grid
H10	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. moved dryer to survey grid
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1312 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Summary Report
1312 Gateview Avenue Unit D

Unit Summary :

Completion Date: 8/11/2014 1:46 PM

Instrument: 193-6

Serial #: 309119

Layout: Floor Plan 7

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids D11, D12 and E12 fall outside unit interior floor plan.

Summary Statistics :

Total # of Readings: 113

Average: 3.15 uR/hr

Standard Deviation: 0.22 uR/hr

Minimum: 2.40 uR/hr


Maximum: 4.00 uR/hr

Median: 2.80 uR/hr

Anomalies: 0

Grid Legend:

-  No anomalous measurements
-  Inaccessible (no measurement collected)
-  Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		3.2	uR/hr	Living Room			uR/hr			No	Stair static taken at 1.5 meters above ground floor
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.5 meters above ground floor
A7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.4 meters above ground floor
A8	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Utility	Washing machine within grid.	4.0	uR/hr	Bathroom			uR/hr			No	80% accessible, washer moved for survey
A10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	50% accessible, washer and dryer moved for survey
A11	3.2	uR/hr	Storage		2.8	uR/hr	Utility	Clothes dryer within grid.		uR/hr			No	90% accessible, Dryer moved for survey
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1312 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stair static taken at 0.8 meters above ground floor
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 0.8 meters above ground floor
B8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	3.2	uR/hr	Utility		3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Storage		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
C6	3.2	uR/hr	Storage		3.2	uR/hr	Hallway		3.2	uR/hr	Stairs		No	Stair static taken at 0.4 meters above ground floor
C7	2.8	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	Stair static taken at 0.4 meters above ground floor
C8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility	Installed furnace.	3.2	uR/hr	Hallway			uR/hr			No	70% accessible
C10	3.2	uR/hr	Utility		2.4	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	



Summary Report
1312 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	90% accessible
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	75% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	



Summary Report
1312 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	Installed refrigerator moved for survey
E7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.2	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	80% accessible
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
F2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	



**Summary Report
1312 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F11	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	90% accessible, refrigerator moved for survey.
F12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	30% accessible, partial grid in kitchen inaccessible due to installed stove.
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	freezer moved for survey
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1312 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible, survey performed inside base cabinets
H6	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, survey performed inside base cabinets
H7	3.2	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible, survey performed inside base cabinets, installed dishwasher
H8	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :



Signature :



Signoff Notes:



Summary Report
1312 Gateview Avenue Unit E

Unit Summary :

Completion Date: 8/11/2014 11:47 AM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan. Bed in living room (mattress on floor) moved for survey.

Summary Statistics :

Total # of Readings: 129
Average: 3.53 uR/hr
Standard Deviation: 0.28 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	Kitchen reading taken 12" from floor inside base cabinet.
A6	4.0	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	4.0	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	30% accessible.
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible.
B2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Installed Stove.		uR/hr			No	25% accessible. Kitchen reading taken 12" from floor inside base cabinet.
B6	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1312 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible.
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	
C6	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	60% accessible.
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	85% accessible.
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1312 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway		No	Kitchen reading taken 12" from floor inside base cabinet.
D6	3.6	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	
D7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	Kitchen reading taken 12" from floor inside base cabinet.
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	30% accessible. Partial grid in Mech room inaccessible due to installed furnace.
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	30% accessible.



Summary Report
1312 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	45% accessible.
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	35% accessible.
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.6	uR/hr	Stairs			uR/hr			No	Stairs reading taken 12" from floor.
F7	3.6	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	Stairs reading taken 12" from floor.
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Utility		3.6	uR/hr	Hallway			uR/hr			No	90% accessible. Partial grid in Mech room inaccessible due to installed furnace.
F10	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible.
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1312 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	Bed in living room (mattress on top of floor), moved for survey.
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	Bed in living room (mattress on top of floor), moved for survey.
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room		4.0	uR/hr	Storage		2.8	uR/hr	Stairs		No	Stairs reading taken 60" from floor.
G6	4.0	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 60" from floor.
G7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 60" from floor.
G8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Bed in living room (mattress on top of floor), moved for survey.



**Summary Report
1312 Gateview Avenue Unit E**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Bed in living room (mattress on top of floor), moved for survey.
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	4.0	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	4.0	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible. Stairs reading taken 60" from floor.
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Stairs reading taken 60" from floor.
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.	3.6	uR/hr	Bathroom			uR/hr			No	60% accessible. Stairs reading taken 60" from floor.
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. Partial grid due to installed washer.
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. Partial grid due to installed dryer.
H11	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.



Summary Report
1312 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1312 Gateview Avenue Unit E


Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan




CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Summary Report
1312 Gateview Avenue Unit F

Unit Summary :

Completion Date: 8/11/2014 12:05 PM

Instrument: 193-6

Serial #: 309136

Layout: Floor Plan 7

Background Reading: 2.8 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids D11, D12 and E12 are outside of survey unit.

Summary Statistics :

Total # of Readings: 115

Average: 2.86 uR/hr

Standard Deviation: 0.24 uR/hr

Minimum: 2.40 uR/hr


Maximum: 3.60 uR/hr

Median: 2.60 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	Unmovable hutch surveyed inside drawers at 5" over 50% of grid
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	Unmovable hutch surveyed inside drawers at 5" over 50% of grid
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		2.8	uR/hr	Living Room			uR/hr			No	Stair static taken at 1.5 meters above ground level
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.5 meters above ground level
A7	2.4	uR/hr	Stairs		2.8	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.5 meters above ground level
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	dryer moved for survey
A10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	washer moved for survey
A11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1312 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.1 meters above ground level
B7	2.4	uR/hr	Stairs		2.8	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.1 meters above ground level
B8	2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
B9	2.8	uR/hr	Utility		2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway		No	
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.4	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		No	
C6	2.8	uR/hr	Storage		3.2	uR/hr	Hallway		2.8	uR/hr	Stairs		No	Stair static taken at 0.5 meters above ground level
C7	2.8	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	Stair static taken at 0.5 meters above ground level
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Utility	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	60% accessible
C10	2.8	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	70% accessible
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	



Summary Report
1312 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	95% accessible
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.8	uR/hr	Living Room			uR/hr			No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	2.4	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	Survey over 5" wood china base cabinet
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	refrigerator moved for survey

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
E8	2.8	uR/hr	Hallway		2.8	uR/hr	Kitchen			uR/hr			No	
E9	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E10	2.4	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	40% accessible
E11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible, Static taken at 7" through unmovable china cabinet shelf
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.4	uR/hr	Trash	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	60% accessible
F12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room			uR/hr			No	30% accessible, Surveyed over 2.5" unmovable wood living room furniture base shelf
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, surveyed unmovable china cabinet wood shelf at 5"

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Survey performed under unmovable china cabinet with M19 s/n 267078, 6µR/hr. Background level 5µR/hr.
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Survey performed under unmovable china cabinet with M19 s/n 267078, 6µR/hr. Background level 5µR/hr.
H5	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible, surveyed unmovable china cabinet wood shelf
H6	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, survey inside installed cabinets
H7	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible, installed dishwasher, survey inside installed cabinets
H8	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1312 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :

A handwritten signature in black ink on a light blue background. The signature appears to be "AH", with a large, stylized "A" followed by two vertical strokes for the "H".

Signature :

A handwritten signature in black ink on a light blue background. The signature appears to be "PB", with a stylized "P" followed by a large, rounded "B".

Signoff Notes:



Summary Report
1313 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/11/2014 2:30 PM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 131
Average: 3.15 uR/hr
Standard Deviation: 0.21 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
A6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Kitchen	Installed Stove.	3.2	uR/hr	Living Room			uR/hr			No	60% accessible
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1313 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Trash		3.2	uR/hr	Dining Room			uR/hr			No	
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
D6	3.2	uR/hr	Kitchen		2.8	uR/hr	Hallway			uR/hr			No	moved installed refrigerator
D7	2.8	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1313 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway		3.2	uR/hr	Mech Room	Installed furnace.		uR/hr			No	75% accessible
E10	3.2	uR/hr	Mech Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Hallway			uR/hr			No	60% accessible, installed furnace
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F7	3.2	uR/hr	Hallway		3.2	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	



**Summary Report
1313 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F9	3.2	uR/hr	Hallway		3.2	uR/hr	Utility			uR/hr			No	
F10	3.2	uR/hr	Utility		2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs		3.2	uR/hr	Bathroom		No	static taken on stairs 40" from floor surface
G7	3.2	uR/hr	Bathroom		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
G9	3.2	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1313 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H8	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, static taken by toilet
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility			uR/hr			No	moved washer to survey grid, 60% accessible
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	moved dryer to survey grid, 60% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible



Summary Report
1313 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1313 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized and appears to read "N. Rothell".

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized and appears to read "Ricky Laguna".

Signoff Notes:



Summary Report
1313 Gateview Avenue Unit B

Unit Summary :

Completion Date: 8/11/2014 3:28 PM

Instrument: 193-6

Serial #: 309110

Layout: Floor Plan 7

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

D12, E11 and E12 grids are outside unit interior boundary.

Summary Statistics :

Total # of Readings: 109

Average: 3.59 uR/hr

Standard Deviation: 0.50 uR/hr

Minimum: 2.80 uR/hr


Maximum: 5.00 uR/hr

Median: 3.20 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	5.0	uR/hr	Living Room			uR/hr				uR/hr			No	surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4µR/hr
A2	5.0	uR/hr	Living Room			uR/hr				uR/hr			No	surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4µR/hr
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		4.0	uR/hr	Living Room	Survey performed on non-movable item.		uR/hr			No	reading 1.8 meters from floor for stairs. surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4µR/hr
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	move washer to survey grid
A10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	moved dryer to survey grid
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	



Summary Report
1313 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	4.0	uR/hr	Living Room	Survey performed on non-movable item.	3.6	uR/hr	Storage			uR/hr			No	surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4μR/hr
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
B8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C5	5.0	uR/hr	Storage	Survey performed on non-movable item.	4.0	uR/hr	Living Room	Survey performed on non-movable item.	3.2	uR/hr	Hallway		No	surveyed storage and living room with model 19 s/n 267078 due to non-movable bookcase, background 4µR/hr.
C6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs		3.6	uR/hr	Hallway		No	reading .6 meters from floor for stairs
C7	3.2	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	reading .6 meters from floor for stairs
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility	Installed furnace.	3.6	uR/hr	Hallway			uR/hr			No	75% accessible
C10	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	75% accessible
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D11	3.2	uR/hr	Mech Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible-installed water heater.
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
E11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1313 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	5.0	uR/hr	Dining Room			uR/hr				uR/hr			No	surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4µR/hr.
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	moved 2nd refrigerator to survey grid.
F11	3.6	uR/hr	Trash		5.0	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	95% accessible. surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4µR/hr
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Kitchen	Installed Stove.	3.6	uR/hr	Living Room			uR/hr			No	60% accessible
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	5.0	uR/hr	Dining Room			uR/hr				uR/hr			No	surveyed with model 19 s/n 267078 inside non-movable mini refrigerator, background 4μR/hr.
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	5.0	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4μR/hr
H2	5.0	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible. surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4μR/hr
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible-installed dishwasher
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible-installed dishwasher
H8	4.0	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4µR/hr.
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	5.0	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible. surveyed with model 19 s/n 267078 due to non-movable bookcase, background 4µR/hr



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Unit Summary :

Completion Date: 8/11/2014 1:25 PM
Instrument: 193-6
Serial #: 309119
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 fall outside unit interior floor plan.

Summary Statistics :

Total # of Readings: 124
Average: 3.17 uR/hr
Standard Deviation: 0.14 uR/hr
Minimum: 2.80 uR/hr
Maximum: 3.60 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	50% accessible, survey performed inside base cabinets
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	30% accessible. Partial grid in kitchen inaccessible due to installed stove



Summary Report
1313 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	90% accessible
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Trash			uR/hr			No	90% accessible
C12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway		No	
D6	3.2	uR/hr	Kitchen	Installed refrigerator.	3.2	uR/hr	Hallway			uR/hr			No	50% accessible, survey performed inside base cabinets
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	40% accessible



Summary Report
1313 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E10	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr				uR/hr			No	40% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible. Partial grid in mech room inaccessible due to installed water heater
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stair static taken at 0.4 meters above ground floor
F7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 0.4 meters above ground floor
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility	Installed furnace.	3.2	uR/hr	Hallway			uR/hr			No	90% accessible
F10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.4 meters above ground floor
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.2 meters above ground floor
G8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
G9	3.2	uR/hr	Utility	Washing machine within grid.	3.2	uR/hr	Bathroom			uR/hr			No	80% accessible
G10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	80% accessible
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1313 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor
H7	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor
H8	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.	3.2	uR/hr	Bathroom			uR/hr			No	40% accessible, installed washer moved for survey
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible, installed dryer moved for survey

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible. Survey performed on bottom wooden shelf of unstable furniture, static at 12".
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1313 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :




Signature :



Signoff Notes:



- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		3.6	uR/hr	Living Room			uR/hr			No	Stairs reading taken 60" from floor.
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 60" from floor.
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 60" from floor.
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Utility	Washing machine within grid.	4.0	uR/hr	Bathroom			uR/hr			No	40% accessible.
A10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	40% accessible.
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage		2.8	uR/hr	Stairs		3.6	uR/hr	Living Room		No	Stairs reading taken 60" from floor.
B6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	Stairs reading taken 44" from floor.
B7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 44" from floor.



Summary Report
1313 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Utility		3.6	uR/hr	Hallway		3.6	uR/hr	Bathroom		No	
B10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Living Room		No	
C6	3.2	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Stairs		No	Stairs reading taken 12" from floor.
C7	3.6	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	Stairs reading taken 12" from floor.
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Utility		3.6	uR/hr	Hallway			uR/hr			No	60% accessible. Partial grid in Mech room inaccessible due to installed furnace.
C10	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible.
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
D1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.



Summary Report
1313 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	60% accessible. Partial grid in Mech room inaccessible due to installed furnace.
D10	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	20% accessible. Partial grid in Mech room inaccessible due to installed water heater.
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1313 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E9	3.6	uR/hr	Hallway		3.6	uR/hr	Dining Room			uR/hr			No	
E10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.6	uR/hr	Dining Room			uR/hr			No	30% accessible.
E11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible.
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Living Room			uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1313 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F11	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.	3.6	uR/hr	Dining Room			uR/hr			No	60% accessible.
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Kitchen	Installed Stove.	3.6	uR/hr	Living Room			uR/hr			No	25% accessible.
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.6	uR/hr	Living Room			uR/hr			No	60% accessible. Kitchen reading taken 12" from floor inside base cabinet.



Summary Report
1313 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Kitchen reading taken 12" from floor inside base cabinet.
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. Kitchen reading taken 12" from floor inside base cabinet. Partial grid due to installed dishwasher.
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	4.0	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H10	4.0	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H11	4.0	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.



CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Summary Report
1313 Gateview Avenue Unit E

Unit Summary :

Completion Date: 8/18/2014 1:36 PM

Instrument: 193-6

Serial #: 309119

Layout: Floor Plan 7B

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids in column I, row 13 and D11 fall outside unit interior floor plan.

Summary Statistics :

Total # of Readings: 124

Average: 3.22 uR/hr

Standard Deviation: 0.28 uR/hr

Minimum: 2.40 uR/hr


Maximum: 4.00 uR/hr

Median: 2.80 uR/hr

Anomalies: 0

Grid Legend:

-  No anomalous measurements
-  Inaccessible (no measurement collected)
-  Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	surveyed on wooden shelf of non-movable furniture 4" above ground floor
A4	3.2	uR/hr	Living Room	Survey performed on non-movable item.		uR/hr				uR/hr			No	surveyed on wooden shelf of non-movable furniture 4" above ground floor
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.2	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	50% accessible, survey performed inside base cabinets
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B5	3.2	uR/hr	Living Room	Grid partially obstructed by installed.	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	40% accessible, installed stove
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Trash			uR/hr			No	90% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room	Grid partially obstructed by installed.	3.2	uR/hr	Hallway			uR/hr			No	70% accessible, installed base cabinet
D6	2.8	uR/hr	Kitchen	Installed refrigerator.	3.2	uR/hr	Hallway			uR/hr			No	80% accessible, installed refrigerator moved for survey
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway	Grid partially obstructed by installed.		uR/hr				uR/hr			No	60% accessible due to installed furnace in mech room.
E10	3.2	uR/hr	Mech Room	Installed water heater.	2.8	uR/hr	Hallway			uR/hr			No	50% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stair static taken at 0.4 meters above ground floor
F7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 0.4 meters above ground floor



Summary Report
1313 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	
F10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.4 meters above ground floor
G7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.4 meters above ground floor
G8	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.2	uR/hr	Utility	Washing machine within grid.	3.6	uR/hr	Bathroom			uR/hr			No	80% accessible
G10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	80% accessible
G11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, survey performed on non-movable furniture a 4" above ground floor
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, inaccessible/non-movable furniture
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible, non-movable furniture in grid
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H8	3.2	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, surveyed inside installed base cabinets
H9	4.0	uR/hr	Bathroom	Grid partially obstructed by installed.		uR/hr				uR/hr			No	30% accessible due to installed washer in utility room
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible, installed dryer
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

Summary Report
1313 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :



Signature :



Signoff Notes:



Summary Report
1313 Gateview Avenue Unit F

Unit Summary :

Completion Date: 7/9/2014 3:38 PM

Instrument: 193-6

Serial #: 309136

Layout: Floor Plan 7

Background Reading: 2.8 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: No

Tenant Present: No

Unit Notes:

Summary Statistics :

Total # of Readings: 113

Average: 2.81 uR/hr

Standard Deviation: 0.19 uR/hr

Minimum: 2.40 uR/hr

Maximum: 3.60 uR/hr

Median: 2.60 uR/hr

Anomalies: 0

Grid Legend:

-  No anomalous measurements
-  Inaccessible (no measurement collected)
-  Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		2.8	uR/hr	Living Room			uR/hr			No	Stairs static taken 1.7 meters above ground level.
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs static taken 1.7 meters above ground level.
A7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs static taken 1.7 meters above ground level.
A8	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Utility		3.6	uR/hr	Bathroom			uR/hr			No	Elevated level due to NORM in toilet bowl material.
A10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	
B6	2.4	uR/hr	Stairs		2.8	uR/hr	Storage			uR/hr			No	Stairs static taken 1.1 meters above ground level.



Summary Report
1313 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs static taken 1.1 meters above ground level.
B8	2.8	uR/hr	Bathroom		2.8	uR/hr	Hallway			uR/hr			No	
B9	2.8	uR/hr	Utility		3.2	uR/hr	Bathroom		2.8	uR/hr	Hallway		No	
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		No	
C6	2.8	uR/hr	Hallway		2.8	uR/hr	Storage		2.8	uR/hr	Stairs		No	Stairs static taken 0.5 meters above ground level.
C7	2.8	uR/hr	Stairs		2.4	uR/hr	Hallway			uR/hr			No	Stairs static taken 0.5 meters above ground level.
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	2.8	uR/hr	Utility		2.4	uR/hr	Mech Room		2.8	uR/hr	Hallway		No	Furnace not installed.
C10	2.8	uR/hr	Utility		2.4	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible.
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
D1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	



**Summary Report
1313 Gateview Avenue Unit F**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.8	uR/hr	Living Room			uR/hr			No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.4	uR/hr	Hallway		2.4	uR/hr	Mech Room			uR/hr			No	Furnace not installed.
D10	2.8	uR/hr	Hallway		2.4	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible.
D11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	15% accessible.
D12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
E2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
E3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
E6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	Pulled out refrigerator and surveyed.
E7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible.



Summary Report
1313 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
F3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Living Room			uR/hr			No	
F6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Dining Room		2.8	uR/hr	Trash			uR/hr			No	
F12	2.8	uR/hr	Trash			uR/hr				uR/hr			No	
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Kitchen	Installed Stove.	2.8	uR/hr	Living Room			uR/hr			No	90% accessible.
G6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1313 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible.
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.	2.8	uR/hr	Living Room			uR/hr			No	60% accessible. Surveyed within base cabinets.
H6	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Surveyed within base cabinets.
H7	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible. Installed dishwasher.
H8	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :



Signature :



Signoff Notes:

Unit Summary :

Completion Date: 8/11/2014 4:05 PM

Instrument: 193-6

Serial #: 309127

Layout: Floor Plan 7B

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Bath and utility rooms converted into ADA compliant bathroom with tub. Living room has been permanently framed into two rooms. Grids in column I, row 13, and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 130

Average: 3.54 uR/hr

Standard Deviation: 0.28 uR/hr

Minimum:	2.80	uR/hr
----------	------	-------

Maximum:	4.80	uR/hr
----------	------	-------

Median: 3.20 uR/hr


Anomalies: 0

Grid Legend:

 No anomalous measurements

Inaccessible (no measurement collected)

Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	35% accessible.
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
B2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Installed Stove.		uR/hr			No	30% accessible. Kitchen reading taken 12" from floor inside base cabinet.
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



**Summary Report
1314 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	
C6	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	60% accessible.
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
D1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	85% accessible.
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		3.6	uR/hr	Kitchen		No	
D6	3.6	uR/hr	Kitchen		3.2	uR/hr	Hallway			uR/hr			No	



Summary Report
1314 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.6	uR/hr	Kitchen		3.6	uR/hr	Hallway			uR/hr			No	Kitchen reading taken 12" from floor inside base cabinet.
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
E1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	20% accessible. Partial grid due to Mech room inaccessible due to installed furnace.
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.6	uR/hr	Mech Room	Installed water heater.		uR/hr			No	30% accessible.
E11	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
E12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	25% accessible.



Summary Report
1314 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.6	uR/hr	Storage		3.6	uR/hr	Stairs			uR/hr			No	Stairs reading taken 12" from floor.
F7	3.6	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 12" from floor.
F8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	90% accessible. Partial grid due to Mech room inaccessible due to installed furnace.
F10	3.6	uR/hr	Bathroom		3.6	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible.
F11	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1314 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G5	3.6	uR/hr	Living Room		2.8	uR/hr	Stairs		3.6	uR/hr	Storage		No	Stairs reading taken 60" from floor.
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 60" from floor.
G7	2.8	uR/hr	Stairs		4.0	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 60" from floor.
G8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Bathroom		4.0	uR/hr	Bathroom			uR/hr			No	
G10	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
G12	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible. Stairs reading taken 60" from floor.



Summary Report
1314 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	3.2	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Stairs reading taken 60" from floor.
H7	3.2	uR/hr	Stairs	Percentage of grid falls outside of unit.	4.0	uR/hr	Bathroom			uR/hr			No	60% accessible. Stairs reading taken 60" from floor.
H8	4.4	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.	4.8	uR/hr	Bathroom			uR/hr			No	60% accessible. Surveyed inside bath tub.
H10	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Surveyed inside bath tub.
H11	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	35% accessible. Partial grid due to installed washer.
H12	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible. Partial grid due to installed dryer.
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan



Summary Report
1314 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	outside of floor plan




CBI Supervisor : Garrick Anderson

Senior Technician : Patricia Lozano

Signature :



Signature :



Signoff Notes:



Summary Report
1314 Gateview Avenue Unit B

Unit Summary :

Completion Date: 8/11/2014 3:07 PM
Instrument: 193-6
Serial #: 309136
Layout: Floor Plan 7
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Bath and utility converted into ADA compliant bathroom with tub. Living room permanently framed into two separate rooms. Grids D11, D12 and E12 are outside of survey unit.

Summary Statistics :

Total # of Readings: 115
Average: 2.84 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		2.8	uR/hr	Living Room			uR/hr			No	Stair static taken at 1.5 meters above ground level
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.5 meters above ground level
A7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.5 meters above ground level
A8	4.0	uR/hr	Bathroom		2.8	uR/hr	Bathroom			uR/hr			No	
A9	4.0	uR/hr	Bathroom		2.8	uR/hr	Bathroom			uR/hr			No	survey inside bath tub
A10	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	survey inside bath tub
A11	2.8	uR/hr	Utility	Washing machine within grid.		uR/hr				uR/hr			No	70% accessible
A12	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible, dryer moved for survey
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	



Summary Report
1314 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.1 meters above ground level
B7	2.4	uR/hr	Stairs		2.8	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.1 meters above ground level
B8	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Bathroom			uR/hr				uR/hr			No	
B10	2.8	uR/hr	Bathroom			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Storage		2.8	uR/hr	Hallway		2.8	uR/hr	Living Room		No	
C6	2.8	uR/hr	Storage		3.2	uR/hr	Hallway		2.8	uR/hr	Stairs		No	Stair static taken at 0.5 meters above ground level
C7	2.8	uR/hr	Stairs		2.8	uR/hr	Hallway		2.8	uR/hr	Bathroom		No	Stair static taken at 0.5 meters above ground level
C8	2.8	uR/hr	Hallway		2.8	uR/hr	Bathroom			uR/hr			No	
C9	2.8	uR/hr	Bathroom	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	30% accessible
C10	2.8	uR/hr	Bathroom	Installed water heater.		uR/hr				uR/hr			No	60% accessible
C11	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
C12	2.4	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1314 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.8	uR/hr	Living Room			uR/hr			No	
D6	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	70% accessible
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	95% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	refrigerator moved for survey
E7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Dining Room		2.8	uR/hr	Hallway		No	
E8	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	



Summary Report
1314 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E9	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.4	uR/hr	Dining Room			uR/hr			No	40% accessible
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
F6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.	2.4	uR/hr	Dining Room			uR/hr			No	60% accessible
F12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Kitchen	Installed Stove.	2.8	uR/hr	Living Room			uR/hr			No	30% accessible
G6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G7	2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	2.4	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H6	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, survey inside installed cabinets
H7	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible, installed dishwasher
H8	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	2.4	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1314 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :

A handwritten signature in black ink on a light blue background. The signature consists of a large, stylized 'A' followed by three vertical lines, resembling 'AH'.

Signature :

A handwritten signature in black ink on a light blue background. The signature consists of the letters 'P' and 'B' joined together in a stylized, cursive-like font.

Signoff Notes:



Summary Report
1314 Gateview Avenue Unit C

Unit Summary :

Completion Date: 8/11/2014 4:02 PM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 132
Average: 3.39 uR/hr
Standard Deviation: 0.26 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room	Installed base cabinets.		uR/hr				uR/hr			No	50% accessible
A6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	30% accessible
A8	3.2	uR/hr	Dining Room	Installed refrigerator.		uR/hr				uR/hr			No	moved for survey. 80% accessible
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	installed stove in kitchen section. 40% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	



Summary Report
1314 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	No	
D6	3.6	uR/hr	Hallway		3.6	uR/hr	Kitchen			uR/hr			No	
D7	3.6	uR/hr	Hallway		3.6	uR/hr	Kitchen			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	70% accessible
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room	Installed water heater.		uR/hr			No	20% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. Installed hot water heater
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room			uR/hr			No	
F6	3.6	uR/hr	Storage		3.6	uR/hr	Stairs			uR/hr			No	stair static taken at 12" above floor
F7	3.6	uR/hr	Hallway		3.2	uR/hr	Stairs			uR/hr			No	stair static taken at 12" above floor
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
F11	3.2	uR/hr	Storage		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	90% accessible
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Storage		3.6	uR/hr	Living Room		2.8	uR/hr	Stairs		No	stair static taken at 60" above floor



Summary Report
1314 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken at 44" above floor
G7	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		2.8	uR/hr	Stairs		No	stair static taken at 44" above floor
G8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
G9	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		3.2	uR/hr	Utility		No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible. stair static taken at 60" above floor



Summary Report
1314 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Reminder of grid falls outside unit. Stair static taken at 60" above floor
H7	3.6	uR/hr	Bathroom	Survey performed within accessible base cabinet.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible. remainder of grid falls outside unit, stair static taken at 60" above floor
H8	3.6	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	60% accessible. Reminder of grid falls outside unit. Stair static taken at 60" above floor
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility	Washing machine within grid.		uR/hr			No	50% accessible
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	installed clothes dryer 50% accessible
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1314 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1314 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1314 Gateview Avenue Unit D

Unit Summary :

Completion Date: 8/1/2014 10:57 AM
Instrument: 193-6
Serial #: 309136
Layout: Floor Plan 7
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.9 W 7.7
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:

D12 is outside of floor plan. Grid E12 is less than 6" wide and surveyed with adjacent grid.

Summary Statistics :

Total # of Readings: 115
Average: 2.88 uR/hr
Standard Deviation: 0.24 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.4	uR/hr	Stairs		2.8	uR/hr	Living Room			uR/hr			No	Stair static taken at 1.5 meters above ground level
A6	2.4	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.5 meters above ground level
A7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom			uR/hr			No	Stair static taken at 1.5 meters above ground level
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	2.8	uR/hr	Utility		4.0	uR/hr	Bathroom			uR/hr			No	installed washer moved for survey
A10	2.8	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	70% accessible
A11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
A12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
B1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room			uR/hr			No	
B6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.1 meters above ground level



Summary Report
1314 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.4	uR/hr	Stairs		3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway		No	Stair static taken at 1.1 meters above ground level
B8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
B9	2.8	uR/hr	Utility		3.2	uR/hr	Bathroom		2.8	uR/hr	Hallway		No	
B10	2.8	uR/hr	Utility			uR/hr				uR/hr			No	
B11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
B12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C1	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	2.8	uR/hr	Storage		2.8	uR/hr	Living Room		2.8	uR/hr	Hallway		No	
C6	2.8	uR/hr	Storage		2.8	uR/hr	Stairs		2.8	uR/hr	Hallway		No	Stair static taken at 0.5 meters above ground level
C7	2.8	uR/hr	Stairs		2.8	uR/hr	Hallway			uR/hr			No	Stair static taken at 0.5 meters above ground level
C8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Utility	Installed furnace.	2.8	uR/hr	Hallway			uR/hr			No	60% accessible
C10	2.8	uR/hr	Utility	Installed water heater.		uR/hr				uR/hr			No	70% accessible
C11	2.8	uR/hr	Storage			uR/hr				uR/hr			No	
C12	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1314 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
D3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		2.8	uR/hr	Living Room			uR/hr			No	
D6	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	2.8	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	2.8	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	70% accessible
D10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room			uR/hr			No	30% accessible
D11	2.8	uR/hr	Mech Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
E6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	refrigerator moved for survey
E7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway			uR/hr			No	
E8	2.8	uR/hr	Hallway		2.8	uR/hr	Kitchen			uR/hr			No	



**Summary Report
1314 Gateview Avenue Unit D**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E9	2.8	uR/hr	Hallway		2.8	uR/hr	Dining Room			uR/hr			No	
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	40% accessible
E11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
F2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	2.8	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
F6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	60% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
G2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Kitchen	Installed Stove.	2.8	uR/hr	Living Room			uR/hr			No	30% accessible
G6	2.8	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
G8	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1314 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	2.8	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
H2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H5	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible. Installed refrigerator
H6	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H7	2.8	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible, installed dishwasher
H8	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H9	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H10	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
H11	2.8	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible



CBI Supervisor : Adam Hickok

Senior Technician : Phillip Perez

Signature :

A handwritten signature in black ink on a light blue background. The signature consists of a large, stylized capital letter 'A' followed by two vertical lines and a horizontal line, resembling the letters 'AH'.

Signature :

A handwritten signature in black ink on a light blue background. The signature is stylized and appears to be the letters 'PP' or 'PZ'.

Signoff Notes:



Summary Report
1315 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/12/2014 10:31 AM
Instrument: 193-6
Serial #: 293633
Layout: Floor Plan 7B
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 132
Average: 3.38 uR/hr
Standard Deviation: 0.24 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.00 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	installed dishwasher 40% accessible
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	40% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	



Summary Report
1315 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.6	uR/hr	Kitchen			uR/hr			No	
C6	3.6	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	90% accessible
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
C12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1315 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Hallway		No	
D6	3.6	uR/hr	Kitchen	Installed refrigerator.	3.2	uR/hr	Hallway			uR/hr			No	90% accessible
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	70% accessible
E10	3.2	uR/hr	Mech Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Hallway			uR/hr			No	installed hot water heater 25% accessible



Summary Report
1315 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	stair static taken at 12" above floor
F7	3.2	uR/hr	Stairs		3.2	uR/hr	Hallway			uR/hr			No	stair static taken at 12" above floor
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility	Installed furnace.	3.6	uR/hr	Hallway			uR/hr			No	70% accessible
F10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	80% accessible
F11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	



**Summary Report
1315 Gateview Avenue Unit A**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage		2.8	uR/hr	Stairs		No	stair static taken at 60" above floor
G6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stair static taken at 44" above floor
G7	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		2.8	uR/hr	Stairs		No	stair static taken at 44" above floor
G8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
G9	3.6	uR/hr	Bathroom		3.2	uR/hr	Hallway		3.2	uR/hr	Utility	Washing machine within grid.	No	90% accessible
G10	3.2	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	80% accessible
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Model 19 (S/N:267078) used for scan behind immovable desk, 4uR/hr. Background 4uR/hr.
H2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1315 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.8	uR/hr	Stairs			uR/hr			No	60% accessible, stair static taken at 60" above floor
H6	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, stair static taken at 60" above floor
H7	3.6	uR/hr	Bathroom	Survey performed within accessible base cabinet.	2.8	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible, stair static taken at 60" above floor
H8	3.6	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	60% accessible, partial grid, remainder of grid fall outside unit
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.6	uR/hr	Utility	Washing machine within grid.		uR/hr			No	40% accessible
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible installed clothes dryer
H11	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1315 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1315 Gateview Avenue Unit A

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan

CBI Supervisor : Tina Piquet

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1315 Gateview Avenue Unit B

Unit Summary :

Completion Date: 8/1/2014 12:12 PM

Instrument: 193-6

Serial #: 293633

Layout: Floor Plan 7

Background Reading: 3.6 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids D11 and D12 are outside of floor plan.

Summary Statistics :

Total # of Readings: 111

Average: 3.57 uR/hr

Standard Deviation: 0.26 uR/hr

Minimum: 2.80 uR/hr


Maximum: 4.00 uR/hr

Median: 3.20 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
A6	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stairs static taken at 40" above floor
A8	3.6	uR/hr	Bathroom	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Living Room		3.6	uR/hr	Storage			uR/hr			No	
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	stairs static taken at 44" above floor
B7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	stairs static taken at 44" above floor
B8	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		3.6	uR/hr	Utility		No	



**Summary Report
1315 Gateview Avenue Unit B**

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Living Room		3.6	uR/hr	Storage		3.6	uR/hr	Hallway		No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Stairs		No	stairs static taken at 12" above floor
C7	3.6	uR/hr	Hallway		3.2	uR/hr	Stairs			uR/hr			No	stairs static taken at 12" above floor
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway	Installed furnace.	3.6	uR/hr	Utility			uR/hr			No	70% accessible
C10	3.2	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	70% accessible
C11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.2	uR/hr	Living Room	Grid partially contained within wall construction.		uR/hr				uR/hr			No	80% accessible
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Living Room		3.6	uR/hr	Hallway			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1315 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	70% accessible
D10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	installed hot water heater 40% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
E3	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
E6	3.6	uR/hr	Kitchen	Installed refrigerator.		uR/hr				uR/hr			No	20% accessible
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E8	3.6	uR/hr	Hallway		3.6	uR/hr	Dining Room			uR/hr			No	
E9	3.6	uR/hr	Hallway		3.2	uR/hr	Dining Room			uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.6	uR/hr	Dining Room			uR/hr			No	50% accessible



Summary Report
1315 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F3	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Living Room		3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
F6	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	4.0	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
F8	4.0	uR/hr	Dining Room	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash			uR/hr			No	90% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G3	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Living Room	Installed Stove.		uR/hr				uR/hr			No	50% accessible



Summary Report
1315 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G6	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	4.0	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	4.0	uR/hr	Dining Room	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G9	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
G10	4.0	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible surveyed on china cabinet
H4	4.0	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible surveyed on china cabinet
H5	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	60% accessible
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible survey performed within accessible base cabinet



Summary Report
1315 Gateview Avenue Unit B

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H7	4.0	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	survey performed within accessible base cabinet 60% accessible
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible survey performed within accessible base cabinet
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	4.0	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible

CBI Supervisor : Joyce McGee

Senior Technician : Daphne Degering

Signature :



Signature :



Signoff Notes:



Summary Report
1315 Gateview Avenue Unit C

Unit Summary :

Completion Date: 8/12/2014 10:29 AM
Instrument: 193-6
Serial #: 309099
Layout: Floor Plan 7B
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Grids in column I, row 13 and D11 are outside of floor plan.

Summary Statistics :

Total # of Readings: 130
Average: 3.19 uR/hr
Standard Deviation: 0.27 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.40 uR/hr
Median: 2.80 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	3.2	uR/hr	Kitchen		2.8	uR/hr	Living Room			uR/hr			No	
A6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible
A8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.2	uR/hr	Kitchen	Installed Stove.	2.8	uR/hr	Living Room			uR/hr			No	60% accessible
B6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
B8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	40% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible



Summary Report
1315 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
C6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Trash		3.2	uR/hr	Dining Room			uR/hr			No	
C12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	2.8	uR/hr	Hallway		3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen		No	
D6	3.2	uR/hr	Hallway		3.2	uR/hr	Kitchen			uR/hr			No	moved installed refrigerator
D7	3.2	uR/hr	Hallway		3.2	uR/hr	Kitchen			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1315 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Mech Room	Installed furnace.	3.2	uR/hr	Hallway			uR/hr			No	60% accessible
E11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F7	3.2	uR/hr	Hallway		2.8	uR/hr	Stairs			uR/hr			No	static taken on stairs 16" from floor surface
F8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	



Summary Report
1315 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F10	3.2	uR/hr	Mech Room	Installed water heater.	3.2	uR/hr	Utility			uR/hr			No	60% accessible
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G7	3.2	uR/hr	Hallway		2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 40" from floor surface
G8	3.2	uR/hr	Bathroom		3.2	uR/hr	Hallway			uR/hr			No	
G9	3.2	uR/hr	Bathroom		3.2	uR/hr	Utility			uR/hr			No	
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible



Summary Report
1315 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr	Bathroom			uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H7	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	static taken on stairs 56" from floor surface, 60% accessible
H8	4.4	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, static taken by toilet.
H9	4.0	uR/hr	Bathroom	Percentage of grid falls outside of unit.	3.2	uR/hr	Utility			uR/hr			No	60% accessible. Installed washer moved to survey grid
H10	3.2	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Installed dryer moved to survey grid
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	45% accessible



Summary Report
1315 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1315 Gateview Avenue Unit C

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan


CBI Supervisor : Natalie Rothell

Senior Technician : Ricky Laguna

Signature :



Signature :



Signoff Notes:



Summary Report
1315 Gateview Avenue Unit D

Unit Summary :

Completion Date: 8/12/2014 10:15 AM
Instrument: 193-6
Serial #: 309110
Layout: Floor Plan 7
Background Reading: 3.2 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:

E12 grid is outside unit interior boundary.

Summary Statistics :

Total # of Readings: 112
Average: 3.52 uR/hr
Standard Deviation: 0.20 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.00 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1
A2	B2	C2	D2	E2	F2	G2	H2	I2	J2	K2
A3	B3	C3	D3	E3	F3	G3	H3	I3	J3	K3
A4	B4	C4	D4	E4	F4	G4	H4	I4	J4	K4
A5	B5	C5	D5	E5	F5	G5	H5	I5	J5	K5
A6	B6	C6	D6	E6	F6	G6	H6	I6	J6	K6
A7	B7	C7	D7	E7	F7	G7	H7	I7	J7	K7
A8	B8	C8	D8	E8	F8	G8	H8	I8	J8	K8
A9	B9	C9	D9	E9	F9	G9	H9	I9	J9	K9
A10	B10	C10	D10	E10	F10	G10	H10	I10	J10	K10
A11	B11	C11	D11	E11	F11	G11	H11	I11	J11	K11
A12	B12	C12	D12	E12	F12	G12	H12	I12	J12	K12
A13	B13	C13	D13	E13	F13	G13	H13	I13	J13	K13
A14	B14	C14	D14	E14	F14	G14	H14	I14	J14	K14

Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Stairs		3.6	uR/hr	Living Room			uR/hr			No	reading 1.8 meters from floor for stairs
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.8 meters from floor for stairs
A8	3.6	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	4.0	uR/hr	Bathroom		3.6	uR/hr	Utility			uR/hr			No	moved washer to survey grid.
A10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	moved dryer to survey grid
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	3.6	uR/hr	Storage		3.2	uR/hr	Living Room			uR/hr			No	
B6	3.6	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	reading 1.3 meters from floor for stairs
B7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	reading 1.3 meters from floor for stairs
B8	4.0	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	



Summary Report
1315 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B9	3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		3.6	uR/hr	Utility		No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.2	uR/hr	Living Room		3.2	uR/hr	Hallway		No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Stairs		No	reading .6 meters from floor for stairs
C7	3.6	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	reading .6 meters from floor for stairs
C8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	3.6	uR/hr	Hallway	Installed furnace.	3.6	uR/hr	Utility			uR/hr			No	75% accessible
C10	3.6	uR/hr	Utility		3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	60% accessible
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
D1	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D2	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Hallway		3.2	uR/hr	Living Room			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	



Summary Report
1315 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	75% accessible
D10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.6	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible
D11	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.	3.2	uR/hr	Mech Room	Installed water heater.		uR/hr			No	10% accessible
D12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible
E2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Living Room			uR/hr			No	
E6	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
E7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	moved refrigerator to survey grid.
E8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E10	3.2	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
E11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible



Summary Report
1315 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
F3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.6	uR/hr	Kitchen		3.2	uR/hr	Living Room			uR/hr			No	
F6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
F11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr			No	95% accessible
F12	3.2	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	90% accessible
G2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	70% accessible
G3	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	3.6	uR/hr	Kitchen	Installed Stove.	3.6	uR/hr	Living Room			uR/hr			No	60% accessible
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	



Summary Report
1315 Gateview Avenue Unit D

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
G10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
H3	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr			No	60% accessible
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible- installed dishwasher
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible- installed dishwasher
H8	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H10	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	15% accessible



CBI Supervisor : Carlos Bernal

Senior Technician : Antonio Neotti

Signature :



Signature :



Signoff Notes:



Summary Report
1315 Gateview Avenue Unit E

Unit Summary :

Completion Date: 8/12/2014 11:02 AM

Instrument: 193-6

Serial #: 309119

Layout: Floor Plan 7B

Background Reading: 3.2 uR/hr

Dimensions (m): D 11.8 W 7.6

Unit Furnished: Yes

Tenant Present: Yes

Unit Notes:

Grids in column I, row 13 and D11 are outside of floor plan. Storage used as bedroom, bed moved for survey.

Summary Statistics :

Total # of Readings: 126

Average: 3.14 uR/hr

Standard Deviation: 0.25 uR/hr

Minimum: 2.40 uR/hr


Maximum: 4.00 uR/hr

Median: 2.80 uR/hr

Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A2	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
A3	2.8	uR/hr	Living Room			uR/hr				uR/hr			No	
A4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
A5	2.8	uR/hr	Living Room		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr			No	
A6	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
A7	3.6	uR/hr	Kitchen	Installed Dishwasher.		uR/hr				uR/hr			No	60% accessible, survey performed inside base cabinets
A8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
A9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
A11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
B2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
B3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
B5	2.8	uR/hr	Living Room		3.2	uR/hr	Kitchen	Installed Stove.		uR/hr			No	50 % accessible. Survey performed inside base cabinets



Summary Report
1315 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
B7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
B8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
B9	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B10	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
B11	3.2	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible
C2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
C5	3.2	uR/hr	Living Room		3.2	uR/hr	Kitchen			uR/hr			No	
C6	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C7	3.2	uR/hr	Kitchen			uR/hr				uR/hr			No	
C8	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C9	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C10	3.2	uR/hr	Dining Room			uR/hr				uR/hr			No	
C11	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.	2.8	uR/hr	Dining Room			uR/hr			No	90% accessible
C12	2.8	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible
C13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D1	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible



Summary Report
1315 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	85% accessible
D3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
D5	3.2	uR/hr	Living Room		2.8	uR/hr	Kitchen	Survey performed within accessible base cabinet.	2.8	uR/hr	Hallway		No	
D6	3.2	uR/hr	Kitchen	Installed refrigerator.	3.2	uR/hr	Hallway			uR/hr			No	90% accessible, installed refrigerator moved for survey
D7	3.2	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.2	uR/hr	Hallway			uR/hr			No	
D8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
D10	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	40 % accessible
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
E5	3.2	uR/hr	Living Room		3.2	uR/hr	Hallway			uR/hr			No	
E6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
E7	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	
E8	3.2	uR/hr	Hallway			uR/hr				uR/hr			No	

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E9	3.2	uR/hr	Hallway	Installed furnace.		uR/hr				uR/hr			No	40% accessible
E10	2.8	uR/hr	Hallway	Percentage of grid falls outside of unit.	2.8	uR/hr	Mech Room			uR/hr			No	40% accessible
E11	2.8	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible
E12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible
E13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
F5	3.2	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
F6	3.2	uR/hr	Storage		3.2	uR/hr	Stairs			uR/hr			No	Stair static taken at 0.4 meters above ground floor
F7	3.2	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 0.4 meters above ground floor
F8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
F9	3.2	uR/hr	Utility		3.2	uR/hr	Hallway			uR/hr			No	
F10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
F11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	Bed in grid moved for survey.
F12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible. Bed in grid moved for survey.

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
G1	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G2	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G3	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G4	3.2	uR/hr	Living Room			uR/hr				uR/hr			No	
G5	2.8	uR/hr	Living Room		3.2	uR/hr	Storage			uR/hr			No	
G6	3.2	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stair static taken at 1.2 meters above ground floor
G7	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stair static taken at 1.0 meters above ground floor
G8	3.2	uR/hr	Bathroom			uR/hr	Hallway			uR/hr			No	
G9	3.2	uR/hr	Utility	Washing machine within grid.	3.2	uR/hr	Bathroom			uR/hr			No	80% accessible
G10	3.2	uR/hr	Utility			uR/hr				uR/hr			No	
G11	3.2	uR/hr	Storage			uR/hr				uR/hr			No	Bed in grid moved for survey
G12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible. Bed in grid moved for survey
G13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
H1	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H2	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H3	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H4	2.8	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H5	3.2	uR/hr	Living Room	Percentage of grid falls outside of unit.	2.4	uR/hr	Stairs			uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor
H6	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor
H7	2.4	uR/hr	Stairs	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible, Stair static taken at 1.5 meters above ground floor
H8	3.6	uR/hr	Bathroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible
H9	3.2	uR/hr	Utility	Washing machine within grid.	4.0	uR/hr	Bathroom			uR/hr			No	50% accessible, installed washer moved for survey
H10	2.8	uR/hr	Utility	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible, installed dryer moved for survey

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H11	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible. Bed in grid moved for survey
H12	3.2	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible. Bed in grid moved for survey
H13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I1		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I2		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I3		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I4		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I5		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I6		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I7		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



Summary Report
1315 Gateview Avenue Unit E

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
I8		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I9		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I10		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
I13		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan



CBI Supervisor : Steve Phelps

Senior Technician : Efraim Ramirez

Signature :

Signature :

Signoff Notes:



Summary Report
1315 Gateview Avenue Unit F

Unit Summary :

Completion Date: 8/12/2014 10:56 AM
Instrument: 193-6
Serial #: 309127
Layout: Floor Plan 7
Background Reading: 3.6 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:


Living room split into two bedrooms. Dining room used as living room. D11, D12 and E12 are outside of floor plan.

Summary Statistics :

Total # of Readings: 117
Average: 3.61 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.80 uR/hr
Maximum: 4.40 uR/hr
Median: 3.20 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)



Survey Information:

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
A1	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
A2	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
A3	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Bed moved for survey.
A4	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Bed moved for survey.
A5	2.8	uR/hr	Stairs		3.6	uR/hr	Bedroom			uR/hr			No	Stairs reading taken 60" from floor.
A6	2.8	uR/hr	Stairs			uR/hr				uR/hr			No	Stairs reading taken 60" from floor.
A7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom			uR/hr			No	Stairs reading taken 60" from floor.
A8	4.0	uR/hr	Bathroom			uR/hr				uR/hr			No	
A9	3.6	uR/hr	Utility	Washing machine within grid.	4.4	uR/hr	Bathroom			uR/hr			No	30% accessible.
A10	3.6	uR/hr	Utility	Clothes dryer within grid.		uR/hr				uR/hr			No	50% accessible.
A11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
A12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
B1	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
B2	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
B3	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Bed moved for survey.
B4	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Bed moved for survey.
B5	3.6	uR/hr	Storage		3.6	uR/hr	Bedroom		2.8	uR/hr	Stairs		No	Stairs reading taken 60" from floor.
B6	3.6	uR/hr	Storage		2.8	uR/hr	Stairs			uR/hr			No	Stairs reading taken 60" from floor.



Summary Report
1315 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
B7	2.8	uR/hr	Stairs		3.6	uR/hr	Bathroom		3.6	uR/hr	Hallway		No	Stairs reading taken 60" from floor.
B8	4.0	uR/hr	Bathroom		3.6	uR/hr	Hallway			uR/hr			No	
B9	4.0	uR/hr	Utility		4.4	uR/hr	Bathroom		4.0	uR/hr	Hallway		No	
B10	3.6	uR/hr	Utility			uR/hr				uR/hr			No	
B11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
B12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
C1	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
C2	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
C3	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
C4	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
C5	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Bedroom		No	
C6	3.6	uR/hr	Storage		3.6	uR/hr	Hallway		3.6	uR/hr	Stairs		No	Stairs reading taken 12" from floor.
C7	3.2	uR/hr	Stairs		3.6	uR/hr	Hallway			uR/hr			No	Stairs reading taken 12" from floor.
C8	4.0	uR/hr	Hallway			uR/hr				uR/hr			No	
C9	4.0	uR/hr	Utility		4.0	uR/hr	Hallway			uR/hr			No	40% accessible. Partial grid in Mech room inaccessible due to installed furnace.
C10	3.6	uR/hr	Utility	Percentage of grid falls outside of unit.	3.6	uR/hr	Mech Room	Installed water heater.		uR/hr			No	40% accessible.
C11	3.6	uR/hr	Storage			uR/hr				uR/hr			No	
C12	3.6	uR/hr	Storage	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
D1	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	



Summary Report
1315 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
D2	4.0	uR/hr	Bedroom			uR/hr				uR/hr			No	
D3	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
D4	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
D5	3.6	uR/hr	Hallway		3.6	uR/hr	Bedroom			uR/hr			No	
D6	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D7	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D8	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	
D9	3.6	uR/hr	Hallway			uR/hr				uR/hr			No	70% accessible. Partial grid in Mech room inaccessible due to installed furnace.
D10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. Partial grid in Mech room inaccessible due to installed water heater.
D11		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
D12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
E2	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
E3	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
E4	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	
E5	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Bedroom			uR/hr			No	



Summary Report
1315 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
E6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
E7	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Hallway			uR/hr			No	
E8	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
E9	3.6	uR/hr	Hallway		3.6	uR/hr	Living Room			uR/hr			No	
E10	3.6	uR/hr	Hallway	Percentage of grid falls outside of unit.	3.6	uR/hr	Living Room			uR/hr			No	30% accessible.
E11	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	5% accessible.
E12		uR/hr	Outside	Grids are outside unit interior boundary.		uR/hr				uR/hr			No	Outside of floor plan
F2	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
F3	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Bed (mattress on top of floor) moved for survey.
F4	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Bed (mattress on top of floor) moved for survey.
F5	3.6	uR/hr	Kitchen	Survey performed within accessible base cabinet.	3.6	uR/hr	Bedroom			uR/hr			No	
F6	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
F7	4.0	uR/hr	Kitchen			uR/hr				uR/hr			No	
F8	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F9	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
F10	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	



Summary Report
1315 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
F11	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.	3.6	uR/hr	Living Room			uR/hr			No	60% accessible.
F12	3.6	uR/hr	Trash	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	30% accessible.
G2	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	80% accessible.
G3	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Bed (mattress on top of floor) moved for survey.
G4	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	Bed (mattress on top of floor) moved for survey.
G5	3.6	uR/hr	Bedroom			uR/hr				uR/hr			No	20% accessible. Partial grid in Kitchen inaccessible due to installed stove.
G6	3.6	uR/hr	Kitchen			uR/hr				uR/hr			No	
G7	4.0	uR/hr	Kitchen	Survey performed within accessible base cabinet.		uR/hr				uR/hr			No	
G8	3.6	uR/hr	Dining Room			uR/hr				uR/hr			No	
G9	4.0	uR/hr	Living Room			uR/hr				uR/hr			No	
G10	3.6	uR/hr	Living Room			uR/hr				uR/hr			No	
G11	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible.
H2	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	50% accessible.



Summary Report
1315 Gateview Avenue Unit F

Grid	Primary Reading	Unit	Desc.	Cell Note	2nd Reading	Unit	Desc.	Cell Note	3rd Reading	Unit	Desc.	Cell Note	Anomaly	General Notes
H3	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H4	3.6	uR/hr	Bedroom	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H5	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.	3.6	uR/hr	Bedroom			uR/hr			No	60% accessible. Kitchen reading taken 12" from floor inside base cabinet.
H6	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H7	3.6	uR/hr	Kitchen	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	20% accessible. Partial grid due to installed dishwasher.
H8	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H9	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H10	3.6	uR/hr	Living Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	60% accessible.
H11	3.6	uR/hr	Dining Room	Percentage of grid falls outside of unit.		uR/hr				uR/hr			No	10% accessible.




CBI Supervisor : Garrick Anderson

Senior Technician : Joseph Norris

Signature :



Signature :



Signoff Notes:



Summary Report
1316 Gateview Avenue Unit A

Unit Summary :

Completion Date: 8/12/2014 10:41 AM
Instrument: 193-6
Serial #: 309136
Layout: Floor Plan 7B
Background Reading: 2.8 uR/hr
Dimensions (m): D 11.8 W 7.6
Unit Furnished: Yes
Tenant Present: Yes

Unit Notes:

Bath and utility converted into ADA compliant bathroom with tub. Grids in column I and row 13 are outside of floor plan. A11, B11, and D11 are less than 6" and were surveyed with adjacent grids.

Summary Statistics :

Total # of Readings: 122
Average: 2.73 uR/hr
Standard Deviation: 0.25 uR/hr
Minimum: 2.40 uR/hr
Maximum: 4.00 uR/hr
Median: 2.60 uR/hr
Anomalies: 0

Grid Legend:

- No anomalous measurements
- Inaccessible (no measurement collected)
- Anomaly (elevated measurement)

